



DOUGLAS COUNTY SURVEYOR'S OFFICE

RANDY SMITH, COUNTY SURVEYOR

COURTHOUSE ROOM 105-A
ROSEBURG, OREGON 97470
(541) 440-4272

January 12, 2011

This is a print out of the corners visited while collecting data for the County's GIS project. This information was typed into the data collector, no other notes were taken.

Hundreds of corners were visited to get GPS locations on them, but due to the need to visit as many corners as possible, the crew noted what monuments and BTs that they could quickly see. They did not do a comprehensive corner report and in most cases did not renew the corner. They used a rating system of 1-10 to note how bad the corner needs to be renewed. (rehab or rehab 1 being the lowest ranking and rehab 10 meaning that the corner will be lost if it isn't renewed soon)

Found oks were later added to the corner reports.

Jean Crawford
Survey Tech, DCSO

FILED

Date: 1-12-2011 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: 67/33-1

DOUGLAS COUNTY
SURVEYOR

C.S. File No 67/33-1

GeoXT_PLSS

Easting	Northing	Tp_Rg_GCDBID	Corner_type	Monum	Agency	Size	Comment_1	Comment_2	GPS_Date	Datafile
4206041.925	762727.158	02100S00400W037030	DLC cor	IP/BC	County	2 1/2" bc on i.p.			6/6/2006	C060614A.cor
4206041.925	762727.158	02100S00400W037030	DLC cor	IP/BC	County	2 1/2" bc on i.p.			6/6/2006	C060614A.cor
4199852.593	750003.625	02100S00400W100100	Section corner	IP/BC	Private	1.25 ins.	ok		5/19/2004	C051913A.cor
4202961.004	760521.217	02100S00400W140300	Quarter corner	Other	Private	5/8" bolt	renewed today	offset position	6/5/2006	C060514A.cor
4202961.004	760521.217	02100S00400W140300	Quarter corner	Other	Private	5/8" bolt	renewed today	offset position	6/5/2006	C060514A.cor
4205628.312	760442.559	02100S00400W200300	Section corner	Other	Private	comp. pos.	renewed today	offset pos.	6/6/2006	C060614A.cor
4205628.312	760442.559	02100S00400W200300	Section corner	Other	Private	comp. pos.	renewed today	offset pos.	6/6/2006	C060614A.cor
4168144.787	751331.405	02100S00500W100100	Section corner	Rebar	County	5/8 ins	ok		5/18/2004	C051812A.cor
4171101.727	756459.179	02100S00500W140200	Quarter corner	IP/BC	County	2 1/2" bc on 1 1/4" ip	renewed today		7/25/2005	C072510A.cor
4160267.893	751643.005	02100S00600W540100		BC IP					8/15/2001	r081517a.cor
4163737.822	575518.09	02100S00800W300300	Section corner	IP/BC	County	1.24 ins	ok		3/7/2004	C030717A.cor
4204867.212	734110.666	02200S00400W200400	Section corner	IP/BC	GLO/BLM	2.5 ins. ip	renewed 5/6/04		5/6/2004	C050615A.cor
4171187.861	722940.903	02200S00500W042040	DLC cor	IP/BC	County	1 1/4" ip w/bc	ok, 4 live bt's		11/29/2005	C112913A.cor
4171230.42	724087.808	02200S00500W042050	DLC cor	AP/AC	Private	3 1/4" alum. cap	ok, 2 live bt's & ref. mon.		11/29/2005	C112913A.cor
4167223.534	724871.125	02200S00500W100200	Section corner	Rebar	Private	5/8" i.r. w/ypc mkd. BRANCH EN			11/29/2005	C112913A.cor
4167318.366	727507.297	02200S00500W100240	Quarter corner	Rebar	Private	5/8" i.r. w/ypc	ok; 4 live bt's		11/18/2005	C111810A.cor
4167422.151	730138.224	02200S00500W100300	Section corner	IP/BC	County	1 1/4" ip w/bc	rehab 1; 3 live bt's, 2 snags		11/17/2005	C111711A.cor
4167538.837	732795.482	02200S00500W100340	Quarter corner	Other	Private	2 1/2" alum. pipe w/bc inside	OK		11/1/2005	C110112A.cor
4167610.61	735438.383	02200S00500W100400	Section corner	IP/BC	County	1 1/4" i.p. w/bc	ok		11/1/2005	C110112A.cor
4167723.995	738072.439	02200S00500W100440	Quarter corner	IP/BC	County	1 1/4" i.p. w/bc	rehab 6; 1 live bt; 1 snag		11/2/2005	C110210A.cor
4167823.729	740722.894	02200S00500W100500	Section corner	IP/BC	County	1 1/4" i.p. w/bc	rehab 4; 2 live bt's, 2 stumps		10/31/2005	C103111A.cor
4168000.75	745989.91	02200S00500W100600	Section corner	IP/BC	County	1 1/4" ip w/bc	rehab 2; 3 live bt's		10/20/2005	C102010A.cor
4168067.965	748560.94	02200S00500W100640	Quarter corner	IP/BC	County	1 1/4" i.p. w/bc	ok		10/20/2005	C102010A.cor
4169856.647	719517.159	02200S00500W140100	Quarter corner	IP/BC	County	1 1/4" ip w/bc	ok		11/30/2005	C113010A.cor
4170301.458	732710.855	02200S00500W140340	Quarter corner	Other	Private	5/8" i.r. w/alum. cap	ok, 4 live bt's		11/2/2005	C110210A.cor
4170406.181	735328.335	02200S00500W140400	Quarter corner	IP/BC	County	1 1/4" i.p. w/bc	ok; 4 live bt's		11/2/2005	C110210A.cor
4170655.349	740619.412	02200S00500W140500	Quarter corner	IP/BC	County	1 1/4" ip w/bc	ok		10/27/2005	C102711A.cor
4170745.938	745923.572	02200S00500W140600	Quarter corner	Other	Private	3/4" i.d. iron pipe	ok		10/31/2005	C103111A.cor
4170191.443	719507.523	02200S00500W146100	Quarter corner	IP/BC	County	1 1/4" ip w/bc	ok		11/30/2005	C113010A.cor
4172822.708	730012.39	02200S00500W200300	Section corner	IP/BC	County	1 1/4" ip w/bc	ok; 5 live bt's		11/17/2005	C111711A.cor
4173329.441	744535.412	02200S00500W200560	Sixteenth corner	Rebar	Private	5/8"	ok		10/25/2005	C102512A.cor
4173370.611	745858.816	02200S00500W200600	Section corner	IP/BC	County	1 1/4" ip w/bc	rehab 10; stmps, only no trees near		10/25/2005	C102512A.cor
4173499.375	748464.074	02200S00500W200640	Quarter corner	Other	Private	t-iron	rehab 8; 1 live tree, 1 snag.		10/26/2005	C102611A.cor
4175099.151	719346.36	02200S00500W240100	Quarter corner	Other	Private	'T' - iron	in new clearcut; 2 capped stumps		11/30/2005	C113010A.cor
4175420.901	719334.474	02200S00500W244100	Quarter corner	Other	Private	'T' - iron	ok, 3 live bt's		11/30/2005	C113010A.cor
4177688.126	719261.844	02200S00500W300100	Section corner	AP/AC	GLO/BLM	3" alum. cap	renewed today		12/14/2005	C121412A.cor
4177778.817	721860.287	02200S00500W300140	Quarter corner	AP/AC	GLO/BLM	3" alum. cap	renewed today		12/1/2005	C120114A.cor
4178718.999	748271.718	02200S00500W300640	Quarter corner	Orig po:	County	stone w/rebar alongside	rehab 8, stumps only		10/17/2005	C101711A.cor
4178853.106	750907.787	02200S00500W300700	Section corner	Other	County	1" i.p.	rehab 8, stumps only		10/17/2005	C101711A.cor

C.S. File No 67/33-1

GeoXT_PLSS

4178045.446	719219.891	02200S00500W306100	Section corner	AP/AC	GLO/BLM	3" alum cap	renewed today	1/4/2006 C010410A.cor
4179005.924	719215.425	02200S00500W320100	Sixteenth corner	AP/AC	GLO/BLM	3" alum. cap	ok; 2 live bt's	12/13/2005 C121313A.cor
4180326.853	719165.05	02200S00500W340100	Quarter corner	AP/AC	GLO/BLM	3" alum. cap	rehab 7; 1 live bt	12/13/2005 C121313A.cor
4180424.469	721785.179	02200S00500W340140	Quarter corner	AP/AC	GLO/BLM	3" alum. cap	rehab 5; 1 live bt, 1 snag	11/30/2005 C113010A.cor
4180517.099	724420.533	02200S00500W340200	Quarter corner	AP/AC	Private	3" alum. cap	renewed today	12/6/2005 C120610A.cor
4181231.465	745615.854	02200S00500W340600	Quarter corner	Other	County	1 1/2" dia. i.r. w/t-iron near	rehab 10; no bt's	10/20/2005 C102010A.cor
4181342.136	748229.817	02200S00500W340640	Quarter corner	Other	County	1 1/2" i.d. iron pipe	rehab 10; no bt's	10/19/2005 C101910A.cor
4181456.963	750791.872	02200S00500W340700	Quarter corner	IP/BC	County	1 1/4" iP w/bc	ok	10/13/2005 C101311A.cor
4180645.84	719152.228	02200S00500W344100	Quarter corner	AP/AC	GLO/BLM	3" alum. cap	rehab 10	12/13/2005 C121313A.cor
4183044.819	721636.996	02200S00500W400140	Quarter corner	AP/AC	GLO/BLM	3" alum. cap	ok; 3 live bt's	12/8/2005 C120814A.cor
4183698.597	737632.221	02200S00500W400440		BC IP				5/23/2001 R052322A.cor
4183866.903	745544.455	02200S00500W400600	Section corner	Other	Private	T-iron	2 bt's standing, rehab 4.	10/11/2005 C101110A.cor
4183932.035	748178.644	02200S00500W400640	Quarter corner	IP/BC	County	1 1/4" ip w/bc; t-iron alongsi	rehab 4; 2 live trees	10/18/2005 C101812A.cor
4184082.303	750695.643	02200S00500W400700	Section corner	Other	County	1" i.d. i.p.	rehab 6, 2 live bt's	10/18/2005 C101812A.cor
4186201.176	734808.159	02200S00500W440400	Quarter corner	IP/BC	Private	2 1/2" bc on ip	rehab 5; 2 live bt's	1/12/2006 C011211A.cor
4186398.316	740100.531	02200S00500W440500	Quarter corner	Other	Private	1" i.d. iron pipe	ok, 3 standing bt's	10/11/2005 C101110A.cor
4186623.456	748034.152	02200S00500W440640	Quarter corner	IP/BC	Private	2" ip w/bc	ok; 3 live bt's	10/19/2005 C101910A.cor
4186714.69	750572.987	02200S00500W440700	Quarter corner	Other	Private	1" id iron pipe	rehab 7, 1 live bt	10/18/2005 C101812A.cor
4187865.809	745364.716	02200S00500W460600	Sixteenth corner	Other	Private	2" i.d. iron pipe	rehab 8; 2 bt stumps, no suitable trees	1/10/2006 C011011A.cor
4189201.807	745298.24	02200S00500W500600	Section corner	IP/BC	County	1 1/4" ip w/bc	ok, 3 standing bt's	10/11/2005 C101110A.cor
4189257.274	747892.69	02200S00500W500640	Quarter corner	Other	Private	rebar w/alum cap	OK both bt's of rec. standing	10/11/2005 C101110A.cor
4189314.23	750426.236	02200S00500W500700	Section corner	IP/BC	County	1 1/4" ip w/bc	rehab 8, only stumps	10/17/2005 C101711A.cor
4190880.648	718794.888	02200S00500W540100	Quarter corner	AP/AC	GLO/BLM	3" alum. cap	2 live bt's; 1 snag	1/4/2006 C010410A.cor
4191522.722	737199.38	02200S00500W540440	Quarter corner	Other	Private	1" i.d. iron pipe		10/10/2005 C101010A.cor
4191600.317	739916.552	02200S00500W540500	Quarter corner	IP/BC	County	1 1/4" ip w/bc	rehab 3, unrec. trees here	10/10/2005 C101010A.cor
4191716.043	742511.773	02200S00500W540540	Quarter corner	IP/BC	Private	1 1/4" ip w/bc	ok	10/10/2005 C101010A.cor
4191953.505	750339.384	02200S00500W540700	Quarter corner	Other	Private	axle	ok, 3 live bt's	10/13/2005 C101311A.cor
4193678.349	723961.35	02200S00500W600200	Section corner	IP/BC	GLO/BLM	3" bc	rehab 10	1/5/2006 C010510A.cor
4193889.772	729206.725	02200S00500W600300	Section corner	IP/BC	GLO/BLM	3" bc	ok; 4 live bt's, 2 stumps	1/9/2006 C010910A.cor
4194166.89	737124.589	02200S00500W600440	Quarter corner	Other	Private	iron bolt	rehab 6;	10/19/2005 C101910A.cor
4194184.259	738413.496	02200S00500W600460	Sixteenth corner	IP/BC	Private	2" ip w/bc	ok	9/28/2005 C092811A.cor
4194177.868	739857.243	02200S00500W600500	Section corner	IP/BC	County	1 1/4" ip w/bc	ok	9/28/2005 C092811A.cor
4194428.801	745036.508	02200S00500W600600	Section corner	IP/BC	County	1 1/4" ip w/bc	ok, 3 standing bt's	10/12/2005 C101211A.cor
4194518.203	747671.031	02200S00500W600640	Quarter corner	IP/BC	GLO/BLM	3" bc	ok, 3 standing bt's	10/12/2005 C101211A.cor
4194604.402	750230.943	02200S00500W600700	Section corner	AP/AC	GLO/BLM	3" al. cap on al. pipe	rehab 4, 1 live bt, 2 stumps	10/13/2005 C101311A.cor
4194977.16	723914.358	02200S00500W620200	Sixteenth corner	Rebar	Private	5/8" i.r.	rehab 8; 2 stumps, 1 snag	1/9/2006 C010910A.cor
4196280.349	723885.425	02200S00500W640200	Quarter corner	IP/BC	County	ip/bc buried under stump/slide	rehab 4; 2 wit. mons, 3 stumps	1/10/2006 C011011A.cor
4196527.462	729102.206	02200S00500W640300	Quarter corner	IP/BC	GLO/BLM	3" bc	ok; 4 live bt's	1/9/2006 C010910A.cor
4196705.02	734388.059	02200S00500W640400	Quarter corner	IP/BC	County	1 1/4" ip w/bc	ok; 3 live bt's, 1 snag	10/20/2005 C102010A.cor
4196896.863	739643.198	02200S00500W640500	Quarter corner	IP/BC	County	1 1/4" ip w/bc	rehab 7	9/27/2005 C092713A.cor

GeoXT_PLSS

4197086.433	744925.177	02200S00500W640600	Quarter corner	AP/AC	GLO/BLM	3" ac on 2 1/2" ap	rehab 6	9/28/2005 C092811A.cor
4197220.293	750149.346	02200S00500W640700	Quarter corner	IP/BC	Private	1 1/4" ip w/bc	rehab 1, 3 live bt's	10/13/2005 C101311A.cor
4197845.026	729047.962	02200S00500W660300	Sixteenth corner	IP/BC	GLO/BLM	3" bc set in concrete	ok; 3 live bt's	1/9/2006 C010910A.cor
4199058.733	726369.228	02200S00500W700240	Quarter corner	IP/BC	County	2 1/2" bc on ip	rehab 5; 2 live bt's, 1 stump	1/5/2006 C010510A.cor
4199164.838	728995.816	02200S00500W700300	Section corner	IP/BC	County	2 1/2" bc on ip	ok, 5 live bt's	1/5/2006 C010510A.cor
4199258.531	731638.8	02200S00500W700340	Quarter corner	IP/BC	County	1 1/4" i.p. w/bc	rehab 2; 3 live bt's	10/31/2005 C103111A.cor
4199527.796	739534.807	02200S00500W700500	Section corner	IP/BC	County	1 1/4" ip w/bc	ok	9/28/2005 C092811A.cor
4199734.249	744798.088	02200S00500W700600	Section corner	IP/BC	County	1.25 in	ok	10/5/2005 C100514B.cor
4149109.531	744079.388	02200S00600W038020			STONE			6/20/2001 R062020C.cor
4151161.46	738687.492	02200S00600W039030			IP			6/21/2001 R062118A.cor
4156544.974	741171.277	02200S00600W041020			IP			10/1/2001 R100119A.cor
4167594.281	750910.188	02200S00600W044010			STONE			9/6/2001 R090622A.cor
4143899.155	741639.887	02200S00600W240500	Quarter corner	IP/BC	GLO/BLM	3" bc on ip	ok	7/27/2005 C072714A.cor
4146553.651	741540.46	02200S00600W300500	Section corner	IP/BC	County	2 1/2" bc on 1 1/4" ip	rehab 5	7/27/2005 C072714A.cor
4152486.252	746501.066	02200S00600W400600			IP			8/28/2001 R082820A.cor
4156087.546	746496.192	02200S00600W460600			IP			8/27/2001 r082721a.cor
4157375.228	746415.823	02200S00600W500600			IP			9/6/2001 R090623B.cor
4106097.206	724176.897	02200S00700W037030						6/25/2002 R062521A.cor
4110464.813	723093.947	02200S00700W037040			IP			10/3/2001 R100320A.cor
4120099.765	724099.393	02200S00700W400140						6/3/2002 R060320A.cor
4083490.227	729618.557	02200S00800W044100	DLC cor	IP/BC	County	2 1/2" bc	renewed today	6/21/2006 C062113A.cor
4085859.648	729523.364	02200S00800W044110	DLC cor	IP/BC		1 1/4" ip w/bc		10/3/2005 C100315A.cor
4085859.317	729847.904	02200S00800W044120	DLC cor	IP/BC	County	1 1/4" ip w/bc	rehab 7	9/26/2005 C092613A.cor
4080004.159	733538.739	02200S00800W045060	DLC cor	Other	GLO/BLM	maple stump	renewed today	9/20/2005 C092012A.cor
4079889.701	729660.671	02200S00800W045070	DLC cor	IP/BC	GLO/BLM	3"bc'renewed today		9/21/2005 C092110A.cor
4083488.796	729547.453	02200S00800W045080	DLC cor	IP/BC	GLO/BLM	3" bc	renewed today	6/21/2006 C062113A.cor
4089807.779	742446.629	02200S00800W052010	DLC cor	Rebar	Private	5/8 "	OK	12/7/2004 C120713A.cor
4092522.838	744172.202	02200S00800W053020	DLC cor	Other	County	1 1/2" IP		4/19/2005 C041910A.cor
4092484.569	743180.063	02200S00800W053030	DLC cor	Other	Other	1/2" IP		4/19/2005 C041910A.cor
4080949.243	729539.818	02200S00800W240220	Sixteenth corner	IP/BC	GLO/BLM	3" bc	ok	9/26/2005 C092613A.cor
4080950.231	729629.253	02200S00800W240221	Other	IP/BC	GLO/BLM	3" bc	ok	9/21/2005 C092110A.cor
4080961.203	733364.283	02200S00800W240300	Quarter corner	IP/BC	GLO/BLM	3" BC	renewed today	9/20/2005 C092012A.cor
4083243.854	730811.746	02200S00800W300240	Quarter corner	IP/BC	GLO/BLM	3" BC	renewed today	6/14/2006 C061411A.cor
4083360.979	733413.849	02200S00800W300300	Section corner	IP/BC	GLO/BLM	3" bc	ok	9/21/2005 C092110A.cor
4091751.337	743728.091	02200S00800W440500	Quarter corner	Rebar	Private	5/8"		4/19/2005 C041910A.cor
3948947.262	740489.368	02200S01200W140300	Quarter corner	IP/BC	Private	2" bc	ok	9/19/2005 C091913A.cor
3949019.572	741797.14	02200S01200W140320	Sixteenth corner	Rebar	County	1 1/2" alum. cap		9/12/2005 C091213A.cor
3949202.483	745680.917	02200S01200W140400	Quarter corner	IP/BC	Private	2" BC ON IP	REHAB 8	8/22/2005 C082211A.cor
3950220.855	740435.952	02200S01200W160300	Sixteenth corner	Rebar	Private	2" bc	ok	9/19/2005 C091913A.cor
3950299.861	741735.999	02200S01200W160320	Sixteenth corner	Rebar	County	1 1/2" alum. cap on 5/8" rebar	surveyed in	9/12/2005 C091213A.cor

GeoXT_PLSS

3951650.68	743002.785	02200S01200W200340	Quarter corner	IP/BC	County	2 1/2" bc on 1 1/4" ip	renewed today	9/19/2005	C091913A.cor
3952141.351	753324.941	02200S01200W200540	Quarter corner		County	1 ins	ok	1/27/2004	C012723A.cor
3966168.171	738770.305	02200S01200W460260	Sixteenth corner	IP/BC	Private	1.25 ins."	ok	9/1/2005	C090113A.cor
3941403.59	746013.554	02200S01300W600400	Section corner	IP/BC	GLO/BLM	2.5 ins	ok	3/31/2004	C033115A.cor
3941515.253	748638.596	02200S01300W600440	Quarter corner	IP/BC		2 ins.	ok	4/29/2004	C042913B.cor
3941557.859	750697.395	02200S01300W600475	Other	Other	Private	.75 ins	ok	7/8/2004	C070814A.cor
3942120.746	751102.542	02200S01300W605500	Other	Other	County	.625 ins.	ok	7/8/2004	C070814A.cor
3942873.258	749866.792	02200S01300W620460	Sixteenth corner	Other	County	brass disc in conc.	ok	4/29/2004	C042913B.cor
3942917.315	751094.529	02200S01300W620500	Sixteenth corner	Other	County	brass diisc in conc.	ok	4/29/2004	C042913B.cor
3944141.655	748480.03	02200S01300W640440	Quarter corner	Other	County		ok	7/28/2004	C072814A.cor
3944235.769	751034.438	02200S01300W640500	Quarter corner	Other	Private	2 ins.	ok	4/22/2004	C042215A.cor
3946783.583	748329.871	02200S01300W700440	Quarter corner	Rebar	Other	1.5 ins	rehab	7/28/2004	C072814A.cor
4199163.759	718452.517	02300S00400W100700	Section corner	Other	County	2 ins.	rehab	5/18/2004	C051812A.cor
4180857.959	714778.562	02300S00500W037010	DLC cor	IP/BC	County	2 1/2" bc	renewed today	5/22/2007	C052211A.cor
4180770.159	712144.378	02300S00500W037040	DLC cor	Orig po:	GLO/BLM	stone w/iron pipe beside		1/12/2006	C011211A.cor
4181581.373	706845.11	02300S00500W038040	DLC cor	Orig po:	GLO/BLM	stone w/i.r. alongside	rehab 10; no bt's	1/26/2006	C012615A.cor
4180679.227	709510.952	02300S00500W038060	DLC cor	IP/BC	County	1.25 ins.	ok	1/12/2006	C011211A.cor
4183321.579	709417.371	02300S00500W039040	DLC cor	Other	Private	3/4" i.p. very rusted	ok; 4 live bt's	1/23/2006	C012313A.cor
4183328.327	709516.836	02300S00500W041030	Other	Orig po:	Private	stone w/i.r. beside	ok; 4 live bt's	1/23/2006	C012313A.cor
4193158.496	714460.121	02300S00500W043010	DLC cor	IP/BC	County	2 1/2" b.c.	ok; 3 live bt's	2/28/2007	C022813A.cor
4192957.353	709224.492	02300S00500W043040	DLC cor	IP/BC	County	2 1/2" bc	ok; 3 live bt's	11/15/2006	C111512A.cor
4188797.408	704104.065	02300S00500W044030	DLC cor	Rebar	County	5/8" i.r. w/alum. cap	renewed today	5/24/2007	C052413A.cor
4183633.722	709514.83	02300S00500W045020	DLC cor	Other	Private	buried conc. block	ok, 4 live bt's	1/25/2006	C012510A.cor
4183498.435	704283.669	02300S00500W045030	DLC cor	IP/BC	Private	2 1/2" bc		11/28/2006	C112813A.cor
4179803.529	699078.744	02300S00500W046030	DLC cor	IP/BC	County	2 1/2" bc	rehab 7; 1 live tree, 1 snag	12/7/2006	C120711A.cor
4185039.202	698907.158	02300S00500W046040	DLC cor	IP/BC	County	2 1/2 ins.	ok	5/21/2007	C052114A.cor
4177278.739	697940.182	02300S00500W047040	DLC cor	IP/BC	County	2 1/2" bc	ok; 3 live bt's	12/7/2006	C120711A.cor
4177137.943	693908.244	02300S00500W047050	DLC cor	Rebar	Private	5/8 ins.	ok	11/30/2006	C113011A.cor
4182983.458	693693.702	02300S00500W047060	DLC cor	Orig po:	County	rock with 'X'	ok	11/28/2006	C112813A.cor
4166439.147	688035.397	02300S00500W100100	Section corner	IP/BC	GLO/BLM	3.25 ins.	ok	5/25/2004	C052511A.cor
4166936.5	701199.9	02300S00500W100340	Quarter corner	IP/BC	GLO/BLM	2 1/2" bc	rehab 5; 2 live bt's	1/31/2006	C013113A.cor
4167018.111	703853.809	02300S00500W100400	Section corner	IP/BC	Private	2 1/2" BC on IP	rehab 9; 1 bt stump	2/6/2006	C020611A.cor
4167092.471	706474.376	02300S00500W100440	Quarter corner	IP/BC	GLO/BLM	2 1/2" bc	rehab 9; 2 bt stumps	2/7/2006	C020711A.cor
4167169.706	709102.673	02300S00500W100500	Section corner	IP/BC	GLO/BLM	2 1/2" bc on ip	ok; 3 live bt's & 1 stump	3/6/2006	C030611A.cor
4167374.589	714351.574	02300S00500W100600	Section corner	IP/BC	GLO/BLM	2 1/2" bc on ip	ok; 3 live bt's, 1 snag bt.	3/13/2006	C031313A.cor
4167508.53	719567.984	02300S00500W100700	Section corner	IP/BC	GLO/BLM	3.25 ins.	ok	5/19/2004	C051913A.cor
4168436.47	710370.193	02300S00500W120520	Sixteenth corner	IP/BC	Private	2 ins.	ok	3/6/2006	C030611A.cor
4169208.12	693227.223	02300S00500W140200	Quarter corner	Other	Private	2" pipe w/flange	1 live bt	5/2/2007	C050212A.cor
4169382.984	698482.501	02300S00500W140300	Quarter corner	Other	County	1 1/4" U-bar	renewed today	2/6/2006	C020611A.cor
4169708.504	709002.399	02300S00500W140500	Quarter corner	IP/BC	Private	2 1/2" bc on ip	ok	3/6/2006	C030611A.cor

GeoXT_PLSS

4169899.934	714292.144	02300S00500W140600	Quarter corner	IP/BC	County	2 1/2" b.c. on i.p.	renewed today		1/25/2006	C012510A.cor
4171831.765	693133.241	02300S00500W200200	Section corner	IP/BC	County	2 1/2" b.c.	rehab 8; 1 live bt		1/26/2006	C012615A.cor
4171920.686	695760.436	02300S00500W200240	Quarter corner	IP/BC	Private	2 1/2" bc			5/2/2007	C050212A.cor
4172021.067	698406.284	02300S00500W200300	Section corner	Rebar	County	5/8" i.r.	ok		1/31/2006	C013113A.cor
4172184.782	703657.941	02300S00500W200400	Section corner	Other	Private	t-iron	ok; 3 live bt's, 1 bt stump		2/6/2006	C020611A.cor
4172274.326	706268.146	02300S00500W200440	Quarter corner	Other	Private	3" alum. cap			5/29/2007	C052915A.cor
4172438.935	711563.633	02300S00500W200540	Quarter corner	IP/BC	Private	1 1/2" ip w/bc	ok, 4 live bt's		11/30/2005	C113010A.cor
4172522.641	714231.247	02300S00500W200600	Section corner	IP/BC	County	2 1/2" bc	rehab 5; 3 live bt's		1/23/2006	C012313A.cor
4174985.181	708827.484	02300S00500W240500	Quarter corner	Rebar	Private	3/4" i.r.	o.k.		5/30/2007	C053011A.cor
4177105.661	692931.655	02300S00500W300200	Section corner	IP/BC	County	2 1/2"	ok		11/30/2006	C113011A.cor
4177200.304	695577.84	02300S00500W300240	Quarter corner	IP/BC	County	2 1/2" bc	ok		11/30/2006	C113011A.cor
4177265.297	698206.805	02300S00500W300300	Section corner	IP/BC	County	2 1/2" bc	ok; 4 live bt's		12/7/2006	C120711A.cor
4177366.169	700850.262	02300S00500W300340	Quarter corner	IP/BC	Private	2 1/2" bc	bt's all stumps; no suitable trees near		11/28/2006	C112813A.cor
4177450.657	703487.106	02300S00500W300400	Section corner	SSP/BC	GLO/BLM	2 1/2" ssp/bc	rehab 4; 2 live bt's, 2 stumps		1/25/2006	C012510A.cor
4177709.462	711398.193	02300S00500W300540	Quarter corner	IP/BC	County	2 1/2" bc	renewed today		11/14/2006	C111410A.cor
4177783.937	714042.92	02300S00500W300600	Section corner	IP/BC	County	2 1/2" bc	renewed today		4/12/2006	C041216A.cor
4179896.977	698112.174	02300S00500W340300	Quarter corner	SSP/BC	GLO/BLM	3" bc	ok		12/7/2006	C120711A.cor
4180090.989	703394.967	02300S00500W340400	Quarter corner	IP/BC	Private	2 1/2" bc			11/29/2006	C112910A.cor
4182181.562	687463.344	02300S00500W400100	Section corner	Rebar	Private	5/8"	ok, as per record.		11/29/2006	C112910A.cor
4182906.356	708572.72	02300S00500W400500	Section corner	Other	County	mon. is in conc. pad of garage	offset position		1/25/2006	C012510A.cor
4187537.455	689911.579	02300S00500W500140	Quarter corner	Other	County	3/4" i.d. ip			5/31/2006	C053110A.cor
4187912.532	700475.173	02300S00500W500340	Quarter corner	IP/BC	County	2 1/2" BC	renewed today		5/23/2007	C052313A.cor
4188008.324	703092.776	02300S00500W500400	Section corner	IP/BC	County	2 1/2" bc	1 live bt, 1 snag	offset position	5/22/2007	C052211A.cor
4188280.272	711015.41	02300S00500W500540	Quarter corner	IP/BC	County	2 1/2" dia. bc	ok, renewed today		2/28/2007	C022813A.cor
4190551.364	700377.361	02300S00500W540340	Quarter corner	Rebar	Private	5/8" i.r. w\cap	ok; as per rec.		5/21/2007	C052113A.cor
4190640.382	702998.988	02300S00500W540400	Quarter corner	Rebar	Private	5/8" i.r. w\cap	ok; as per rec.		5/21/2007	C052113A.cor
4193007.901	694993.94	02300S00500W600240	Quarter corner	Rebar	Private	2 1/2" alum. cap	ok; 4 live bt's		12/7/2006	C120711A.cor
4193108.88	697627.856	02300S00500W600300	Section corner	Rebar		2 1/2" al. cap on rebar	ok, 4 live bt's		2/7/2007	C020712A.cor
4193183.132	700278.056	02300S00500W600340	Quarter corner	Other	Private	alum. cap/threaded rod	ok; 4 live bt's		5/15/2007	C051511A.cor
4193271.354	702918.747	02300S00500W600400	Section corner	IP/BC	County	2 1/2"bc	ok; 4 live bt's	ok	5/14/2007	C051411A.cor
4193360.95	705556.23	02300S00500W600440	Quarter corner	IP/BC	GLO/BLM	3" bc	ok; 3 live bt's		5/14/2007	C051411A.cor
4193455.557	708194.042	02300S00500W600500	Section corner	SSP/BC	GLO/BLM	3" bc	ok; 4 live bt's		11/16/2006	C111611A.cor
4195534.777	692260.542	02300S00500W640200	Quarter corner	Rebar	Private	2 1/2" al. cap on rebar	ok; 4 live bt's		2/7/2007	C020712A.cor
4195721.317	697537.601	02300S00500W640300	Quarter corner	Other	Private	5/8" i.r. w/alum. cap	ok	offset position	2/14/2007	C021414A.cor
4195904.457	702934.312	02300S00500W640400	Quarter corner	IP/BC	GLO/BLM	3" bc	ok; 4 live bt's		5/14/2007	C051411A.cor
4196111.768	708084.611	02300S00500W640500	Quarter corner	SSP/BC	GLO/BLM	3"	renewed today		11/16/2006	C111611A.cor
4196299.31	713366.896	02300S00500W640600	Quarter corner	IP/BC	County	2 1/2" bc	1 live bt; no other suitable trees near		11/14/2006	C111410A.cor
4197036.524	697609.208	02300S00500W660300	Sixteenth corner	Other	Private	2 1/2" al. cap on 5/8" i.r.	ok; 2 live bt's		2/7/2007	C020712A.cor
4197940.121	686855.471	02300S00500W700100	Section corner	IP/BC	Private	1 1/4 ins.	ok		5/13/2004	C051310A.cor
4198268.566	694779.406	02300S00500W700240	Quarter corner	Other	Private	2 1/2" al. cap on 5/8" i.r.	ok; 3 live bt's, 1 snag	offset position	2/7/2007	C020712A.cor

GeoXT_PLSS

4198344.2	697421.947	02300S00500W700300	Section corner	SSP/BC	GLO/BLM	3" dia. bc	ok; 3 live bt's, 2 ref. mons.	2/7/2007 C020712A.cor
4198508.025	702691.822	02300S00500W700400	Section corner	IP/BC	County	2 1/2" bc	ok; 4 live bt's	5/15/2007 C051511A.cor
4198597.711	705348.4	02300S00500W700440	Quarter corner	IP/BC	County	2 1/2" bc	ok; 2 live bt's, 1 snag	5/15/2007 C051511A.cor
4198763.127	707977.003	02300S00500W700500	Section corner	IP/BC	County	2 1/2" bc	ok; 4 live bt's	5/15/2007 C051511A.cor
4198872.073	710632.515	02300S00500W700540	Quarter corner	Other	Private	T--iron	needs renewed; 1 live bt	5/16/2007 C051611A.cor
4198948.264	713274.374	02300S00500W700600	Section corner	IP/BC	County	2 1/2" bc	ok; 4 live bt's	5/16/2007 C051611A.cor
4152100.851	709103.526	02300S00600W400500	Section corner	IP/BC	GLO/BLM	2" dia. BC on IP	renewed today	7/13/2005 C071312A.cor
4167023.89	719608.13	02300S00600W672700						6/12/2003 R061223A.cor
4116770.459	693189.262	02300S00700W038020						2/28/2002 R022819A.cor
4119694.356	698103.436	02300S00700W046070						7/30/2002 R073018A.cor
4121421.419	698122.641	02300S00700W046080	DLC					7/30/2002 R073022A.cor
4108972.116	717973.397	02300S00700W050020						7/24/2002 R072418A.cor
4107360.875	712132.165	02300S00700W050050						6/25/2002 R062523A.cor
4108136.713	695338.272	02300S00700W169200						4/17/2003 R041720A.cor
4109168.728	703318.988	02300S00700W200340						5/6/2003 R050620A.cor
4119675.554	697538.207	02300S00700W400240						7/30/2002 R073019B.cor
4122368.731	700065.03	02300S00700W440300						7/31/2002 R073121A.cor
4120033.586	708209.846	02300S00700W440400	Quarter corner	IP/BC	GLO/BLM	2.25 ins	rehab 10; no bt's	3/7/2006 C030715A.cor
4095527.996	721806.713	02300S00800W037020						6/20/2002 R062021A.cor
4096702.522	722248.33	02300S00800W540700						6/25/2002 R062519A.cor
4228522.476	654414.909	02400S00300W100100	Section corner	IP/BC	GLO/BLM	3 1/4 ins	ok	5/13/2004 C051310A.cor
4196928.814	655080.896	02400S00400W100100	Section corner	IP/BC	County	1.25 ins	ok	5/25/2004 C052511A.cor
4165226.702	656280.871	02400S00500W100100	Section corner	IP/BC	County	1.25 ins.	ok	5/26/2004 C052611A.cor
4166285.75	682764.764	02400S00500W100600	Section corner	SSP/BC	Private	2 1/2" BC		5/30/2007 C053011A.cor
4171402.225	679851.22	02400S00500W200540	Quarter corner	IP/BC	Private	1.25 ins.	rehab	12/1/2005 C120110A.cor
4133415.204	657418.072	02400S00600W100100	Section corner	IP/BC	GLO/BLM	2 ins.	ok	5/12/2004 C051210A.cor
4107352.242	661149.127	02400S00700W200140	Quarter corner	IP/BC	Private	1 1/4" IP	B.C. is broke off	4/18/2005 C041813A.cor
4110145.659	663698.971	02400S00700W240200	Quarter corner	Rebar	Private	5/8" i.r	ok	4/18/2005 C041813A.cor
4207656.1	645486.26	02500S00400W041010	DLC cor	IP/BC	County	1.25 ins. ip		2/7/2005 C020710B.cor
4210083.044	646569.533	02500S00400W049030	DLC cor	Other		1/2 ins ip w/stone	rehab 7	2/7/2005 C020710B.cor
4207630.36	644787.71	02500S00400W049050	DLC cor	Other	Other	2" I.P.	rehab 10	2/3/2005 C020313A-1.cor
4209929.373	646770.808	02500S00400W340540	Quarter corner	IP/BC	Private	2 1/2 ins bc	ok	2/7/2005 C020710B.cor
4224561.975	627754.186	02500S00400W640200	Quarter corner	IP/BC	GLO/BLM	3 ins. bc	ok	11/1/2004 C110115A.cor
4184230.929	654832.544	02500S00500W046010	DLC cor	Other	County	2 ins	rehab 3	8/17/2004 C081710A.cor
4182201.83	654027.459	02500S00500W046030	DLC cor	IP/BC	County	1.25 ins	ok	8/5/2004 C080511A.cor
4172226.867	624290.387	02500S00500W240100	Quarter corner	IP/BC	County	1.25 ins	ok	8/17/2004 C081710A.cor
4173160	650700.73	02500S00500W240600						10/23/2003 R102322A.cor
4174869.701	624200.634	02500S00500W300100	Section corner	IP/BC	County	1.25 ins	ok	8/17/2004 C081710A.cor
4180151.427	624013.935	02500S00500W400100	Section corner	IP/BC	County	1.25 ins	rehab 5	8/17/2004 C081710A.cor
4180311.66	626553.194	02500S00500W400140	Quarter corner	IP/BC	County	1.25 ins	ok	8/17/2004 C081710A.cor

GeoXT_PLSS

4183724.738	655578.784	02500S00500W440700	Quarter corner	IP/BC	County	1.25 ins	rehab 1	8/5/2004	C080511A.cor
4185664.427	628950.473	02500S00500W500200	Section corner	IP/BC	County	1.25 ins	rehab 5	8/10/2004	C081010A.cor
4186215.437	647557.175	02500S00500W500540	Quarter corner	IP/BC	County	1.25 ins.	ok	8/5/2004	C080511A.cor
4186299.672	650190.84	02500S00500W500600	Section corner	IP/BC	County	1.25 ins	ok	8/5/2004	C080511A.cor
4186364.91	655482.718	02500S00500W500700	Section corner	IP/BC	County	1.25 ins	ok	8/9/2004	C080910A.cor
4186364.91	655482.718	02500S00500W500700	Section corner	IP/BC	County	1.25 ins	ok	8/9/2004	C080910A.cor
4188274.52	628909.517	02500S00500W540200	Quarter corner	IP/BC	County	1.25 ins	ok	8/10/2004	C081010A.cor
4191044.014	634164.522	02500S00500W600300	Section corner	Rebar	Private	5/8 ins	ok	8/9/2004	C080910A.cor
4193668.745	634038.988	02500S00500W640300	Quarter corner	IP/BC	County	1.25 ins	ok	8/9/2004	C080910A.cor
4196291.348	633941.916	02500S00500W700300	Section corner	IP/BC	GLO/BLM	3 ins	ok	8/9/2004	C080910A.cor
4132945.684	631215.678	02500S00600W039010		BC IP				8/24/2000	R082423A.cor
4139630.159	628841.274	02500S00600W040010	DLC cor	IP/BC	County	1.25 ins.	ok	3/30/2004	C033015B.cor
4139583.05	628815.349	02500S00600W040010	DLC cor	IP/BC	County	1.5 ins		6/24/2004	C062412A.cor
4138157.239	628854.472	02500S00600W041030	DLC cor	IP/BC	County	1.5 ins	ok	6/24/2004	C062412A.cor
4139358.677	628855.465	02500S00600W041040						1/15/2002	R011521A.cor
4139353.839	628853.096	02500S00600W041040	DLC cor	IP/BC	County	1.25 ins.	ok	3/30/2004	C033015B.cor
4139306.678	628826.656	02500S00600W041040	DLC cor	IP/BC	County	1.5 ins	ok	6/24/2004	C062412A.cor
4139334.193	629798.613	02500S00600W054030	DLC cor	Other	County	2 ins	ok	6/28/2004	C062810A.cor
4153674.136	631978.934	02500S00600W057030	DLC cor	Orig po:	County	5x17 ins	rehab	6/28/2004	C062810A.cor
4132469.21	625704.344	02500S00600W100100	Section corner	IP/BC	Private	1.25	rehab	5/12/2004	C051210A.cor
4132937.208	638929.385	02500S00600W100340	Quarter corner	IP/BC	GLO/BLM	2.5 ins	ok	7/11/2004	C070108A.cor
4133396.249	651704.197	02500S00600W100600	Section corner	IP/BC	County	1.25 ins.	rehab	7/7/2004	C070709A.cor
4133507.698	654362.183	02500S00600W100640	Quarter corner	IP/BC	County	1.25 ins.	ok	7/7/2004	C070709A.cor
4135433.298	630553.572	02500S00600W140200	Quarter corner	Rebar	Private	5/8 ins	rehab	6/28/2004	C062810A.cor
4138125.913	636069.44	02500S00600W200300	Section corner	IP/BC	County	1.25 ins	ok	7/6/2004	C070609A.cor
4138303.71	641334.19	02500S00600W200400	Section corner	IP/BC	County	1.25 ins	rehab	7/11/2004	C070108A.cor
4138496.065	646586.325	02500S00600W200500	Section corner	Other	Private	1.5 ins	ok	6/30/2004	C063008A.cor
4138685.962	651873.581	02500S00600W200600	Section corner	IP/BC	County	1.25 ins	ok	7/6/2004	C070609A.cor
4140576.677	630711.027	02500S00600W240200	Quarter corner	IP/BC	County	1.25 ins	ok	7/6/2004	C070609A.cor
4143221.344	630613.67	02500S00600W300200	Section corner	IP/BC	County	1.25 ins	ok	6/28/2004	C062810A.cor
4143473.078	635893.969	02500S00600W300300	Section corner	Other	Private	.75 ins ip	ok	6/28/2004	C062810A.cor
4143596.214	641165.657	02500S00600W300400	Section corner	Rebar	Private	5/8 ins.	ok	7/11/2004	C070108A.cor
4143721.627	646424.982	02500S00600W300500	Section corner	IP/BC	County	1.25 ins	rehab	7/6/2004	C070609A.cor
4143859.387	649074.243	02500S00600W300540	Quarter corner	IP/BC	County	1.25	ok	6/30/2004	C063008A.cor
4143940.366	651715.823	02500S00600W300600	Section corner	IP/BC	County	1.25 ins	ok	6/30/2004	C063008A.cor
4144018.908	654347.282	02500S00600W300640	Quarter corner	Other	County	1.25 ins I.P.	ok	6/30/2004	C063008A.cor
4144097.85	657059.065	02500S00600W300700	Section corner	IP/BC	County	1.25 ins.	ok	6/30/2004	C063008A.cor
4146233.466	641067.783	02500S00600W340400	Quarter corner	IP/BC	County	1.25 ins	ok	7/11/2004	C070108A.cor
4146592.028	651650.828	02500S00600W340600	Quarter corner	IP/BC	County	1.25 ins	ok	6/30/2004	C063008A.cor
4148557.625	630490.382	02500S00600W400200						1/23/2002	R012400A.cor

GeoXT_PLSS

4149053.231	646251.766	02500S00600W400500	Section corner	Orig po:	County	1.25 ins.	ok	7/1/2004 C070108A.cor
4149387.429	656855.42	02500S00600W400700	Section corner	IP/BC	GLO/BLM	2.5 ins.	ok	6/30/2004 C063008A.cor
4153845.262	632851.772	02500S00600W500240	Quarter corner	IP/BC	County	1.25 ins	rehab	6/28/2004 C062810A.cor
4154487.117	651296.781	02500S00600W500600	Section corner	IP/BC	County	1.25 ins.	ok	6/30/2004 C063008A.cor
4154579.14	653930.073	02500S00600W500640	Quarter corner	IP/BC	County	1.25 ins	ok	6/30/2004 C063008A.cor
4154688.083	656660.183	02500S00600W500700	Section corner	IP/BC	GLO/BLM	2.5 ins	ok	7/1/2004 C070108A.cor
4156423.896	630147.789	02500S00600W540200	Quarter corner	Other	County	1.25 ins	rehab	7/7/2004 C070709A.cor
4156560.626	635400.008	02500S00600W540300	Quarter corner	IP/BC	County	1.25 ins	rehab	7/8/2004 C070809A.cor
4158812.6	624770.688	02500S00600W600100	Section corner	IP/BC	County	1.25 ins.	ok	7/8/2004 C070809A.cor
4159087.575	632688.582	02500S00600W600240	Quarter corner	IP/BC	County	1.25 ins.	rehab	7/8/2004 C070809A.cor
4159654.504	648539.722	02500S00600W600540	Quarter corner	IP/BC	County	1.25 ins	ok	7/7/2004 C070709A.cor
4159872.006	653801.389	02500S00600W600640	Quarter corner	IP/BC	County	1.25 ins	ok	7/7/2004 C070709A.cor
4161443.655	624678.516	02500S00600W640100	Quarter corner	IP/BC	County	1.25 ins	ok	7/8/2004 C070809A.cor
4164087.599	624584.011	02500S00600W700100	Section corner	IP/BC	GLO/BLM	2.5 ins	ok	7/8/2004 C070809A.cor
4132677.495	631805.544	02500S00700W038010		BC IP				8/24/2000 R082421A.cor
4127313.526	631300.979	02500S00700W045040		IP				8/8/2000 R080822B.cor
4263608.75	609567.322	02600S00200W200500	Section corner	IP/BC	GLO/BLM	3" BC	renewed today	5/17/2005 C060216A.cor
4263760.093	612207.902	02600S00200W200540	Quarter corner	IP/BC	GLO/BLM	2 1/2" BC	ok renewed	5/17/2005 C051715A.cor
4278941.198	604218.288	02600S00200W500400	Section corner	IP/BC	County	2 1/2" BC	OK, 3 live bt's	2/16/2006 C021611A.cor
4280201.003	602698.364	02600S00200W520360	Sixteenth corner	IP/BC	GLO/BLM	3 ins.	ok	2/16/2006 C021613A.cor
4280252.758	604193.752	02600S00200W520400	Sixteenth corner	IP/BC	GLO/BLM	3" bc	ok, 2 live bt's	2/16/2006 C021611A.cor
4233427.892	609634.073	02600S00300W038040	DLC cor	IP/BC	County	2 1/2" bc on ip	2 live bt's	6/15/2006 C061514A.cor
4233426.131	609687.687	02600S00300W040050	DLC cor	IP/BC	County	2 1/2" bc	renewed today	6/20/2006 C062016A.cor
4235673.745	609603.483	02600S00300W040060	DLC cor	Other	County	1" i.p..	renewed today	6/22/2006 C062214A.cor
4235672.255	609535.554	02600S00300W041030	DLC cor	IP/BC	County	2 1/2" bc	renewed today	6/22/2006 C062214A.cor
4228933.782	593731.07	02600S00300W045030						12/16/2002 R121620A.cor
4226552.7	601181.039	02600S00300W100300	Section corner	IP/BC	County	1 1/4" ip w/bc	renewed today	3/16/2005 C031608A.cor
4220763.402	606713.06	02600S00400W043110	DLC cor	IP/BC	Private	2 1/2" bc on ip	ok; 1 bt, 3 ir's	1/3/2006 C010312A.cor
4210738.745	596315.001	02600S00400W400200		BC IP				10/18/2000 R101823A.cor
4216201.521	601492.636	02600S00400W500300		BC IP				6/7/2001 R060719A.cor
4216215.534	603972.971	02600S00400W500340						6/7/2001 R060718A.cor
4163649.25	611387.374	02600S00500W100440	Quarter corner	Rebar	County	1 1/2" alum. cap	ok	11/13/2006 C111310A.cor
4192741.416	602320.422	02600S00500W640300						2/5/2003 R020600C.cor
4132692.201	623801.801	02600S00600W037010	DLC cor	Rebar	County	5/8 ins	ok	6/21/2004 C062108A.cor
4132607.816	622811.328	02600S00600W038010	DLC cor	Rebar	Private	5/8 ins	ok	6/22/2004 C062213A.cor
4135049.046	622747.06	02600S00600W038020	DLC cor	IP/BC	County	1.25 ins	ok	6/21/2004 C062108A.cor
4159133.455	601376.241	02600S00600W044020	DLC cor	Other	County	2 ins.	ok	11/30/2004 C113013A.cor
4149662.326	599486.303	02600S00600W047080	DLC cor	Other	County	3/4 ins. bolt	ok	11/30/2004 C113013A.cor
4160727.479	601326.315	02600S00600W053040	DLC cor	IP/BC	County	1.25 ins. ip	ok	11/30/2004 C113013A.cor
4145962.769	607640.35	02600S00600W061060	DLC cor	IP/BC	County	1.25 ins.	ok	7/20/2004 C072010A.cor

GeoXT_PLSS

4132542.857	620847.79	02600S00600W062050	DLC cor	IP/BC	County	1.25 ins	ok	6/22/2004	C062213A.cor
4131437.775	596688.147	02600S00600W100140	Quarter corner	IP/BC	Private	1.25 ins	ok	6/18/2004	C061809A.cor
4131502.229	599322.558	02600S00600W100200	Section corner	IP/BC	Private	1.25 ins	ok	6/18/2004	C061809A.cor
4132266.601	620411.413	02600S00600W100600	Section corner	IP/BC	County	1.25 ins	ok	6/22/2004	C062213A.cor
4134124.297	599215.968	02600S00600W140200	Quarter corner	IP/BC	Private	1.5 ins	ok	6/16/2004	C061610A.cor
4137254.821	612313.571	02600S00600W200440	Quarter corner	IP/BC	County	1.25 ins	rehab	6/22/2004	C062213A.cor
4137328.851	614934.1	02600S00600W200500	Section corner	Other	County	2 ins.	needs rehab.	6/15/2004	C061512A.cor
4137425.791	617558.318	02600S00600W200540	Quarter corner	Other	County	unknown	rehab	6/23/2004	C062310A.cor
4137581.579	620258.716	02600S00600W200600	Section corner	IP/BC	County	1.25 ins	ok	6/21/2004	C062108A.cor
4137655.512	623419.723	02600S00600W200646	Other	IP/BC	County	1.25	rehab	6/23/2004	C062310A.cor
4137798.579	625530.23	02600S00600W200700	Section corner	IP/BC	County	1.25 ins	ok	6/21/2004	C062108A.cor
4140404.134	625417.959	02600S00600W240700	Quarter corner	IP/BC	County	1.25 ins	rehab	6/23/2004	C062310A.cor
4141884.718	593632.208	02600S00600W300100	Section corner	IP/BC	County	1.25 ins	rehab	6/18/2004	C061809A.cor
4142094.353	598917.605	02600S00600W300200	Section corner	IP/BC	County	1 1/4" ip w/bc	ok	10/4/2005	C100415A.cor
4142152.071	601524.951	02600S00600W300240	Quarter corner	IP/BC	County	1.25 ins	ok	6/18/2004	C061809A.cor
4142245.943	604168.619	02600S00600W300300	Section corner	Other	County	1 ins	ok	6/18/2004	C061809A.cor
4142341.942	606816.475	02600S00600W300340	Quarter corner	IP/BC	County	1.25 ins	rehab	6/18/2004	C061809A.cor
4142433.998	609458.358	02600S00600W300400	Section corner	Rebar	County	.5 ins	ok	6/16/2004	C061610A.cor
4142628.169	614725.94	02600S00600W300500	Section corner	IP/BC	County	1.25 ins.	needs rehab.	6/15/2004	C061512A.cor
4142736.214	617360.767	02600S00600W300540	Quarter corner	IP/BC	County	1.25 ins.	ok	7/16/2004	C071611A.cor
4143039.493	625323.294	02600S00600W300700	Section corner	IP/BC	County	1.25 ins	ok	6/23/2004	C062310A.cor
4144956.955	604121.409	02600S00600W340300	Quarter corner	IP/BC	County	1.25 ins	ok	6/21/2004	C062108A.cor
4145228.063	613343.884	02600S00600W340460	Sixteenth corner	IP/BC	Private	1.25 ins.	ok	7/16/2004	C071611A.cor
4145675.849	625225.596	02600S00600W340700	Quarter corner	IP/BC	County	1.25 ins.	ok	7/6/2004	C070612A.cor
4147870.894	611966.958	02600S00600W400440	Quarter corner	IP/BC	County	1.25 ins.	rehab	7/20/2004	C072010A.cor
4147929.49	614583.076	02600S00600W400500	Section corner	IP/BC	County	1.25 ins.	rehab	7/16/2004	C071611A.cor
4148016.004	617227.738	02600S00600W400540	Quarter corner	IP/BC	County	1.25 ins.	rehab	7/15/2004	C071515A.cor
4148309.357	625133.6	02600S00600W400700	Section corner	IP/BC	County	1.25 ins.	ok	7/6/2004	C070612A.cor
4150412.087	609217.836	02600S00600W440400	Quarter corner	IP/BC	County	1.25 ins.	ok	7/20/2004	C072010A.cor
4150952.494	622441.023	02600S00600W440640	Quarter corner	Other	Other	6.75 ins.	ok	7/20/2004	C072010A.cor
4152983.342	609090.892	02600S00600W500400	Section corner	IP/BC	County	1.25 ins	ok	6/17/2004	C061710A.cor
4153081.433	611736.067	02600S00600W500440	Quarter corner	IP/BC	County	1 ins	ok	6/16/2004	C061610A.cor
4153165.214	614382.557	02600S00600W500500	Section corner	IP/BC	County	1.25 ins.	ok	6/16/2004	C061610A.cor
4158384.434	611567.614	02600S00600W600440	Quarter corner	IP/BC	County	1 INS		1/21/2004	R012123A.cor
4123629.011	623631.967	02600S00700W042010		STONE				8/3/2000	R080317A.cor
4108302.063	610495.461	02600S00700W240400	Quarter corner	IP/BC	County	2 1/2" BC on 1 1/4" IP	renewed today	7/18/2005	C071815A.cor
4049565.975	602330.535	02600S00900W300240		BC IP				11/28/2000	R112820A.cor
4049687.938	607583.371	02600S00900W300340		IP				11/28/2000	R112822A.cor
4052305.125	604875.364	02600S00900W400240		IP				11/27/2000	R112722A.cor
4231308.123	582326.541	02700S00300W200540	Quarter corner	IP/BC	County	2 1/2" bc	renewed today	12/13/2006	C121314A.cor

GeoXT_PLSS

4223043.609	582657.349	02700S00400W039020							12/4/2002 R120421C.cor
4223472.946	582640.326	02700S00400W039030							12/4/2002 R120421A.cor
4209458.442	579252.013	02700S00400W043010		BC IP					9/28/2000 R092815A.cor
4194123.523	559921.484	02700S00400W100100	Section corner	Rebar	County	5\8" i.r. w/alum. cap		renewed today	4/26/2007 C042610A.cor
4194295.238	565218.629	02700S00400W100200	Section corner	IP/BC	County	2 1\2" bc		ok	4/26/2007 C042610A.cor
4196890.852	565111.318	02700S00400W140200	Quarter corner	IP/BC	County	2 1\2" bc		ok	4/26/2007 C042610A.cor
4199499.375	564977.251	02700S00400W200200	Section corner	IP/BC	County	2 1\2" bc		ok	4/26/2007 C042610A.cor
4207936.433	585945.965	02700S00400W340600		BC IP					9/18/2000 R091819A.cor
4210281.803	577819.389	02700S00400W400440		BC IP					9/28/2000 R092817A.cor
4215493.642	575010.165	02700S00400W500400	Section corner	IP/BC	GLO/BLM	3" bc		ok	3/8/2006 C030814A-1.cor
4218046.438	572296.441	02700S00400W540340	Quarter corner	IP/BC	GLO/BLM	3" bc		rehab 8; 2 snags	3/15/2006 C031516A.cor
4218376.081	585549.601	02700S00400W540600		BC IP					9/14/2000 R091419A.cor
4220578.93	569518.882	02700S00400W600227	Section corner	IP/BC	GLO/BLM	2 1/2" bc on ip		ok	3/8/2006 C030814A-1.cor
4220583.266	569554.818	02700S00400W600300	Section corner	IP/BC	GLO/BLM	3"bc		OK	3/8/2006 C030814A-1.cor
4161826.146	561016.246	02700S00500W100100	Section corner	IP/BC	County	1.25 ins.		ok	4/15/2004 C041509A.cor
4162168.869	568977.539	02700S00500W100240		BC IP					1/2/2001 R010223B.cor
4162460.078	576430.683	02700S00500W100372	Other	Rebar	County	1.5 ins. alc on 5/8 ins i.r.		ok	11/6/2006 C110612A.cor
4159252.129	576448.026	02700S00600W056030	DLC cor	Other	County	no mon., set up @ offset pos.		ok	4/14/2005 C041409A.cor
4133104.341	592396.463	02700S00600W057020	DLC cor	IP/BC	County	1.25 ins		ok	6/16/2004 C061610A.cor
4135285.129	586675.722	02700S00600W059030	DLC cor	Other	County	1 7/8 ins		rehab 1	8/3/2004 C080310A.cor
4135267.263	586039.618	02700S00600W064040	DLC cor	Rebar	Private	5/8 ins.		rehab - 8; stones gone, rebar bent.	8/3/2004 C080310A.cor
4130145.787	562149.174	02700S00600W100100	Section corner	IP/BC	GLO/BLM	3 ins.		ok	4/15/2004 C041509A.cor
4130355.533	567474.921	02700S00600W100200	Section corner	IP/BC	County	1.25 ins		ok	7/19/2004 C071909A.cor
4130454.956	570112.96	02700S00600W100240	Quarter corner	Other	County	1 ins		rehab 3	7/19/2004 C071909A.cor
4130542.67	572755.122	02700S00600W100300	Section corner	IP/BC	County	1.25 ins		ok	8/4/2004 C080408A.cor
4130927.842	583312.25	02700S00600W100500	Section corner	Orig po:	County	1.25 ins		ok	7/19/2004 C071909A.cor
4131119.846	588583.562	02700S00600W100600	Section corner	IP/BC	County	1.25 ins.		ok	7/19/2004 C071909A.cor
4131164.755	591184.858	02700S00600W100640	Quarter corner	IP/BC	County	1.25 ins.		ok	7/20/2004 C072009A.cor
4133279.791	577922.323	02700S00600W140400	Quarter corner	IP/BC	County	1.25 ins		rehab 4	8/2/2004 C080209A.cor
4133470.119	583208.004	02700S00600W140500	Quarter corner	IP/BC	County	1.25 ins		ok	8/4/2004 C080408A.cor
4136019.898	580450.816	02700S00600W200440	Quarter corner	IP/BC	County	1.25 ins		rehab 2	8/3/2004 C080310A.cor
4136104.597	583086.137	02700S00600W200500	Section corner	IP/BC	County	1.25 ins.		ok	8/4/2004 C080408A.cor
4136205.59	585738.294	02700S00600W200540	Quarter corner	IP/BC	County	1.25 ins		ok	8/3/2004 C080310A.cor
4136343.842	588419.46	02700S00600W200600	Section corner	Other	Other				3/30/2004 C033015B.cor
4138579.558	577722.776	02700S00600W240400	Quarter corner	IP/BC	County	1.25 ins		rehab 5	8/2/2004 C080209A.cor
4140739.96	564409.688	02700S00600W300140	Quarter corner	IP/BC	County	1.25 ins.		ok	8/2/2004 C080209A.cor
4141025.567	572348.081	02700S00600W300300	Section corner	Other	County	.75 ins			7/20/2004 C072009A.cor
4141120.007	574988.791	02700S00600W300340	Quarter corner	IP/BC	County	1.25 ins		ok	8/4/2004 C080408A.cor
4141714.044	590871.805	02700S00600W300640	Quarter corner	Rebar	Private	1/2 in. i.r.		rehab - 7	7/20/2004 C072009A.cor
4144087.514	582855.578	02700S00600W340500	Quarter corner	IP/BC	County	1 1/4" IP W/BC		REHAB 5	4/14/2005 C041409A.cor

GeoXT_PLSS

4152145.276	587784.963	02700S00600W500600	Section corner	IP/BC	County	1 1/4 ins.	needs ren.		5/5/2004 C050516A.cor
4128184.889	575496.041	02700S00700W048050	DLC cor	IP/BC	County	2.5 ins	ok		9/21/2006 C092112A.cor
4103083.102	565454.406	02700S00700W054050							11/4/2002 R110420A.cor
4110062.845	589353.88	02700S00700W300600	Section corner	IP/BC	County	2 1/2" bc	renewed today		4/6/2006 C040610A.cor
4111481.548	591942.199	02700S00700W320640	Sixteenth corner	IP/BC	County	2 1/2" bc on ip	ok; 2 live bt's	offset position	4/6/2006 C040610A.cor
4112685.774	589260.559	02700S00700W340600	Quarter corner	IP/BC	County	2 1/2" bc	rehab 10; 1 btstump		4/11/2006 C041116A.cor
4112810.809	593193.021	02700S00700W340660	Sixteenth corner	Rebar	County	5/8 ins.	ok		4/8/2004 C040812A.cor
4120817.565	594375.511	02700S00700W500700	Section corner	IP/BC	County	2 1/2" bc	ok		4/6/2006 C040610A.cor
4125490.577	578227.82	02700S00700W600400							10/24/2002 R102420A.cor
4127954.284	572868.508	02700S00700W640300	Quarter corner	IP/BC	County	2 1/2" bc	rehab 9, 1 live bt		9/21/2006 C092112A.cor
4128322.97	583431.605	02700S00700W640500							10/21/2002 R102121A.cor
4130772.47	578047.799	02700S00700W700400		BC IP					1/11/2001 R011121A.cor
4130880.61	580686.859	02700S00700W700440							10/31/2002 R103121A.cor
4225190.879	558605.851	02800S00300W100700	Section corner	IP/BC	GLO/BLM	2.75 ins	ok		6/17/2004 C061710A.cor
4161313.19	529280.163	02800S00500W100100	Section corner	IP/BC	County	1.25 ins.	ok		6/2/2004 C060211A.cor
4162444.593	561001.698	02800S00500W100700	Section corner	IP/BC	County	1.25 ins.	ok		4/15/2004 C041509A.cor
4183445.726	555201.227	02800S00500W500600							7/17/2002 R071721A.cor
4147914.302	529729.62	02800S00600W042010	DLC cor	Other	County	1.25 ins	rehab		7/15/2004 C071509A.cor
4146603.212	530438.478	02800S00600W042030	DLC cor	Rebar	Private	.5 ins	rehab 4		7/15/2004 C071509A.cor
4133793.393	542763.499	02800S00600W049030	DLC cor	IP/BC	County	1.25 ins.	ok		7/15/2004 C071509A.cor
4132477.584	542812.634	02800S00600W051020	DLC cor	IP/BC	County	1.25 ins	ok		7/19/2004 C071909A.cor
4132229.312	537515.539	02800S00600W051030	DLC cor	Other		1 inch iron rod	ok		7/19/2004 C071909A.cor
4129471.492	530412.637	02800S00600W100100	Section corner	IP/BC	County	1.25 ins.	ok		4/14/2004 C041414A.cor
4129776.303	538331.069	02800S00600W100240	Quarter corner	IP/BC	County	1.25 ins	rehab		7/12/2004 C071209A.cor
4130066.075	546280.073	02800S00600W100400	Section corner	IP/BC	County	1.25 ins.	ok		7/14/2004 C071409A.cor
4130262.26	551562.081	02800S00600W100500	Section corner	IP/BC	County	1.25 ins	ok		7/12/2004 C071209A.cor
4130358.88	554215.063	02800S00600W100540	Quarter corner	Other	County	1 ins	ok		7/12/2004 C071209A.cor
4130638.51	562131.631	02800S00600W100700	Section corner	IP/BC	GLO/BLM	3 ins. o.d.	ok		4/15/2004 C041509A.cor
4132431.431	535588.318	02800S00600W140200	Quarter corner	IP/BC	GLO/BLM	2.25 ins	ok		7/12/2004 C071209A.cor
4132826.426	546160.503	02800S00600W140400	Quarter corner	IP/BC	County	1.25 ins.	ok		7/15/2004 C071509A.cor
4134886.778	530209.989	02800S00600W200100	Section corner	IP/BC	GLO/BLM	2.5 ins	ok		7/12/2004 C071209A.cor
4135862.5	556650.118	02800S00600W200600	Section corner	IP/BC	County	1.25 ins.	ok		7/14/2004 C071409A.cor
4135952.654	561968.391	02800S00600W200700	Section corner	IP/BC	County	1.25 ins	ok		7/13/2004 C071309A.cor
4138533.543	556583.694	02800S00600W240600							11/14/2002 R111420A.cor
4140574.11	540635.353	02800S00600W300300	Section corner	Rebar	County	5/8 ins.	ok		4/14/2005 C041409A.cor
4141107.814	556459.922	02800S00600W300600	Section corner	Other	Private	buried iron pipe	ok		7/14/2004 C071409A.cor
4148111.777	529725.72	02800S00600W440100	Quarter corner	IP/BC	County	1.25 ins	ok		7/15/2004 C071509A.cor
4156048.052	529459.46	02800S00600W600100	Section corner	IP/BC	County	1.25 ins.	ok		7/12/2004 C071209A.cor
4156331.512	537386.314	02800S00600W600240	Quarter corner	IP/BC	County	1.25 ins	ok		7/13/2004 C071309A.cor
4156540.929	542635.21	02800S00600W600340	Quarter corner	IP/BC	County	1.25 ins	rehab		7/13/2004 C071309A.cor

GeoXT_PLSS

4161497.925	534549.347	02800S00600W700200	Section corner	IP/BC	County	1.25 ins.	ok	7/14/2004	C071409A.cor
4162292.254	555733.272	02800S00600W700600	Section corner	IP/BC	County	2 1/2" bc		4/10/2007	C041010A.cor
4162320.427	558359.347	02800S00600W700640	Quarter corner	Rebar	Private	5/8 ins.	ok	7/14/2004	C071409A.cor
4108089.209	541912.564	02800S00700W055040		BC IP				2/13/2001	R021320A.cor
4108055.333	540996.186	02800S00700W055050		IP				2/8/2001	R020819A.cor
4101255.496	533592.501	02800S00700W056010		BC IP				1/30/2001	R013023A.cor
4100448.578	537494.83	02800S00700W059010		IP				2/8/2001	R020821A.cor
4098094.081	538080.36	02800S00700W100200		BC IP				1/31/2001	R020100A.cor
4098277.166	541191.408	02800S00700W100240		BC IP				2/7/2001	R020722A.cor
4101276.193	537867.126	02800S00700W140200		BC IP				2/8/2001	R020823A.cor
4103817.729	535282.742	02800S00700W200140		BC IP				2/22/2001	R022223A.cor
4103902.409	537738.169	02800S00700W200200		IP				2/22/2001	R022220A.cor
4104035.886	540384.632	02800S00700W200240		IP				2/13/2001	R021323B.cor
4124966.854	543894.898	02800S00700W600340						11/13/2002	R111322C.cor
4098177.295	539638.399	02800S007V00W100240		BC IP				2/7/2001	R020800A.cor
4096250.046	537033.657	02800S00800W037050		BC IP				2/1/2001	R020121B.cor
4097564.941	536986.697	02800S00800W037060	DLC	BC IP				2/6/2001	R020622A.cor
4097535.806	536258.311	02800S00800W038020	DLC	BC IP				2/6/2001	R020623A.cor
4095416.087	537058.521	02800S00800W640200		BC IP				2/5/2001	R020522A.cor
4097967.328	535502.945	02800S00800W915100		BC IP				2/12/2001	R021222A.cor
4226267.853	501700.616	02900S00300W200200	Section corner	IP/BC	County	2 1/2" bc	renewed today	4/23/2007	C042312A.cor
4226325.577	504360.706	02900S00300W200240	Quarter corner	IP/BC	County	2 1/2" bc	renewed today	4/23/2007	C042312A.cor
4200924.213	500006.108	02900S00400W300140	Quarter corner	Other	Private	2" i.p.	renewed today	8/16/2005	C081612A.cor
4205412.159	497414.957	02900S00400W400100	Section corner	IP/BC	GLO/BLM	2.5 ins.	ok	8/4/2005	C080415A.cor
4184645.272	505356.052	02900S00500W046010		BC IP				1/9/2001	R010921B.cor
4177854.122	500873.863	02900S00500W046050	DLC cor	IP/BC	County	1 1/4" ip w/bc	ok	10/4/2005	C100408A.cor
4181073.632	497415.389	02900S00500W500100	Section corner	IP/BC	GLO/BLM	2.5 ins	ok	3/11/2004	C031110A.cor
4186648.18	497293.795	02900S00500W606100	Section corner	IP/BC	GLO/BLM	3 1/4" b.c. on i.p.	ok; 4 live bt's	2/23/2006	C022315A.cor
4193099.721	528509.548	02900S00500W700700	Section corner	IP/BC	County	1.25 ins	ok	4/15/2004	C041509A.cor
4157342.37	528300.419	02900S00600W040010	DLC cor	Other	County	3/4 inch	rehab	8/24/2004	C082410B.cor
4159144.777	524252.879	02900S00600W040040	DLC cor	Orig po:	Other		rehab	8/24/2004	C082410B.cor
4159224.93	526729.059	02900S00600W040050	DLC cor	Rebar	Private	5/8 inch	rehab	8/27/2004	C082714A.cor
4156225.137	518150.038	02900S00600W042040	DLC cor	IP/BC		0.75 ins.	rehab	8/19/2004	C081909A.cor
4128098.736	499710.419	02900S00600W100100	Section corner	IP/BC	GLO/BLM	2.5 ins.	ok	8/5/2004	C080510A.cor
4131405.766	499539.413	02900S00600W140100	Quarter corner	IP/BC	GLO/BLM	2.5 ins.	rehab	8/11/2004	C081109A.cor
4134050.101	499405.793	02900S00600W200100	Section corner	IP/BC	GLO/BLM	2.5 ins	rehab	8/10/2004	C081009A.cor
4134474.853	509954.623	02900S00600W200300	Section corner	IP/BC	GLO/BLM	2.5 inches	ok	8/20/2004	C082009A.cor
4134561.347	512497.922	02900S00600W200340	Quarter corner	Other	Private	2 inches	5/8 inch iron rod	8/20/2004	C082009A.cor
4134942.038	530240.17	02900S00600W200700		BC IP				1/10/2001	R011019A.cor
4136712.214	504562.214	02900S00600W240200	Quarter corner	IP/BC	County	1.25 ins	rehab 6	8/12/2004	C081210A.cor

GeoXT_PLSS

4137512.378	520069.725	02900S00600W240500	Quarter corner	IP/BC	GLO/BLM	2.5 inches	rehab	8/20/2004	C082009A.cor
4139316.018	504475.22	02900S00600W300200	Section corner	IP/BC	GLO/BLM	3 ins	ok	8/12/2004	C081210A.cor
4140386.476	525056.177	02900S00600W300600	Section corner	IP/BC	County	1.25 inches	ok	8/20/2004	C082009A.cor
4149789.305	509154.859	02900S00600W500300	Section corner	IP/BC	GLO/BLM	2.5 ins.	rehab	8/18/2004	C081809A.cor
4152102.3	503966.241	02900S00600W540200	Quarter corner	IP/BC	County	1.25 ins	rehab	8/17/2004	C081709A.cor
4152363.609	509040.226	02900S00600W540300	Quarter corner	Other	Private	0.75 ins.	ok	8/18/2004	C081809A.cor
4154423.067	501209.74	02900S00600W600140	Quarter corner	IP/BC	County	1.25	rehab	8/17/2004	C081709A.cor
4154584.059	503804.695	02900S00600W600200	Section corner	IP/BC	County	1.5 ins.	rehab	8/19/2004	C081909A.cor
4154761.125	506364.589	02900S00600W600240	Quarter corner	IP/BC	County	1.25	rehab	8/18/2004	C081809A.cor
4154929.875	508906.165	02900S00600W600300	Section corner	IP/BC	County	1.25 ins.	rehab	8/17/2004	C081709A.cor
4155216.562	513919.716	02900S00600W600400	Section corner	IP/BC	County	1.0 ins.	rehab	8/19/2004	C081909A.cor
4155779.46	518976.107	02900S00600W600500	Section corner	IP/BC	County	1.5 ins.	rehab	8/19/2004	C081909A.cor
4157469.697	508793.084	02900S00600W640300	Quarter corner	IP/BC	County	1.25 ins.	needs rehab	3/8/2004	C030810B.cor
4158581.443	526768.591	02900S00600W640640	Quarter corner	IP/BC	Private	1.00 inch	1.0 " iron pipe	8/24/2004	C082410B.cor
4159892.661	500828.048	02900S00600W700140	Quarter corner	Rebar	Private	.625 ins.	rehab	8/18/2004	C081809A.cor
4160498.857	511134.512	02900S00600W700340	Quarter corner	IP/BC	County	1.25 ins.	rehab	8/18/2004	C081809A.cor
4160585.652	512419.599	02900S00600W700360	Sixteenth corner	IP/BC	County	1.25 ins.	ok	8/20/2004	C082009A.cor
4160671.75	513703.955	02900S00600W700400	Section corner	IP/BC	County	11.25 ins.	rehab	8/20/2004	C082009A.cor
4160885.104	518908.79	02900S00600W700500	Section corner	IP/BC	County	1.25 ins.	ok	8/19/2004	C081909A.cor
4161211.506	526696.421	02900S00600W700640	Quarter corner	IP/BC		1.25 inches	rehab	8/24/2004	C082410B.cor
4101241.699	531228.194	02900S00700W037040		BC IP				1/23/2001	R012400A.cor
4102731.5	524513.986	02900S00700W039050		BC IP				1/22/2001	R012220A.cor
4099053.764	529946.991	02900S00700W043010		BC IP				1/18/2001	R011823A.cor
4098955.834	527283.655	02900S00700W043020		BC IP				1/16/2001	R011622A.cor
4101699.923	529051.433	02900S00700W044010		BC IP				1/25/2001	R012522A.cor
4100551.514	527257.909	02900S00700W140600		BC IP				1/25/2001	R012523A.cor
4101065.749	532680.114	02900S00700W140700		BC IP				1/29/2001	R012920A.cor
4103151.32	524527.842	02900S00700W200540		BC IP				1/22/2001	R012221A.cor
4103260.649	527147.974	02900S00700W200600		BC IP				1/22/2001	R012223A.cor
4105776.77	524404.617	02900S00700W240540	Quarter corner	Rebar	Private	5/8"	renewed today	7/25/2005	C072510A.cor
4097775.983	529274.505	02900S00800W700640		IP				4/12/2001	R041219A.cor
4097685.475	529993.472	02900S00800W920110		BC IP				4/12/2001	R041222A.cor
4278173.206	480865.064	03000S00200W600400		BC IP				10/23/2000	R102321A.cor
4222864.58	491343.01	03000S00300W136600	Quarter corner	IP/BC	GLO/BLM	3" BC on 2 1/2" IP	renewedd today	8/15/2005	C081511A.cor
4223224.701	491317.25	03000S00300W140600	Quarter corner	IP/BC	County	BC on 1 1/4" IP		8/15/2005	C081511A.cor
4199373.669	488117.424	03000S00400W039120	DLC cor	IP/BC	GLO/BLM	3" BC	RENEWED TODAY	9/14/2005	C091414A.cor
4196895.136	491573.038	03000S00400W200600		BC IP				7/17/2000	r071723b.cor
4209324.212	478219.369	03000S00400W440340	Quarter corner	Other	Private	.625	ok	7/13/2004	C071313A.cor
4211933.803	478040.274	03000S00400W500340	Quarter corner	IP/BC	GLO/BLM	2.5 ins.	rehab	7/13/2004	C071313A.cor
4172203.167	494663.85	03000S00500W037040	DLC cor	Other	County	3/4" i.d. i.p.	renewed 2/24/05	2/24/2005	C022410A.cor

GeoXT_PLSS

4167041.829	481160.677	03000S00500W043010	DLC cor	Other	Private	1 ins. i.p.	rehab	12/15/2004	C121513A.cor
4166696.407	474880.698	03000S00500W044030	DLC cor	IP/BC	Private	3 ins. bc	ok	1/13/2005	C011312A.cor
4168580.552	474820.598	03000S00500W044040	DLC cor	IP/BC	Private	3 ins. bc	ok	1/13/2005	C011312A.cor
4168963.064	479689.564	03000S00500W044050	DLC cor	IP/BC	County	1 1/4" ip w/bc	ok	2/28/2005	C022810A.cor
4165641.669	481237.057	03000S00500W045030	DLC cor	Other	Private		0k	3/3/2005	C030315A.cor
4178923.121	480307.836	03000S00500W048010	DLC cor	Other	County	1" IRON PIPE	REHAB 2	12/16/2004	C121611A.cor
4177357.261	480378.381	03000S00500W049030	DLC cor	Other	County	1.25" hex. axle	rehab 8'	12/16/2004	C121611A.cor
4182428.791	480982.766	03000S00500W052010	DLC cor	Other	County	3/4" iron rod w/foot	renewed 6/16/2005	6/16/2005	C061614A.cor
4179455.026	481083.932	03000S00500W052020	DLC cor	Other	County	leaf spring	rehab 5	12/16/2004	C121611A.cor
4183085.365	480327.164	03000S00500W052050	DLC cor	Other	County	1" IP	rehab 10	3/10/2005	C031009A.cor
4183089.337	480387.065	03000S00500W053020	DLC cor	Other	County	leaf spring	rehab 10	3/10/2005	C031009A.cor
4186480.77	482846.255	03000S00500W054020	DLC cor	Rebar	Private	5/8" i.r. w/pc		3/10/2005	C031009A.cor
4189774.858	481328.426	03000S00500W055040	DLC cor	Other	Private	3/4 ins. dia. iron bolt	renewed 12/13/2004	12/13/2004	C121315A.cor
4161555.77	475939.983	03000S00500W063010	DLC cor	Other	County	3.5" gear on 1" dia. shaft	rehab 5	1/4/2005	C010410A.cor
4163353.999	474073.586	03000S00500W063050	DLC cor	IP/BC	County	1.25 ins. ip w/bc	ok	1/13/2005	C011312A.cor
4161500.091	474152.051	03000S00500W063060	DLC cor	IP/BC	County	1.25 ins. ip	ok	1/4/2005	C010410A.cor
4158795.598	469497.673	03000S00500W100140	Quarter corner	IP/BC	County	1.25 ins ip w/bc	ok	2/8/2005	C020809A.cor
4158926.374	472068.326	03000S00500W100200	Section corner	IP/BC	County	2 1/4" BC on 1 1/4" IP	ok	2/2/2005	C020214A-1.cor
4158927.565	472166.702	03000S00500W100202	Section corner	Other	Private	1" ID IP	OK	2/2/2005	C020214A-1.cor
4158998.667	474672.593	03000S00500W100240	Quarter corner	IP/BC	County	1.25ins. i.p.	ok	1/3/2005	C010313A.cor
4159002.822	474772.583	03000S00500W100242	Quarter corner	IP/BC	County	1.25 ins.i.p.	ok	1/3/2005	C010313A.cor
4159759.161	498210.824	03000S00500W100700	Section corner	Other	Private	5/8 rebar/alum. cap	ok	3/15/2004	C031510A.cor
4161638.972	466814.815	03000S00500W140100	Quarter corner	IP/BC	County	2 1/2" bc	new position	2/22/2007	C022213A.cor
4161864.894	469425.431	03000S00500W140140	Quarter corner	IP/BC	County	2 1/2" bc	set today, new position	1/24/2007	C012412A.cor
4161864.894	469425.431	03000S00500W140140	Quarter corner	IP/BC	County	2 1/2" bc	set today, new position	1/24/2007	C012412A.cor
4161772.406	469462.373	03000S00500W140140	Quarter corner	IP/BC	County	1.25 ins.	rehab	2/8/2005	C020809A.cor
4162093.372	472035.433	03000S00500W140200	Quarter corner	Other	County	n/a	ok	2/8/2005	C020809A.cor
4162107.024	474660.803	03000S00500W140240	Quarter corner	IP/BC	Private	1 1/2" ID IP, BC missing	OK	2/2/2005	C020214A.cor
4162227.507	479883.828	03000S00500W140340	Quarter corner	Other	Private		rehab 5	2/28/2005	C022810A.cor
4162338.174	482494.507	03000S00500W140400	Quarter corner	IP/BC	GLO/BLM	3" BC	rehab 9	2/28/2005	C022810A.cor
4162582.338	485068.725	03000S00500W140440	Quarter corner	IP/BC	County	1.25" ip w/bc	ok	3/1/2005	C030115A.cor
4162567.232	487915.499	03000S00500W140500	Quarter corner	IP/BC	County	2 1/2" bc		6/14/2005	C061414A.cor
4163142.195	468090.361	03000S00500W160120	Sixteenth corner	IP/BC	County	2 1/2" bc	set today, new position	1/30/2007	C013014A.cor
4163142.195	468090.361	03000S00500W160120	Sixteenth corner	IP/BC	County	2 1/2" bc	set today, new position	1/30/2007	C013014A.cor
4163232.241	469397.161	03000S00500W160140	Sixteenth corner	IP/BC	County	2 1/2" bc	ok, set today	1/10/2007	C011014A.cor
4163232.241	469397.161	03000S00500W160140	Sixteenth corner	IP/BC	County	2 1/2" bc	ok, set today	1/10/2007	C011014A.cor
4163318.174	470711.905	03000S00500W160160	Sixteenth corner	IP/BC	County	2 1/2" bc		1/24/2007	C012412A.cor
4163318.174	470711.905	03000S00500W160160	Sixteenth corner	IP/BC	County	2 1/2" bc		1/24/2007	C012412A.cor
4164528.172	468065.108	03000S00500W200120	Sixteenth corner	IP/BC	County	2 1/2" bc	set today	2/8/2007	C020813A.cor
4164590.473	469379.185	03000S00500W200140	Quarter corner	IP/BC	County	2 1/2" bc	ok, set by survey	1/9/2007	C010914A.cor

GeoXT_PLSS

4164590.473	469379.185	03000S00500W200140	Quarter corner	IP/BC	County	2 1/2" bc	ok, set by survey		1/9/2007	C010914A.cor
4164409.22	469438.268	03000S00500W200140		IP/BC	County	1.25 ins. w/bc	ok		2/8/2005	C020809A.cor
4164656.473	470697.271	03000S00500W200160	Sixteenth corner	IP/BC	County	2 1/2" bc	renewed today, new position		1/31/2007	C013111A.cor
4164656.473	470697.271	03000S00500W200160	Sixteenth corner	IP/BC	County	2 1/2" bc	renewed today, new position		1/31/2007	C013111A.cor
4164676.723	471979.533	03000S00500W200200	Section corner	IP/BC	County	1.25 ins i.p. w/bc	ok		1/12/2005	C011214A.cor
4164756.43	474598.162	03000S00500W200240	Quarter corner	IP/BC	County	1.25 ins. ip w/bc	ok		1/12/2005	C011214A.cor
4164915.221	477194.076	03000S00500W200300	Section corner	IP/BC	County	1.25 ins. ip w/bc	ok		1/4/2005	C010410A.cor
4165003.271	479785.089	03000S00500W200340	Quarter corner	IP/BC	County	2.5ins. bc	reehab 3		1/3/2005	C010313A.cor
4165049.09	481130.663	03000S00500W200360	Sixteenth corner	IP/BC	GLO/BLM	2.5 ins	ok		3/3/2005	C030315A.cor
4165035.431	482458.994	03000S00500W200400	Section corner	IP/BC	GLO/BLM	2.5 ins	rehab		3/16/2004	C031614A.cor
4165326.897	485097.555	03000S00500W200440	Quarter corner	Other	GLO/BLM	n/a	rehab		3/1/2005	C030115A.cor
4165777.163	468047.078	03000S00500W220120	Sixteenth corner	IP/BC	County	2 1/2" bc	set, new position	offset position	1/31/2007	C013111A.cor
4165777.163	468047.078	03000S00500W220120	Sixteenth corner	IP/BC	County	2 1/2" bc	set, new position	offset position	1/31/2007	C013111A.cor
4165868.514	469324.533	03000S00500W220140	Sixteenth corner	IP/BC	County	2 1/2" bc	renewed today. .		1/30/2007	C013014A.cor
4165868.514	469324.533	03000S00500W220140	Sixteenth corner	IP/BC	County	2 1/2" bc	renewed today. .		1/30/2007	C013014A.cor
4166912.563	466787.997	03000S00500W240100	Quarter corner	IP/BC	County	2 1/2" b.c.	set today		3/5/2007	C030514A.cor
4167046.748	469302.018	03000S00500W240140	Quarter corner	IP/BC	County	1 1/4" IP W/BC	rehab 5		2/24/2005	C022410A.cor
4167377.332	471796.03	03000S00500W240200	Quarter corner	IP/BC	County	1 1/4" ip w/bc	ok		2/25/2005	C022511A.cor
4167391.49	473120.632	03000S00500W240220	Sixteenth corner	IP/BC	GLO/BLM	3" bc	ok		2/25/2005	C022511A.cor
4167350.284	474423.535	03000S00500W240240	Quarter corner	IP/BC	GLO/BLM	3 ins. bc	ok		1/13/2005	C011312A.cor
4167765.008	482338.631	03000S00500W240400	Quarter corner	IP/BC	GLO/BLM	3 ins. BC	renewed		12/15/2004	C121513A.cor
4170557.695	484799.692	03000S00500W300440	Quarter corner	IP/BC	County	1.25 ins	rehab 7		1/3/2005	C010313A.cor
4176020.014	487259.026	03000S00500W400500	Section corner	IP/BC	GLO/BLM	3" bc	ok		3/7/2005	C030711A.cor
4176070.526	489862.299	03000S00500W400540	Quarter corner	Other	GLO/BLM	cor. tree now stump	needs rehab		3/16/2004	C031614A.cor
4176219.843	494917.174	03000S00500W400640	Quarter corner	IP/BC	County	1 11/4" ip w/bc	rehab 7		3/14/2005	C031413A.cor
4176304.481	497636.686	03000S00500W400700	Section corner	IP/BC	GLO/BLM	2.5 ins	rehab		3/17/2004	C031715A.cor
4178352.519	481928.128	03000S00500W440400	Quarter corner	IP/BC	GLO/BLM	2.5" IP / 3.25" BC	REHAB 5		12/16/2004	C121611A.cor
4178620.514	487149.542	03000S00500W440500	Quarter corner	IP/BC	County	1 1/4" ip w/bc	ok		3/9/2005	C030913A.cor
4178734.798	492219.048	03000S00500W440600	Quarter corner	IP/BC	GLO/BLM	3" bc	ok		3/8/2005	C030812A.cor
4178829.733	494800.607	03000S00500W440640	Quarter corner	IP/BC	GLO/BLM	3" BC	REHAB 7		3/14/2005	C031413A.cor
4180997.962	481850.891	03000S00500W500400	Section corner	IP/BC	GLO/BLM	2.5 " IP WITH BC	OK		12/16/2004	C121611A.cor
4181124.736	484469.931	03000S00500W500440	Quarter corner	IP/BC	GLO/BLM	2.5" IP WITH BC	REHAB 2		12/16/2004	C121611A.cor
4181255.397	487092.126	03000S00500W500500	Section corner	IP/BC	GLO/BLM	3" bc	ok		3/8/2005	C030812A.cor
4181449.879	497393.882	03000S00500W500700	Section corner	IP/BC	GLO/BLM	2.5 ins	ok		3/11/2004	C031110A.cor
4183766.482	486913.085	03000S00500W540500	Quarter corner	IP/BC	County	1 1/4" IP W/BC	OK		3/9/2005	C030913A.cor
4185472.76	465782.997	03000S00500W600100	Section corner	IP/BC	GLO/BLM	2.25 ins.	rehab		7/19/2005	C071914A.cor
4185775.182	476272.834	03000S00500W600300	Section corner	IP/BC	Private	2 ins.	ok		3/15/2004	C031510A.cor
4186154.987	481537.048	03000S00500W600400	Section corner	IP/BC	County	1.25 ins	needs rehab		3/2/2004	C030218A.cor
4186236.307	486712.401	03000S00500W600500	Section corner	IP/BC	GLO/BLM	2.5 ins	ok		3/8/2004	C030810B.cor
4185552.968	465783.055	03000S00500W602100	Section corner	IP/BC	GLO/BLM	2 1/4" ip w/bc	rehab 7		7/19/2005	C071914A.cor

GeoXT_PLSS

4188841.271	486458.112	03000S00500W640500	Quarter corner	Rebar	County	5/8"	renew today	7/6/2005 C070611A.cor
4189157.365	491764.679	03000S00500W640600	Quarter corner	IP/BC	GLO/BLM	3" BC	REHAB 4	7/6/2005 C070611A.cor
4190537.74	465546.428	03000S00500W700100	Section corner	IP/BC	County	1 1/4 ins.	needs ren.	4/8/2004 C040812A.cor
4190635.46	467883.946	03000S00500W700134	Section corner	IP/BC	County	1 1/4" i.p. w/bc	rehab 4	6/21/2005 C062115A.cor
4190651.218	468223.095	03000S00500W700140	Quarter corner	IP/BC	County	1 1/4" i.p. w/bc	rehab 7	6/21/2005 C062115A.cor
4190893.672	476014.513	03000S00500W700300	Section corner	Other	County	4+6+22 stone	needs rehab	3/2/2004 C030218A.cor
4191006.105	478624.689	03000S00500W700340	Quarter corner	IP/BC	County	1.25" IP	OK	12/9/2004 C120911A.cor
4191112.522	481282.091	03000S00500W700400	Section corner	Rebar	Private	1 ins. I.R.	OK	12/9/2004 C120911A.cor
4191293.825	486559.385	03000S00500W700500	Section corner	IP/BC	GLO/BLM	2.5 ins	ok	3/11/2004 C031110A.cor
4191566.003	491698.788	03000S00500W700600	Section corner	IP/BC	GLO/BLM	2.5 ins.		3/9/2004 C030912B.cor
4191792.325	497157.202	03000S00500W700700	Section corner	IP/BC	GLO/BLM	2.5 ins	rehab.	3/9/2004 C030912B.cor
4156777.382	483893.089	03000S00600W047010	DLC cor	IP/BC	County	2.25 ins.	ok	7/9/2007 C070912A.cor
4127660.309	489452.67	03000S00600W100500	Section corner	IP/BC	County	1.25 ins	ok	3/1/2004 C030121A.cor
4129550.106	468336.224	03000S00600W140100	Quarter corner	Rebar	Private	5/8 rebar w/alum. cap	ok	4/7/2004 C040711A.cor
4130675.719	499563.811	03000S00600W140700	Quarter corner	IP/BC	GLO/BLM	3 ins	ok	8/12/2004 C081210A.cor
4132357.556	473420.898	03000S00600W200200	Section corner	IP/BC	County	1.25 ins	ok	3/1/2004 C030121A.cor
4133266.589	499463.948	03000S00600W200700	Section corner	IP/BC	GLO/BLM	2.5 ins.	ok	8/10/2004 C081009A.cor
4135845.648	499276.582	03000S00600W240700	Quarter corner	IP/BC	GLO/BLM	2.5 ins	rehab	8/11/2004 C081109A.cor
4138401.417	499153.713	03000S00600W300700	Section corner	IP/BC	GLO/BLM	3 ins	ok	8/12/2004 C081210A.cor
4149513.146	498686.91	03000S00600W500700	Section corner	IP/BC	County	1.25 ins	glo cap not vis	3/3/2004 C030323A.cor
4154663.391	498489.112	03000S00600W600700	Section corner	IP/BC	County	1.25 ins.	OK	3/8/2004 C030810B.cor
4156506.19	477584.282	03000S00600W640300	Quarter corner	IP/BC	County	2 1/2" bc	renewed today	9/21/2006 C092112A.cor
4158669.85	466880.575	03000S00600W700100	Section corner	IP/BC	County	1 1/4 ins	ok	4/7/2004 C040711A.cor
4064479.212	490418.942	03000S00800W100500	Section corner	IP/BC	County	2 1/2" bc	ok; 3 live bt's, 1 snag	4/24/2007 C042411A.cor
4066982.224	485068.562	03000S00800W140400	Quarter corner	Other	County	rot. cedar stump	renewed today	4/24/2007 C042411A.cor
4074870.17	485050.56	03000S00800W300400	Section corner	IP/BC	County	2 1/2" bc	2 live bt's	4/24/2007 C042411A.cor
4045246.385	470154.535	03000S00900W100340	Quarter corner	IP/BC	County	1.25 ins	ok	5/24/2005 C052414A.cor
4261540.279	459704.171	03100S00200W300600	Section corner	IP/BC	County	1.25 ins..	rehab	7/7/2004 C070715A.cor
4261552.415	459881.969	03100S00200W300603						7/7/2004 C070710A.cor
4264255.31	459836.96	03100S00200W340600	Quarter corner	IP/BC	GLO/BLM	3 ins. bc	ok	11/8/2004 C110812A.cor
4266913.28	459760.267	03100S00200W400600	Section corner	IP/BC	County	1.25 ins. ip	ok	11/8/2004 C110812A.cor
4237217.767	449432.915	03100S00300W400400	Section corner	IP/BC	County	1.25 ins	needs rehab. ipbc leans n. meas. plumb.	2/24/2004 C022421A.cor
4237278.181	452123.451	03100S00300W400440	Quarter corner	Rebar	Private	5/8 ins	needs rehab	2/24/2004 C022421A.cor
4237684.248	466657.247	03100S00300W400700	Section corner	IP/BC	County	1.25 ins	ok	2/24/2004 C022421A.cor
4242139.005	438644.543	03100S00300W500200	Section corner	IP/BC	County	1 .25 ins	needs rehab	2/23/2004 C022322A.cor
4247383.186	435825.553	03100S00300W600140	Quarter corner	IP/BC	County	1.25 ins	ok	2/20/2004 C022018A.cor
4252949.947	446409.542	03100S00300W700340	Quarter corner	IP/BC	Private	2 ins	ok	2/23/2004 C022322A.cor
4253200.272	457116.634	03100S00300W700540	Quarter corner	IP/BC	Private	2 ins	ok	2/25/2004 C022520A.cor
4253495.667	466216.125	03100S00300W700700	Section corner	IP/BC	County	1.25 ins	rehab	2/25/2004 C022520A.cor
4105133.731	455804.753	03100S00700W300440	Quarter corner	IP/BC	County	1 1/4 ins	needs rehab	2/2/2004 R020217A.cor

GeoXT_PLSS

4110463.418	458291.27	03100S00700W400500	Section corner	IP/BC	GLO/BLM	2 1/2 ins		2/2/2004	R020217A.cor
4110747.185	469065.095	03100S00700W400700	Section corner	IP/BC	GLO/BLM	2 ins		2/2/2004	R020217A.cor
4116030.922	468886.778	03100S00700W500700	Section corner	IP/BC	County	1 1/4 ins		2/2/2004	R020217A.cor
4069230.243	448636.569	03100S00800W200300	Section corner	IP/BC	GLO/BLM	2.5 ins	ok	4/1/2004	C040115A.cor
4041695.891	449758.645	03100S00900W300300	Section corner	IP/BC	County	2.25	OK	1/26/2004	R012622A.cor
4060805.96	462177.517	03100S00900W640540	Other	Rebar	Private	.625		1/22/2004	C012217B.cor
4060910.842	464793.465	03100S00900W640600	Quarter corner	IP/BC	County	1 .5 ins		1/22/2004	C012217B.cor
4060992.356	467433.073	03100S00900W640640	Quarter corner	Other	Private	.635	ok	2/26/2004	C022620A.cor
4062823.293	446403.074	03100S00900W700240	Quarter corner	IP/BC	GLO/BLM	2 1/2 ins	needs rehab	1/23/2004	C012323A.cor
4178430.833	408540.979	03200S00500W500200	Section corner	Other	County	1 1/2 ins		1/21/2004	C012117A.cor
4181557.615	434716.041	03200S00500W540700	Quarter corner	IP/BC	GLO/BLM	1 ins	needs rehab	1/21/2004	C012117A.cor
4148516.461	409078.095	03200S00600W038010	DLC cor	Other	County	2" I P	renewed today	4/7/2005	C040713A.cor
4149940.141	406038.886	03200S00600W038040	DLC cor	Rebar	County	5/8"	renewed today	4/20/2005	C042013A.cor
4149957.745	408229.143	03200S00600W038050	DLC cor	IP/BC	County	2 1/2" BC on 1 1/4" IP	renewed today	6/13/2005	C061313A.cor
4128091.884	426144.692	03200S00600W140500	Quarter corner	IP/BC	Other	2 ins.	ok	2/18/2004	C021819A.cor
4130166.371	410246.704	03200S00600W200200	Section corner	Other	Private	2 ins	needs renewal	2/19/2004	C021918A.cor
4141322.919	428251.068	03200S00600W400540	Quarter corner	IP/BC	GLO/BLM	2.5 ins	ok	2/19/2004	C021918A.cor
4148490.948	404283.885	03200S00600W540100	Quarter corner	Other	Private	2" IP		4/12/2005	C041213A.cor
4148670.784	409577.923	03200S00600W540200	Quarter corner	IP/BC	County	1 1/4" BC ON IP	RENEWED TODAY	4/6/2005	C040615A.cor
4148693.553	404270.859	03200S00600W543100	Quarter corner	IP/BC	Private	2 1/2" BC on 1" IP	OK	4/13/2005	C041314A.cor
4151300.99	409467.376	03200S00600W600200	Section corner	Rebar	Private	1 ins	ok	2/20/2004	C022018A.cor
4098593.793	411398.273	03200S00700W200200	Section corner	IP/BC	County	1.25 ins	ok	2/26/2004	C022620A.cor
4109391.022	421344.781	03200S00700W400400	Section corner	Other	Private	2 ins. ip	ok	2/17/2004	C021719A.cor
4114761.018	426294.692	03200S00700W500500	Section corner	IP/BC	County	1.25 ins.	OK	2/17/2004	C021719A.cor
4119150.155	410411.313	03200S00700W600200	Section corner	IP/BC	County	1.25 ins	ok	2/19/2004	C021918A.cor
4120303.385	436894.05	03200S00700W600700	Section corner	IP/BC	GLO/BLM	2.5 ins	ok	2/18/2004	C021819A.cor
4062703.69	407410.743	03200S00800W100100	Section corner	IP/BC	GLO/BLM	2.5	OK	2/5/2004	C020522A.cor
4068057.659	409822.43	03200S00800W200140	Quarter corner	IP/BC	County	1 1/4 ins	ok	1/30/2004	C013022A.cor
4073310.626	417197.166	03200S00800W300300	Section corner	IP/BC	GLO/BLM	2.5 in	ok	1/29/2004	C012920A.cor
4078264.319	412000.311	03200S00800W400200	Section corner	IP/BC	County	1 1/4 ins	ok	2/3/2004	C020321A.cor
4078363.766	417055.248	03200S00800W400300		IP/BC	County	1.25 ins	ok	1/29/2004	C012920A.cor
4078444.316	432824.925	03200S00800W400600	Other	IP/BC	GLO/BLM	2.5 ins	ok	1/29/2004	C012920A.cor
4093443.999	414164.482	03200S00800W700240	Quarter corner	IP/BC	County	1 1/4 ins	needs rehab	1/28/2004	C012821A.cor
4093637.449	419400.926	03200S00800W700340	Quarter corner	IP/BC	County	1 1/4 ins	ok	1/28/2004	C012821A.cor
4163759.624	575550.539	03300S00700W200200	Quarter corner	IP/BC	County	2 ins	rehab	3/7/2004	C030717A.cor