

GOVERNMENT CORNER RESTORATION FORM

Date: 4-6-2011 By: JC
 This survey consists of:
 Township 29S Range 6W Sec. 31 County DOUGLAS
 State OREGON Date MARCH 10, 2011 No. 140100
 Narrative: _____
 Corner Rpt: CS 67/33-23

Corner Designation

1/4 S 31 ONLY

DOUGLAS COUNTY

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals NONE

Monument(s) Found: (Condition and Source)

FROM THE 1980 ORIGINAL SURVEY
A 3 1/4 INCH DIAMETER BRASS CAP (MARKED AS
AT RIGHT) ON A 2 1/2 INCH O.D. IRON PIPE FIRMLY
SET PROTRUDING APPROX 6 INCHES ABOVE GROUND.

US DEPT. OF THE INTERIOR
 T295 R6W
1/4 S31

T305 R6W
 1980

BUR. OF LAND MANAGEMENT

Accessories Found:

TWO ORIGINAL BEARING TREES FOUND.
A FIR 5" DIA. NOW A 19 INCH D.B.H. DOUGLAS FIR WITH NO VISIBLE EVIDENCE
OF BLAZING; BEARS N55°14'E, 63[±] FEET DISTANT (RECORD N55°14'E, 64[±] FEET)
A GRAND FIR 11" DIA. NOW A 17 INCH D.B.H. GRAND FIR WITH A MOSTLY HEALED
BLAZE, SHOWING ILLEGIBLE SCRIBING; BEARS N23°12'W, 80[±] FEET DISTANT (AS PER RECORD).

