

GOVERNMENT CORNER RESTORATION FORM

Date: 4-6-2011 By: JC

This survey consists of:

Township 30S Range 6W Sec. 9 County DOUGLAS Map: _____

State OREGON Date MARCH 23, 2011 No. 400500 Narrative: _____
Corner Rpt: CS 67/33-26

Corner Designation

S9 | S10

S16 | S15

DOUGLAS COUNTY SURVEYOR

- _____ Condition Report Only
- _____ Not Found
- Renewed
- _____ Unrecorded
- _____ Surveyed In
- _____ Referenced Out

Previous Renewals 1967

Monument(s) Found: (Condition and Source)

FROM THE 1967 BLM RENEWAL:
A 3 1/4 INCH DIAMETER BRASS CAP (MARKED AS AT RIGHT) ON A 2 1/2 INCH O.D. IRON PIPE IS FIRMLY SET PROTRUDING 10 INCHES ABOVE GROUND. MONUMENT IS SET 6 INCHES SOUTH FROM THE END POST OF A SOUTH RUNNING FENCE.
AN UNRECORDED MONUMENT FIRST DESCRIBED IN THE 1967 RENEWAL. THIS IS AN IRON BOLT 1" DIA. WHICH IS FOUND TO BE A 1 1/8 INCH DIAMETER BY 30 INCH LONG IRON BOLT WITH A 2 INCH DIAMETER HEX HEAD TOP LYING LOOSE AND OUT OF POSITION; BEARING S58°W, 13 3/8 FEET DISTANT (RECORD S80°W, 20 1/2 FEET).

Accessories Found:

WE CHECK FOR ORIGINAL BEARING TREE EVIDENCE FROM THE 1967 RECORD POSITION FOR THE IRON BOLT. AT A POINT APPROX. N75°E, 29 1/2 FEET DISTANT IS A VERY LARGE ROOTHOLE ON THE EAST EDGE OF WHICH LAYS A FALLEN AND ROTTEN 20 INCH DIAMETER FIR TREE. THIS TREE IS INTACT AT ITS 4 INCH DIAMETER. WE FULLY EXAMINE THIS TREE FOR 1855 BLAZING OR SCRIBING AND FIND NONE. NO EVIDENCE OF OTHER O.B.T.'S REMAINS.
POSSIBLE EVIDENCE OF ONE BEARING TREE FOUND IN 1967, WHICH IS RELATED TO THE 1967 IRON BOLT POSITION, IS A STUMP-HOLE (NO REMAINS OF TREE); BEARING N72°W, 9 1/2 FEET DISTANT (AS PER RECORD).

EVIDENCE OF FOUR (NEWLY MARKED IN 1967) RENEWAL BEARING TREES. (MEAS'D. FROM B.C.)
A FIR 7" DIA. NOW A DEAD, STANDING, 23 INCH DIAMETER BREST HEIGHT GRAND FIR WITH NO VISIBLE BLAZE EVIDENT; BEARS N26 1/2°E, 42 1/2 FEET DISTANT (AS PER RECORD).
A FIR 20" DIA. NOW A STUMP-HOLE AND FALLEN 20 INCH DIAMETER FIR DESCRIBED IN THE O.B.T. REFERENCE ABOVE AND NOT ANY 1967 MARKINGS (EITHER); BEARS APPROX. S75°E, 12 1/2 FEET DISTANT (AS PER RECORD).
A FIR 25" DIA. NOW A FALLEN, ROTTEN, SHORT SAWN, 26 INCH DIAMETER FIR STUMP WITH NO MARKINGS VISIBLE; THE STUMP-HOLE OF WHICH BEARS S63 1/2°W, 23 3/8 FEET DISTANT (AS PER RECORD).
A FIR 22" DIA. NOW A FALLEN AND ROTTEN FIR (PARTLY BURIED) OF INDISTINCT LENGTH AND DIAMETER BUT WITH THE CLEAR SCRIBING "T30SR6W" FOUND; THE BASE OF WHICH BEARS N63°W, 30 1/4 FEET DISTANT (AS PER RECORD).

MONUMENT DETAIL

U.S. DEPT. OF THE INTERIOR
T30S R6W

S9 | S10

S16 | S15
1967

BUR. OF LAND MANAGEMENT

