

GOVERNMENT CORNER RESTORATION FORM

FILED

Township 22S Range 05W Sec. 4

County DOUGLAS This survey consists of:

State OREGON Date 4/4/11

No. 340600 Narrative:

Corner Designation

$\frac{1}{4}$ $\frac{S4}{S9}$

Corner Rpt: CS 67/33-27

DOUGLAS COUNTY SURVEYOR

- Condition Report Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals 1912, 1927, 1948, 1955

Monument(s) Found: (Condition and Source)

N/A

FROM THE 1912 RENEWAL A 1/4 INCH DIAMETER IRON ROD FIRMLY SET AND PROTRUDING 1 INCH ABOVE GROUND; FROM WHICH A 1955 RENEWAL MONUMENT BEARS S83°W, 0.5 FEET DISTANT (1983 CORNER REPORT RECORD N75°37'W, 0.50 FT.) THE 1955 MONUMENT IS A 1 INCH DIAMETER BRASS WASHER (MARKED AS AT RIGHT) ON 3/4 X 1 INCH "T" IRON FIRMLY SET AND PROTRUDING 9 INCHES ABOVE GROUND.

WILFORD N. HAINES
239
SURVEY
DRAIN, ORE.

Accessories Found:

POSSIBLE EVIDENCE OF ONE ORIGINAL BEARING TREE A R. FIR 36" DIA. NOW A REASONABLY DISTINCT ROOT-HOLE; BEARS S30°E, 47.5 FEET DISTANT (AS PER RECORD). NO EVIDENCE OF NW BEARING TREE REMAINS.

NO RENEWAL BEARING TREE EVIDENCE IS FOUND.

MONUMENTS ARE JUST SOUTH OF FALLEN F-W WIRE FENCE.

