

GOVERNMENT CORNER RESTORATION FORM

Date: 4/12/2011 By: X  
This survey consists of:

Township 21S Range 05W Sec. 32

County DOUGLAS Map: \_\_\_\_\_

State OREGON Date APRIL 6, 2011

No. 300100 Narrative: \_\_\_\_\_  
Corner Rpt: C-67/33-29

Corner Designation

532 | 533  
55 | 54

DOUGLAS COUNTY  
SURVEYOR

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

MONUMENT DETAIL

Previous Renewals 1915, 1924, 1959

Monument(s) Found: (Condition and Source)

FROM 1959 BUT OF UNKNOWN ORIGIN;  
A 1 INCH INSIDE DIAMETER IRON PIPE FIRMLY  
AND PLUMBLY SET PROTRUDING 6 INCHES ABOVE  
GROUND.  
1 1/2 INCH IRON PIPE FROM 1924 IS NOT SEEN;  
APPARENTLY DEEPLY SET.

N/A

Accessories Found:

EVIDENCE OF 2 ORIGINAL BEARING TREES.  
A FIR 12" DIA., NOW A 4 1/4 INCH DIAMETER 2 FOOT TALL FIR STUMP WITH POSSIBLE HEALED  
BLAZE; BEARS N42°E, 11 1/2 FEET DISTANT (AS PER RECORD)

A FIR 30" DIA., NOW A ROOT-HOLE CONTAINING FIR REMNANTS (NO MARKS FOUND);  
BEARS N57°W, 24 1/2 FEET DISTANT (AS PER RECORD)

EVIDENCE OF TWO 1915 RENEWAL BEARING TREES.  
A FIR 36" DIA., NOW A 60 INCH DIAMETER 3 FOOT TALL FIR STUMP, NO MARK SEEN  
(FACE SIDE BURIED UNDER PACK-RAT NEST WHICH IS NOT DISTURBED); BEARS  
S71°E, 58° FEET DIST. (RECORD S69 3/4°E, 58 FT.)

A FIR 16" DIA., NOW A DEPRESSION WITH FIR ROOTS; BEARS N68°W, 45° FEET  
DISTANT (AS PER RECORD).

EVIDENCE OF ONE 1959 RENEWAL BEARING TREE.  
A 9" FIR, NOW AN 18 INCH D.B.H., 6 FOOT TALL DOUGLAS FIR STUMP WITH A FULLY HEALED DOUBLE  
BLAZE; BEARS N51°W, 18° FEET DISTANT (AS PER RECORD).

