

GOVERNMENT CORNER RESTORATION FORM

FILED

Township 27S Range 05W Sec. 18

County DOUGLAS This survey consists of:

Date: 2-8-2012 By: JC

State OREGON Date Nov. 16, 2011

No. 100409

Map: _____
Narrative: _____
Corner Rpt: CS 67/36-1

Corner Designation _____

- DOUGLAS COUNTY
- Condition Report Only
 - Not Found
 - Renewed
 - Unrecorded
 - Surveyed In
 - Referenced Out

Previous Renewals 1936

Monument(s) Found: (Condition and Source)

A 3/4 x 24 INCH IRON ROD SHOWING EVIDENCE OF HAVING ONCE BEEN DRIVEN INTO GROUND. THIS ROD IS NOW SEVERELY BENT AND LYING ON ITS SIDE APPROXIMATELY 2 INCHES BELOW SURFACE.

N/A

Accessories Found:

NO TREES OF RIGHT AGE IN VICINITY.

RENEWAL

Monument Set (Procedure and Description)

Monument Detail

POSITION OF FOUND IRON ROD IN RELATION TO SECTION CORNER JUST TO THE SOUTH IS CHECKED USING A STAFF COMPASS AND AN EDM. THIS MEASUREMENT TO BE APPROXIMATELY 6 FEET NORTH AND 7 FEET EAST OF THE POSITION OF MEANDER CORNER SET IN 1936.

A SURVEY WOULD BE REQUIRED TO REESTABLISH THIS CORNER.

New Accessories

N/A

Sketch of Monument, Accessories, and General Area

N/A

Location & Comments

FOUND I.R. IS NEAR NORTHWEST TIP OF ELK ISLAND IN AREA SUBJECT TO MUCH FLOODING AND BRUSH CLEARING IN THE LAST 75 YEARS.

Comp. Declin. 16 1/2° E
 Agency DCSO
 Party Chief STEPHEN J FLAUSC
 Notekeeper _____
 Witnesses _____

Address

Surveyor's Seal

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

Steph J Flausc

OREGON
 JULY 25, 1900
 RANDALL W. SMITH
 2408

RETURN 6-30-2012