

GOVERNMENT CORNER RESTORATION FORM

Date: 3-12-2012 By: JC

This survey consists of:

Township 28S Range 07W Sec. 28 County DOUGLAS Map: _____

State OREGON Date JAN 17, 2012 No. 340200 Narrative: _____

Corner Rpt: CS 67/36-3

Corner Designation

1/4 S28
S33

DOUGLAS COUNTY SURVEYOR

Condition Report Only

Not Found

Renewed

Unrecorded

Surveyed In

Referenced Out

MONUMENT DETAIL

Previous Renewals 1969

Monument(s) Found: (Condition and Source)

FROM THE 1969 RENEWAL A 2 1/2 INCH DIAMETER BRASS CAP (MARKED AS AT RIGHT) ON A 1 INCH I.D. IRON PIPE, FIRMLY SET AND PROTRUDING 14 INCHES ABOVE GROUND.

COUNTY SURVEYOR'S OFFICE
T 28S R 7W

1/4 S28
S33

1969

Accessories Found:

A WIDE SEARCH WAS MADE FOR THE ORIGINAL BEARING TREES; NO GOOD EVIDENCE WAS FOUND.

EVIDENCE OF TWO 1969 RENEWAL B.T.S FOUND.

A 14" HEMLOCK NOW A 27 INCH D.B.H. 6 FOOT TALL ROTTED HEMLOCK STUMP WITH A PREVIOUSLY HEALED DOUBLE BLAZE, THE UPPER BLAZE OF WHICH HAS BEEN OPENED TO SHOW "1/4 S33 CS". THIS STUMP BEARS S54°E, 24° FT. DISTANT (RECORD S52°E, 24° FT.)

A 13" S. PINE NOW A LOW CUT 30 INCH DIAMETER 10 FOOT TALL PINE STUMP WITH THE ROTTED REMNANTS OF A LOWER BLAZE WITH THE SCRIBING "BT" EVIDENT. THIS STUMP BEARS N73 1/2° W, 51 1/2 FEET DISTANT (RECORD N72° W, 51 1/2 FT.)

