

GOVERNMENT CORNER RESTORATION FORM

FILED

Township 31S Range 05W Sec. 1

County DOUGLAS This survey consists of:

State OREGON Date JAN. 30, 2013

No. 640600

Map: _____
Narrative: _____
Corner Rpt: CS 67/38-13

Corner Designation

$\frac{1}{4}$ $\frac{S1}{S12}$

- DOUGLAS COUNTY SURVEYOR
- Condition Report Only
 - Not Found
 - Renewed
 - Unrecorded
 - Surveyed In
 - Referenced Out

Previous Renewals 1972

Monument(s) Found: (Condition and Source)

FROM THE 1972 BLM RESURVEY A 3/4 INCH DIAMETER BRASS CAP (MARKED AS AT RIGHT) ON A 2 INCH I. D. IRON PIPE FIRMLY AND PLUMBLY SET PROTRUDING APPROX. 6 INCHES ABOVE GROUND.

U.S. DEPT. OF THE INTERIOR

$\frac{1}{4}$ $\frac{S1}{S12}$

T31S R5W
1972

BUR. OF LAND MANAGEMENT

Accessories Found:

A SEARCH IS MADE FOR THE ORIGINAL B.T.'S. NO EVIDENCE OF LARGE (40+ INCH) FIRS REMAIN IN AREA AND THE ONE LARGER MADRONE STUB FOUND IS ROTTED, BROKEN AND LACKING ANY BLAZE OR FACE EVIDENCE.

THE TWO 1972 BEARING TREES.

A FIR 10" DIA. NOW A 12 INCH DIAMETER DOUGLAS FIR WITH A FULLY HEALED DOUBLE BLAZE; BEARS N12°W, 40² FEET DISTANT (AS PER RECORD).
A FIR 20" DIA. NOW A 28 INCH DIAMETER DOUGLAS FIR WITH A FULLY HEALED DOUBLE BLAZE; BEARS S61°W, 30¹ FEET DISTANT (RECORD S61°W, 31² FEET WHICH MAY BE A SLOPE DISTANCE).

C.S. File No 67/38-13

