

JULY 17, 2017

²⁹
~~T305, R04W, E¹4531, PLSS200140~~

● CAUTION REPORT.

FIND DEC 5 2018

MONUMENTS AND ACCESSORIES ARE FOUND

● AS DESCRIBED IN THE 1992 BLM DEPENDENT RESURVEY AND THE 2010 DAVID EDWARDS RENEWAL WITH THE FOLLOWING

● EXCEPTIONS: TWO B.T.'S REFERENCING THE 1947, 3/4 INCH DIA. IRON ROD WHICH FORMERLY STOOD AS THE 1/4 COR.; A FIR 14" DIA. IN THE SW QUADRANT, IS NOW A 15" DIA., 5 FT. TALL D. FIR STUMP WITH A FULLY HEALED DOUBLE BLAZE; A FIR 15" DIA. IN THE SE QUADRANT, IS NOW A 16" DIA., 3 1/2 FT. TALL D. FIR STUMP WITH A FULLY HEALED DOUBLE BLAZE.

● ONE OF THE B.T.'S FOUND BY EDWARDS IN 2010, REFERENCING THE BLM 1/4 CORNER MONUMENT; A 12" FIR IN THE SW QUADRANT, IS NOW A 16" DIA. 7 FT. TALL D. FIR STUMP WITH A HEALED BLAZE.

C.S. FILE 67/45-17