

FD OK

TOWNSHIP 25 RANGE 06 POINT IDENTIFIER # 100640
700640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 1; & Sec. 6, T25-6

| | |
|-------------|-------------------|
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |
| Alias _____ | Description _____ |

NOV 5 2019

Bruce Shaner Engineering - For: Wester Timber Company - July 28, 1989 - C.S. File 63/96 and RM 3-72

CORNER REPORT ONLY

Found - 1" Iron pipe with 2 1/2" brass cap erroneously marked "County Surveyors Office W 1/4 S6 T25S R6W R7W 1963", from which

- 36" D.Fir now a rotten stump bears S.38°E., 42.2 ft.
- 36" D.Fir, face overgrown bears S.58 1/2°W., 71.9 ft.
- 8" D.Fir face overgrown, bears N.76°E., 12.2 ft. (BLM record 21.4 ft.)
- Now & SNAG 10" D.Fir, face overgrown, bears S.26 1/4°E., 21.4 ft. (BLM record 12.2 ft.)

Apparently there was a transcription in USBLM notes on above 2 trees' distances. Also, BLM notes say that the above corner erroneously mkd. & is actually common to both sections 1 & 6. Corner lies West approx. 80 ft. from the main road (dirt) along the top of Tye Mt. ridge.

DCSO-GIS Corner visitation - 7/7/2004 - Typed: 1/24/2011 - C.S. File 67/33-1

| | |
|------------|-------------|
| Monument - | 1.25" BC/IP |
| Comment - | OK |

FND OK
11/5/19

UNRECORDED RBG 10x60' FIR SNAG PARTIALLY HEALED BLZ. N 57° W, 243
"BT" SINGLE

FIR AT EDGE OF
LINE TAG ON FOREST ACCESS RD, S 30° E, 50'

LAT: 43.42397467

LONG: -123.4658312

DCSO
SJF AND JL

FILED
Date: 12/18/2019 By: SC
This survey consists of:
Map: _____
Narrative: _____
Corner Rpt: CS 67/46-9

DOUGLAS COUNTY SURVEYOR