

PRIMARY CORNER DESCRIPTION No 1/4 Cor for Sec 5 only

Alias	Description
Alias	Description
Alias	Description
Alias	Description

Brush cleared around monument and to BTs
"LAND LINE" flagging tied on monument & guard posts
Note - Corner falls on north slope under a barbed wire a few feet east of a large fir tree fence corner. Park at dispersed campsite on south side of FS road 150 just prior to first cattle guard, walk south to fence line then west to corner. Maintain line .5 miles south.

Adam DeGroot - For: USFS - Oct 2019 - M171-69A&B

Found - A 2 1/4" iron post by Weaver, in 1980 per C.S. File 58/176-34, firmly set and projecting 8" above ground in an 18" diam. stone mound, with a 2 1/2" brass cap (properly) mkd:

BTs by DCSO IN 1968 -

A 13" G.Fir bears S.31°E., 18.9 ft w/healed dbl blaze (S.28°E., 19.4 ft-DCSO 1968) (S.31°00'E., 19.0 ft-Weaver 1980)

A 14" W.Fir bears S.38°'15'W, 15.5 ft w/healed dbl blaze (S.38°W., 16.6 ft-DCSO 1968) (S.39'03'W., 18.0 ft-Weaver 1980)

New RM - A 5/8"X30" iron rod w/2" alum. cap mkd. "BTS SURVEYING INC RM 1 PLS 89398" bears N.31°00'03"W., 19.67 ft

The section corner of S32/S33 bears S.89°50'26"E., 158.28 ft (line of sight)

A 6"x10" split cedar fence corner of fences east and south bears S.50'E., 2.0 FT

6/3/2020

LAT: 42.828683450

LONG: -122.844203217

FD
OK
DCSO
SSK
SL