

FND OK 7/7/20

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 600340

DCSO Stephen  
Flaur & Jeff  
Lorsung

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 23 and 24

Alias \_\_\_\_\_ Description \_\_\_\_\_ FILED  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Date: 7-13-2020 By: X  
This survey consists of:

Map: \_\_\_\_\_  
Narrative  
Corner Rpt: CS 67/46-36

Original, Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO Records, Volume 9 Page 3672)  
-----  
Set Dogwood post, on ridge course E. and W., 3 ft. long, 3" sq., 24" in the ground for 1/4 sec. cor. mkd. 1/4 S on W. face, from which  
    A Fir 12" dia., bears N.20°E., 18 lks. dist., mkd. 1/4 S BT.  
    A Fir 36" dia., bears S.65°W., 25 lks. dist., mkd. 1/4 S BT.

DOUGLAS COUNTY  
SURVEYOR

GLO Dependent Resurvey by Norman D. [unclear] Instructions dated April, 5, 1942 (7 Pages 11544-45)  
-----  
Point for original 1/4 sec. cor. de record bearings from both old be corner, set an iron post, 3 ft. ground, for 1/4 sec. cor., with br  
  
from which  
    A Fir 60" dia., bears N.20°  
        I uncovered the scribe years of overgrowth.  
        inscription on this ol  
    A Fir 36" dia., bears S.65°  
        I uncovered the scribe years of overgrowth.  
        inscription on this ol  
The old blazed line passes directly through this cor. point.

LAT: 43.37689621  
LONG: -123.012550933

Doug. County Surveyors Office - Vernon Tracy; Mike Stone; Jack Heritage - June 9, 1966 - C.S. File 54/7-62  
-----  
Found - 1943 GLO brass cap, out of ground.  
    Orig. 36" now 42" Fir S.65°W., 48.8 ft., open, face pitched over, "23" scribe visible. Alive but top broken off approx. 80 feet up.  
    Orig. 60" now 70" Fir N.20°E., 17.8 ft., now stump & turned out, shows "24" scribe on face.  
Reset - Brass cap mkd: "1/4 S 23|S24 1943"  
New BTs - 14" Hemlock S.38°W., 70.9 ft. mkd. 1/4 S23 CS BT.  
          12" Hemlock N.58°E., 141.1 ft. mkd. 1/4 S24 CS BT  
Corner falls on N. edge of cat road, course NE and SW and on edge of logged off unit in section 24  
(Cont. Next Page)

1  
C.S. FILE 67/46-36



TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 600340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 23 & 24

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

from which the remains of the original bearing trees

A roothole bears N.20°E., 17.8 ft., alongside of which is an uprooted, sawed, decayed fir stump, 60" dia., with fragmentary scribe marks visible on a partially healed blaze.

A sawed fir stump, 36" dia., bears S.65°W., 48.8 ft., with scribe marks 23 visible on a partially healed blaze, with a metal cover.

and the remains of bearing trees mkd. by the Douglas County Surveyors Office in 1966, reported by Bedell

A sawed, decayed fir stump, 15" dia., bears N.55°E., 141.2 ft.; with fragmentary scribe marks visible on a partially healed blaze.

A sawed hemlock stump, 18" dia., bears S.37°W., 70.6 ft., with fragmentary scribe marks visible on a partially healed blaze, with a metal cover.

and bearing trees mkd. by Bedell

A fir, 17" dia., bears S.50°E., 10.2 ft., with a healed blaze.

A fir, 8" dia., bears S.82°W., 16.5 ft., with a healed blaze.

and the remains of a bearing tree mkd. by person(s) unknown

A sawed, decayed fir stump, 48" dia., bears N.31½°W., 55.2 ft., with a healed blaze and Weyerhaeuser aluminum bearing tree tag mkd. W.T. CO. Sec. 23 TWP 25 S. R. 8

W. 54.5 FT. S 31 E TO E ¼ COR.

Corner is located on a gradual S. slope.