

MARCH 11, 2019

PLSS: 400300

T24SR8WS21

521 | 522

Filed NOV 17, 2001

528 | 527

CREW:

CREW CHIEF: S. J. FLAISE

TECH: J. A. LORSUNG

MONUMENT:

FROM 1959 BLM SURVEY

A 3 1/4" DIA. BRASS CAP ON A 2" I.D. IRON PIPE
CAP STAMPED "U.S. CADASTRAL SURVEY"
T24SR8W

521 | 522

528 | 527

1959

BUR. OF LAND MANAGEMENT

PROJ:

FLUSH WITH
GROUND

FOUND:

EVIDENCE OF THREE O.B.T.'s

A 30" DIA. 2 FT. TALL ROTTED FIR STUMP WITH
A HEALED BLAZE; BEARS N41°E, 41 1/2 FT. DIST. (PER
RECORD). A 39" DIA. 50 FT TALL D. FIR SNAG

WITH FHSB AND TIMBER CO. "Z" IN BARK; BEARS
S52 1/2°E, 20 1/2 FT. DIST. (REC. S52 1/2°E, 21 1/2 FT.)

A 57" DIA. D. FIR WITH FHSB; BEARS N4°W,
46 1/2 FT. DIST. (REC. N4°W, 48 1/2).

FOUR 1959 BLM SURVEY B.T.'s

OVER →

CS 67/50-16

FOUND CONT'D:

A 24" DIA. DOUGLAS FIR (NOT W. FIR)
WITH FHSB BEARS N13°E, 23° FT. (REC
23² FT.). A 21" DIA. GRAND FIR (AKA W. FIR)
WITH FHSB; BEARS S16°E, 34² FT. DIST (PER RECORD)
A MOSTLY ROTTEN AWAY TIPOUT ROOT HOLE
NEAR REC (B. & D). A 19" DIA. D. FIR (NOT
A W. FIR) WITH FHSB; BEARS N18¹/₂°W, 26° FT
DIST (REC. 27¹/₂ FT. DIST.)

S 33¹/₂° W 27¹/₂ FT

CS 67/50-16

MARCH 11, 2019

TOWNSHIP 24 RANGE 08 POINT IDENTIFIER # 400300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 21, 22, 27 and 28

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 8 Page(s) 3343)

Set a post 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 21, 22, 27 and 28 marked, T24S S22 on NE.; R8W S27 on SE.; S28 on SW.; and S21 on NW. faces, with 2 notches on S. and 3 notches on E. edges, from which

SEE BLAZE A Fir 20" dia., bears N.41°E., 63 lks. dist. mkd. T24S R8W S22 BT.

SEE BLAZE A Fir 20" dia., bears S.52½°E., ²¹⁸33 lks. dist. mkd. T24S R8W S27 BT.

GONE A Fir 30" dia, bears S.37°W., 109 lks. dist. mkd. T24S R8W S28 BT.

57" ^D A Fir 20" dia., bears N.4°W., ⁴⁸²73 lks. dist. mkd. T24S R8W *FHSB* S21 BT. ₄₆₂

BLM corner remonumentation by Harold D. Corbin, Cadastral Surveyor, under Group #'s 350 and 427, Surveyed June 1959 - (DCSO records Vol. 30 Page(s) 12614-15)

The sec. cor., determined at record bearing and distance from the original bearing trees:

30"x2'TALL ROTTED STUMP A sawed Fir stump 35" dia., bears N.41°E., ⁴⁴²63 lks. dist., with a healed blaze.

39" x 50" D. FIR SNAG A Fir 38" dia., bears S.52½°E., ²⁰⁸33 lks. dist. with a healed blaze. *FHSB TIMBER CO. "Z" IN BARK*

GONE -rotted Fir stump 35" dia., bears S.37°W., 109 lks. dist. with illegible scribe marks visible on partially opened blaze.

57" ^D A Fir 40" dia., N.4°W., ⁴⁸²73 lks. dist. with a healed blaze.)

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

^{3 1/4"} T 24 S R 8 W U.S. CADASTRAL SURVEY
_{ON 2" IRON} S 21 S 22
S 28 S 27

from which

24" ^D A Fir 7" dia., bears N.13°E., ²³⁰36 lks. dist. mkd. T24S R8W S22 BT. *BUR OF LAND MANAGEMENT*

21" ^D A Fir 7" dia., bears S.16°E., ³⁴³52 lks. dist. mkd. T24S R8W S27 BT. *FHSB*

ROTTEN IRON A Hemlock 13" dia., bears S.33½°W., ²⁷²83 lks. dist. mkd. T24S R8W S28 BT. *HOLE NEAR BED*

19" ^D A Fir 7" dia., bears N.18½°W., ²⁷²41 lks. dist. mkd. T24S R8W S21 BT. *FHSB* ₂₆₀

(Cont. Next Page) *FIND AND USED IN BLM SURVEY 1962 PG. 13321*

52	37	36	83	73	41	1
	6	6	6	6	6	
3162	198	216	488	438	246	
3143	198	216	490	438	246	
3	2178	2376	4778	4818	2706	

CS 67/50-16