

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 26S RANGE 3W SEC. 11 PLSS # 600540

Date: 11-22-2021 By: XL

This survey consists of:

DOUGLAS COUNTY OREGON

DATE 6-7-21

Map: _____

Narrative: _____

Corner Rpt: CS 67/51-9

Corner Designation

DOUGLAS COUNTY
SURVEYOR

1/4 COR S11/S12

Previous Renewals _____
Monument(s) Found: (Condition and Source)

- _____ Condition Report
- _____ Not Found
- _____ Renewed
- _____ Unrecorded
- _____ Surveyed In

MONUMENT DETAIL

2" OD Alum pipe protruding
15" Above ground

IRVING 1933 CS 37/155

DCSO 1977 CS 59/46-26

DCSO 1988 CS 62/52-6

Accessories Found

LARGE Root Hole S15°W 76 FT

28" Cedar (Burnt Dead snag) S59°W 57 FT
(Rec 56 FT)

Root Hole N59°W 54 FT

6" Yew (Burnt stub) S16°E 29 FT

20" D Fir S36°W 17 FT (Rec 17 FT) Healed Double
BLAZE

11" D Fir (20' tall burnt snag) N59½°E 19 FT
(Rec 19 FT) Healed Double BLAZE

RENEWAL

Monument Set (Procedure and Description)

MONUMENT DETAIL

New Accessories

ADDED 4" MAG NAILS RIGHT SIDE CENTER ROOT CROWN TO 28" CEDAR - 20" D. FIR & 11" D. FIR

9" HEMLOCK (BURNT DEAD) N 70° W 17 1/2 FT TO 4" MAG NAIL RIGHT SIDE CENTER ROOT CROWN

Sketch of Monument, Accessories, and General Area

Location & Comments

LAT 43° 19' 21.23"

LONG 123° 00' 41.03"

AREA BADLY BURNT 9/2020

Comp. Decline. 143 1/4° E

Agency DCSO

Party Chief S. F. AUSE

Note keeper J. LORSUNG

Witnesses

REGISTERED PROFESSIONAL LAND SURVEYOR

Ronald A. Quimby

OREGON JULY 14, 1978 RONALD A. QUIMBY 1654

Expires: 12/31/2022

CS 67/51-9

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 26S RANGE 3W SEC. 11 PLSS # 600540

Date: 11/22/2021 By: XC
This survey consists of:

DOUGLAS COUNTY OREGON

DATE JUNE 7, 2021

Map: _____

Narrative: _____

Corner Rpt: CS67/51-9

DOUGLAS COUNTY
SURVEYOR

Corner Designation

1/4

S11 | S12

- _____ Condition Report
- _____ Not Found
- Renewed
- _____ Unrecorded
- _____ Surveyed In

Previous Renewals 1933, 1977, 1988
Monument(s) Found: (Condition and Source)

MONUMENT DETAIL

A 2 INCH O.D. ALUMINUM PIPE
PROTRUDING 15" ABOVE GROUND.
THIS PIPE IS OF UNKNOWN ORIGIN;
FIRST FOUND IN 1977 REPORT.

N/A

Accessories Found

POSSIBLE ORIGINAL BEARING TREE EVIDENCE:
RECENTLY BURNED OUT ROOTHOLE (LAST NOTED AS A 36" DIA. X 3 1/2
FT. TALL D. FIR STUMP); BEARS CLOSE TO RECORD BEARING AND DISTANCE
RECORDED IN 1988.

FROM THE 1933 DCSD RENEWAL EVIDENCE OF ONE B.T.
A 28" DIA. BURNT AND DEAD CEDAR SNAG WITH A FULLY HEALED DOUBLE
BLAZE; BEARS S59°W, 57' FT. DISTANT (BEARING AGREES WITH 1977 RE-
NEWAL, DISTANCE IS TO RIGHT SIDE CENTER NAIL).

FROM THE 1977 DCSD RENEWAL, EVIDENCE OF ONE BT MARKED BY HALE IN 1946
(NO WRITTEN RENEWAL RECORD FOUND)

A 6" DIA. BURNT YEW(?) STUB; BEARS S16°E, 29' FT. DISTANT (PER 1977 REC.).

FROM THE 1988 DCSD RENEWAL TWO B.T.s:
AN 11" X 20 FT. TALL BURNT D. FIR SNAG

RENEWAL

Monument Set (Procedure and Description)

MONUMENT DETAIL

New Accessories

Sketch of Monument, Accessories, and General Area

Location & Comments

Comp. Decline. _____
 Agency _____
 Party Chief _____
 Note keeper _____
 Witnesses _____

**REGISTERED
 PROFESSIONAL
 LAND SURVEYOR**

Ronald A. Gumbly
**OREGON
 JULY 14, 1978
 RONALD A. GUMBLY
 1054**

Expires: 12/31/2022

CS 67151-9
rlc

TOWNSHIP 26 RANGE 03 POINT IDENTIFIER # 600540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 11 and 12

FEMA COR
6/7/21

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - W. H. Byars, Contract #317, dated Jan. 20, 1879
(DCSO records, Vol. 10 Page 4383)

Set Chinquapin post, 5 ft. long, 6" dia., 24" in the ground, for the 1/4 sec. cor. bet. secs. 11 and 12, from which
A Chinquapin 10" dia., bears N.60°E., 17 lks. dist.
A Fir 36" dia., bears S.10°W., 10 lks. dist.

Ben B. Irving - M.L. Kimmel; Fred Schmidt; N.E. Richardson
Feb. 6, 1933 - C.S. File 37/155

Location identified from D.B.T., 36" Fir, S.10°W., 10 lks.
Set a Fir post 4 x 4 x 42" from which ^{29th}
A Fir 18" dia., bears S.28°E., 45 lks. mkd. 1/4 S13 CSBT.
A Cedar 15" dia., bears S.44°W., 85 lks. mkd. 1/4 S11 CSBT.
(Old typed renewal called this a Fir, which was a
typo error). ^{56th}

CORNER REPORT ONLY - Doug. County Surveyors Office - R.B. Kimberling; M. W. Cline - Sept. 28, 1977 - C.S. File 59/40-26

Found - 1 1/2" alum. alloy pipe 12" above ground.
36" now 26" fir snag, badly rotted, bears S.15°W., 7.6 ft. (OBT rec. S.10°W., 6.6 ft.)
15" now 20" Cedar bears S.59°W., (Rec. S.44°W.) 56.1 ft. Found partly healed blaze & scribing "S11 CS".
12" now 30" S.Pine bears N.59°W., 53.5 ft. with a well healed blaze.
5" now 8" Yew bears S.16°E., 29.7 ft. with a well healed blaze.
(Pine and Yew marked by Hale in 1946) (Record source unknown, probably Weyerhaeuser.)

Doug. County Surveyors Office - Randall Smith; Stephen Flauser
May 18, 1988 - C.S. File 62/52-6

Found - A ^{15"} 2" O.D. alum. pipe protruding 12" above ground. Source unknown.
A position at record (S.44°W., 56.1 ft.) was occupied from 23" Cedar BT, no other evidence
(Cont. Next page)

CS 62/51-9

5/4

TOWNSHIP 26 RANGE 03 POINT IDENTIFIER # 600540

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 11 and 12

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

36" now approx. 38" dia., 3 1/2 ft. high rotted D. Fir stump, no blazes or scribing found, bears *ARGE ROOT HOLE* S.15°W., 7.6 ft. (agrees w/rec. per 1988 report) (Orig. rec. S.10°W., 6.6 ft.; dist. is a possible face measurement) Possible Orig BT.

1933BT 28" BURNT DEAD SNAG

15" now 23" dia. Cedar with a partially healed upper and fully healed lower blaze, scribing visible in upper blaze "S11CS" bears S. 59°W., 56.1 ft. (agrees w/1988 record) (Rec. per 1933 Irving, 15" Fir S.44°W., 56.1 ft.) (Tree species is a Cedar in Irving's field book)

FHDB 57 4" MAG RSC

NO EVID REMAINING 18" dia. Fir is gone, possible stump hole found bearing S.41 1/2°E., 29.7 ft. (Rec. per Irving is S.28°E., 29.7 ft.)

Note: Bearings on ~~Irving~~ are North of their record position by approx. ~~the~~ angle.

ROOT HOLE 12" now 36" dia. S. Pine with an axe bark blaze "N/V" and a small healed lower blaze, bears N.59°W., 54.8 ft. (Rec. N.59°W., 53.5 ft. is a possible face measurement, source unknown)

BURNED 6" STUB

5" now 8" dia., Yew with a partially healed double blaze, upper blaze opened, no scribing found. Lower blaze has a Weyerhaeuser W nail set in it, bears S.16°E., 29.7 ft. (agrees with record, source unknown).

Last 2 trees noted as source unknown are possible BTs by Marion D. Hale, date 1946, see C.S. File 53/115.

New BTs *20"* 9" D. Fir double blazed and scribed "1/4 S11 CS BT" bears S.36°W., 17.5 ft. *17L FHDB 4" MAG RSC*
11" x 20FT BURNT SNAG 8" D. Fir double blazed and scribed "1/4 S12 CS BT" bears N.59 1/2°E., 19.5 ft. *192 FHDB 4" MAG RSC*

FD. Ok, 4 live BTs as per 1998 renewal, DCSO 2/26/2008, J. Pike & S. Flause, C.S. File 67/25-20

NEW 9" x 3FT SAW FIR STMP S09°E, 23" TO 4" MAG NAIL TO CNTR

NO BLZ NO SCR

9" BURNED DEAD HEMLOCK N70°W, 17" TO 4" MAG RSC

NO BLZ NO SCR

CS 67/50-9

616