

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 255 RANGE 3W SEC. 9

PLSS # 400540

Date: 11/22/2002 By: SC  
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 6/15/21

Map: \_\_\_\_\_

Narrative: CS

Corner Rpt: 67/51-10

Corner Designation

1/4 COR 9/10

DOUGLAS COUNTY SURVEYOR

Previous Renewals \_\_\_\_\_  
Monument(s) Found: (Condition and Source)

- \_\_\_ Condition Report
- \_\_\_ Not Found
- \_\_\_ Renewed
- \_\_\_ Unrecorded
- \_\_\_ Surveyed In

MONUMENT DETAIL

1" ID IRON PIPE WITH 2 1/2"  
BRASS CAP PROJECTING 3"

Douglas County  
Surveyor

GLD Dependent Resurvey 1940  
DCSO 1966 CS 54/27-57  
BLM 1987-1988 Vol 48 pg 18498  
DCSO 2016 CS 47/44-22

1/4  
T255R3W  
59/510  
2016

Accessories Found

21" FIR N 57 1/4 W 29 FT (44 LKS) HEALED SCAR  
NEW WASHER IN FACE  
BURNT FIR STUMP (ROOTS) S 18 1/2 E 81 1/2 FT  
20" X 2' BURNT STUMP N 8 1/2 W 72 1/2 FT  
16" X 3 1/2 FT D. FIR STUMP WITH NAIL & WASHER TOP  
CENTER S 59 E 10 1/2 FT (REC 9 FT) HEALED BLAZE  
18" X 4 1/2 FT BURNT D. FIR STUMP N 80 1/4 E 20 1/2 FT  
BURNT FACES SOME SCRIBING  
DEAD 6" D. FIR S 58 W 57 1/2 FT PARTIALLY HEALED  
DOUBLE BLAZE NEW WASHER IN FACE

---



---



---



---



---



---

New Accessories

---



---



---



---



---



---



---



---



---



---



---



---



---



---



---



---



---



---



---



---



---



---

Sketch of Monument, Accessories, and General Area

Location & Comments

LAT 43°24'58.41" N  
 LONG 123°02'48.92" W

AREA Badly  
 BURNT 9/2020

---



---



---



---

Comp. Decline. 15° E  
 Agency DCSO  
 Party Chief J Fause  
 Note keeper  
 Witnesses J LORSUNG

Surveyor's Seal

CS 67/5610

6/15/21

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs 9 and 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original, Laban H. Wheeler, Under Contract #467 dated April 7, 1883 (DCSO Records, Volume 9 Page 3699)

-----

Set Cedar post, 3 ft. long, 3" sq., 24" in the ground for 1/4 sec. cor. mkd. 1/4 S on W. face, from which

A Fir 8" dia., bears N.61°W., 10 lks., mkd. 1/4 S BT.

A Fir 6" dia., bears S.55°E., 5 lks., mkd. 1/4 S BT.

GLO Dependent Resurvey by Norman D. Price, Under Special Instructions dated April, 5, 1940. (DCSO records, Volume 27 Pages 11572-73)

-----

Point for original 1/4 sec. cor., determined by reference to the record bearing and distance from the old SE. BT.

At point for corner, Set an iron post, 3 ft. long, 1" dia., 28" in the ground, for 1/4 sec. cor., with brass cap mkd.

1/4  
S9|S10  
1943

from which

A Fir 18" dia., dead and down, bears S.55°E., 5 lks., mkd. 1/4 S BT. (Old BT)

A Fir 50" dia., bears S.18 1/2°E., 126 lks., mkd. 1/4 S10 BT. (New BT)

A Fir 16" dia., bears N.8 1/2°W., 110 lks., mkd. 1/4 S9 BT.

Doug. County Surveyors Office - Vernon Tracy; Joe Brady; Jack Heritage - July/Aug. 1966 - C.S. File 54/27-57

-----

Found - GLO brass cap mkd. 1943, with steel fence post set alongside.

16" now 34" Fir N.8 1/2°W., 72.6 ft., shows very good scar. We do not open.

SE BT now gone.

New BT - 5" D.Fir S.58°E., 9.7 ft. mkd. 1/4 S10 CS BT.

This corner lies on E. edge of rock road, course S.30°W., and N.30°W.

Bureau of Land Management Survey, Subdivision of Section by Wayne Rogers, etal - Group #1386 - Survey, June 1987 Sept. 1988 (DCSO records, Volume 48 Page 18498) (added 11/2017)

-----

The 1/4 sec. cor. of secs. 9 & 10, monumented with an iron post, 1" dia., firmly set, the top flush with the ground, with brass cap (properly) mkd.

from which continued next page

6/14/21  
MMGPS

23-5-400540 TIME 12:00 H.I. = 1.0815m

CS 67/51-19

6/15/21

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 9 & 10

Alias	Description
Alias	Description
Alias	Description
Alias	Description

A decayed fir snag, size indeterminate, bears" dia., bears S.18½°E., 123 lks., no marks visible (rec. 126 lks.)  
 A sawed fir stump, 30" dia., bears N.8½°W., 110 lks, with healed blaze.  
 and a BT mkd. by VR Tracey in 1966  
 A fir, 11" dia., bears S.59°E., 15 lks., with healed double blaze.  
 and a new BT <sup>21"</sup>  
 A fir, <sup>21"</sup> dia., bears N.57¼°W., 44 lks., mkd. ~~S9 BT~~ <sup>FHSD</sup>

NEW WASHER IN FACE

Douglas Co. Surveyor's Office - Crew: Stephen Flause & Mike Koch - 7/18/2016 - C.S. File 67/44-22

Found - The top 12" of the broken 1943 USGLO monument is fd loosely driven into the road shoulder and bearing N.81½°E., 2.25 ft. from the restored corner position.

BTs by Price in 1943 -

<sup>BURNT TO GROUND</sup> A 40" dia. x 30" tall rotted fir stump bears S.18½°E., 81.2 ft. <sup>BURNT ROOTS</sup>

<sup>NEW BURNT 20" X 2 FT STMP.</sup> A 36" Dia. x 24" tall rotted sawn fir stump bears N.8½°W., 72.6 ft. with scribe marks <sup>"S9 BT"</sup> visible on a rotted blaze.

A BT by Tracy in 1966 -

BURNT D. FIR STMP

<sup>16" X 3 1/2 FT</sup> A <sup>17"</sup> dia. D.Fir bears S.59°E., 9.7 ft. with a healed single blaze. <sup>WASHER TOP CNTR N59°E, 10.3</sup>

Set - At the position determined from the fd accessories set a 1" (I.D.) x 32" iron pipe, 29" in the ground with a 2 1/2" dia. Brass cap marked:  
DOUGLAS COUNTY SURVEYOR

T25S R3W  
S9|S10  
2016  
✓ PROV 3"

BURNT D FIR STMP

<sup>18" X 4 1/2 FT</sup> The broken USGLO monument remnant is set along the S edge & now projects 1" above the ground

New BTs- A <sup>19"</sup> dia. D.Fir bears N.80¼°E., 20.4 ft. scribed <sup>"S10 CS BT"</sup>. <sup>BURNT FACES SOME SCRIBING.</sup>

DEAD <sup>6"</sup> A <sup>5"</sup> dia. D.Fir bears S.58°W., 57.6 ft. scribed <sup>X CS BT"</sup> <sup>KH H-LO BLT</sup>

A steel fence post bears south, 2.0 ft.

Location & comments - All BTs have BT tags attached. All new BTs have double blazed faces with bearings measured to the center of the tree at the root crown and distances measured to the side and center of the root crown.

continued next page

CS 67/51-10<sup>2</sup>

TOWNSHIP 25 RANGE 03 POINT IDENTIFIER # 400540

6/15/21

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 9 and 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

The monument falls on the east edge of a gravel road with old mixed fir reprod to the east & young D.Fir reprod to the west. See the sketch map in the attached field notes.  
Compass declination: 15° E.

*NEW REFS*

*NAIL BRASS WASHER / FACE — SEE NEW TREES PG. 2 S 58° W 57 8*  
*21" FIRE KILL D. FIR N 57 1/2° W 28 4*