

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 21S RANGE 11W SEC. 2 PLSS # 600640

Date: 11/23/2021 By: X

This survey consists of:

DOUGLAS COUNTY OREGON

DATE 6-2021

Map: \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Rpt: CS 62/51-11

Corner Designation

1/4 S2/S1

DOUGLAS COUNTY SURVEYOR

Previous Renewals 3/4" IRON Pipe  
Monument(s) Found: (Condition and Source)

- \_\_\_ Condition Report
- \_\_\_ Not Found
- \_\_\_ Renewed
- \_\_\_ Unrecorded
- \_\_\_ Surveyed In

MONUMENT DETAIL

Thiel 1891 Vol 3 Pg 1195  
LANE 1938 CS 19/18A  
HINTZ 1984 M 96-5

Accessories Found

Thiel BT'S  
58" R. CEDAR S 44 1/2 E 19? HEALED SCAR (REC  
1891 S43°E 22.4 FT)

HINTZ 1984  
50" R. CEDAR S 81 1/2 W 44.4 FT Partially healed  
BLAZE ROTTED

RENEWAL

Monument Set (Procedure and Description)

MONUMENT DETAIL

Replace 3/4" Iron Pipe with  
A 1" ID Iron Pipe with  
2 1/2" BRASS CAP Projecting  
7" Above ground. Re set 3/4"  
Iron pipe 0.2' N.W. Flush

Douglas County Surveyors  
OFFICE  
1/4  
T21S R11W  
52 | S1  
2021

New Accessories

Rescribed 50" R. Cedar S 81 1/2° W 44 1/2 FT  
Scribe CS BT with 8" MAG NAIL 44 1/2 FT  
39" R. Cedar N 9° E 40.5 FT Scribed 1/4 S1 CS BT  
on Double black 4" MAG NAIL Side Center Root  
Crown  
16" Alder S 20° W 27 1/2 FT BARK Scribed  
1/4 S2 CS BT 4" MAG NAIL Side Center of  
Root Crown

Sketch of Monument, Accessories, and General Area

Location & Comments

LAT. 43° 14' 29.9" N  
LONG 123° 58' 01.3" W

CORNER IS ON A Steep  
N.W. Slope in Timber  
Approx. 250 S.E. of  
Southern BANK OF  
SMITH RIVER & 100 FT  
S.E. OF TOE OF Slope  
& RIVER Bench  
Comp. Decline. 16' 6"  
Agency DCSO  
Party Chief K. De Groot  
Note keeper ;  
Witnesses J. Lorusung  
S. FLAUSC

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

Ronald A. Qumby

OREGON  
JULY 14, 1978  
RONALD A. QUMBY  
1654

Expires: 12/31/2022

CS 62/51-11



TOWNSHIP 21 RANGE 11 POINT IDENTIFIER # 600640

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Secs. 1 and 2

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by John W. Meldrum, Deputy surveyor, under Contract #116, dated December 16, 1866 (DCSO records Vol. 3 Page(s) 1166)

-----

Set 1/4 sec. post, from which  
 A Spruce 12" dia., bears N.65°E., 31 lks. dist.  
 A Cedar 7" dia., bears N.45°W., 48 lks. dist.

GLO survey by Wm. Thiel, Deputy Surveyor, under Contract #567, dated Feb. 16, 1891 (DCSO records Vol. 3 Page(s) 1195)

-----

The 1/4 sec. cor. bet. 1 and 2; which having been destroyed, I replace by setting a post, 3 ft. long, 3" sq. for 1/4 sec. cor. mkd. 1/4 S on W. face, from which  
 A stump of Cedar 10" dia., bears N.45°W., 48 lks. dist. mkd. BT. This is the only remnant of former survey.  
 A Cedar 10" dia., bears S.43°E., 34 lks. dist. mkd. 1/4 S, BT.

~~B. A. Lane - April 14, 1938 - C.S. File 19/18A~~

-----

Found old stake mkd. 1/4 C.S.  
 Set steering gear of an auto.  
 Old stump decayed to badly to identify checks for dist. and bearing.  
 Orig. 10" Cedar, burned badly, no scribe. Marks visible.  
 Checks Brg. & Dist., remarked 1/4 S CS BT.  
 30" Cedar S.43°E., 26 ft.  
 8" Alder S.28°W., 17 1/2 ft.

Survey by Richard J. Hintz - For: International Paper Co. - Feb. 1984 - M 96-5

-----

Found 1/2" I.P. with alum. alloy fixture (origin unknown) from which:  
 50" Cedar bears S.44°30'E., 19.9 ft. (1891 BT, Rec. S.43°E., 22.4 ft.)  
 New BT, 28" Cedar S.81°30'W., 44.7 ft., scribed.

43°46'29.9"  
 123°58'01.3"

39" R. Cedar bears North, 40°5'

CS 62/51-11  
 1