

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 24S RANGE 3W SEC. 31 PLSS # 120160

Date: 11/23/2021 By: [Signature]  
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 10-25-21

Map: \_\_\_\_\_

Corner Designation

NW 1/16 S31

Narrative: \_\_\_\_\_

Corner Rpt: CS 67/51-20

DOUGLAS COUNTY  
SURVEYOR

Previous Renewals BLM Resurvey 1958  
Monument(s) Found: \_\_\_\_\_ (Condition and Source)

- Condition Report
  - Not Found
  - Renewed
  - Unrecorded
  - Surveyed In
- MONUMENT DETAIL

3 1/4" BRASS CAP ON 2 1/2" IRON  
PIPE  
BLM Resurvey 1958 Vol 30  
pg 12604  
Roseburg Forest Products  
2009 CS 45/44-22  
DCSO 2016 CS 47/44-14

N.W 1/16 S31  
1958

Accessories Found

BT'S by Glenn  
26" Hemlock uprooted SAWN To Low Stump  
No Position determined  
BTS By Roseburg Forest Products  
9" D. FIR Fallen on FACE 508°E 27.1 FT.  
10" X 7" TALL D. FIR Stump 560°W 27.7 FT Scribes  
Visible on partially healed single BLAZE  
BT'S By DCSO 2016  
20" I. Cedar S24 1/2°E 30.7 FT Vis. Scribes on  
unhealed BLAZES  
8" X 10 FT I. Cedar N81 1/2°W 3.0 FT Vis. Scribes on  
unhealed blazes Top Burned Out.

C.S. File 67/51-20

RENEWAL

Monument Set (Procedure and Description)

MONUMENT DETAIL

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

New Accessories

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Sketch of Monument, Accessories, and General Area

Location & Comments

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Comp. Decline. 15° E  
Agency DCSO  
Party Chief S. Flouse  
Note keeper \_\_\_\_\_  
Witnesses J. Loising

**REGISTERED  
PROFESSIONAL  
LAND SURVEYOR**



**OREGON  
JULY 14, 1978  
RONALD A. QUIMBY  
1854**

Expires: 12/31/2022

TOWNSHIP 24 RANGE 03 POINT IDENTIFIER # 120160

PRIMARY CORNER DESCRIPTION NW 1/16 Sec. 31

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by Wm. W. Glenn, Cadastral Surveyor, under Group #416, surveyed Sept/Oct 1958 - (DCSO records Vol. 30 Page(s) 12604)

Point for the center NW 1/16 sec. cor. of sec. 31, at the intersection with the E & W center line of the NW. Set an iron post, 28" long, 2 1/2" dia., 26" in the ground, with brass cap marked:

NW 1/16 S 31  
1958

from which

A hemlock, 6" dia., bears N.80 1/2°E., 37 lks., mkd: NW 1/16 S31 BT.

A fir, 25" dia., bears West, 21 lks., NW 1/16 S31 BT.

Mark Smalley, For Roseburg Forest Products - Crew: William Olson & Niel Danko - May 2009 - C.S. File 65/66-22

Found - 25" Hemlock N.80 1/2°E., 24.4' Healed face - Snag 1958  
25" Fir W 21 lks - Gone 1958

New - 8" D.Fir S.60°W 27.7' measured to a nail in the side-center of stump. Scribed "NW1/16BT" with LS 2354 brass washer

8" D.Fir S.3°E., 37.1' measured to a nail in the side-center of stump Scribed "NW1/16BT" with LS 2354 brass washer.

Compass decl. 18°E.

Douglas Co. Surveyor's Office - Crew: Stephen Flause & Mike Koch - 6/21/2016 - C.S. File 67/44-16

Found - A 2 1/2" dia. Iron post by Glenn, 1958, firmly set, projecting 5" above the ground, with a 3 1/4" brass cap (properly) marked

BTs by Glenn in 1958 -

A 26" dia. x 25' tall hemlock snag bears N.80 1/2°E., 24.4 ft. with a healed single blaze.

There is no remaining evidence of the original 25" dia. Fir BT.

And BTs by M. Smalley in 2009 per C.S. 65/66-22 -

A 9" dia. D.Fir bears S.03°E., 37.1 ft. with illegible scribe marks visible on a partially healed single blaze.

A 10" dia. x 7' tall sawn D.Fir stump bears S.60°W., 27.7 ft. with illegible scribe marks visible on a partially healed single blaze.

continued next page

MM GPS BEGIN 10:08

H.I. = 0.9710M

CS 67/51-20<sup>1</sup>

UNROOTED  
SAWN TO LOW STAMP  
NO POSITION

10" FALLEN ON FACE  
UNROOTED

GOOD

TOWNSHIP 24 RANGE 03 POINT IDENTIFIER # 120160

PRIMARY CORNER DESCRIPTION NW 1/16 Sec. 31

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

New - The 1958 USBLM monument is reset in a plumb position which matches the original bearing and distance to the found 1958 BT.

*20" A 18" dia. I. Cedar bears S. 24<sup>3</sup>/<sub>4</sub>° E., 30.7 ft. scribed "NW 1/16 S31 CS BT".*

*8' x 10' FT*  
*NEAR, TOP BROKEN OUT* A 8" dia. I. Cedar bears N. 81<sup>1</sup>/<sub>2</sub>° W, 3.0 ft. scribed "NW 1/16 S31 CS BT". *UNHEALED BLAZES*

Location & comments - All BTs have BT tags attached. All new BTs have double blazed faces with bearings measured to the center of the tree at the root crown and distances measured to the side and center of the root crown.

See attached notes for vicinity sketch.

Compass declination: 15° E.

CS 67/51-20