

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 26 S RANGE 2W SEC. 23 PLSS # 500300

Date: 11/23/2021 By: X

DOUGLAS COUNTY OREGON

DATE 11-3-21

This survey consists of:

Map: _____

Narrative: _____

Corner Rptr CS 67/51-26

DOUGLAS COUNTY SURVEYOR

Corner Designation

	T26S
SEC COR	S23
	S26
	R2W

Previous Renewals GLD Survey 1916
Monument(s) Found: (Condition and Source)

- Condition Report
- Not Found
- Renewed
- Unrecorded
- Surveyed In

MONUMENT DETAIL

BRASS CAP ON 2" Iron Pipe
GLD Survey 1908 Vol 10 Pg 4227
GLD Survey 1916-1918 Vol 10 Pg
4302 & 4327
BEN Irving 1945
DCSD 1967 CS 54/40-42
BLM Resurvey 1975 Vol 46 pg 15722-3
BLM Resurvey 2011 Vol 58 pg 22927

ADD MARKS

	T26S
Reset 2021	S23
	S26
	R2W
	1918

Accessories Found

FD BRASS CAP loose out of Ground Reset from
NE & S.W BEARING Trees by Dist. Dist Intersection
Projecting 9" Above Ground in Rough mound of stone
ORIG BEARING trees
A root hole N43°E 29.2 FT
Mostly burned 38" Cedar Stump S27°W 29.7 FT
Set 4" mng Nail Near Top Center AT BEARING Dist.
BEARING Trees By DCSD 1967
DEAD 15" Hemlock N55°E 13.9 FT Healed Double BLAZE
BURNED BASE
Uprooted Hemlock mostly burned No Position

RENEWAL

Monument Set (Procedure and Description)

MONUMENT DETAIL

New Accessories

16" D. FIR N30E 24.4 FT NOT Scribed

17" X 1 1/2' FT D. FIR STUMP 4" MAG NAIL TOP AND CENTER N29W 37 FT

Sketch of Monument, Accessories, and General Area

Location & Comments

AREA BURNED BY ARCHIE CR. FIRE 9-2020

Comp. Decline. 14 1/2° E

Agency DLSD

Party Chief S. F. AUSE

Note keeper

Witnesses J. LORSUNG

REGISTERED PROFESSIONAL LAND SURVEYOR

Ronald A. Quimby

OREGON
JULY 14, 1978
RONALD A. QUIMBY
1854

CS 67/51-26

Expires: 12/31/2022

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 500300

PRIMARY CORNER DESCRIPTION West Sec. Cor. Secs. 23 & 26, only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by John A. McQuinn, Deputy Surveyor, under contract No. 466, dated April 5, 1883 - (DCSO records Vol. 10 Page(s) 4198-9)

Set a post, 4 ft. long, 4" sq. 24" in the ground, for cor. to secs. 22, 23, 26, & 27, marked T26S S23 on NE, R2W S26 on SE, S27 on SW, S22 on NW faces, with 2 notches on S & E. edges; from which

- A fir, 12" dia. bears N.45°E. 11 lks. mkd: T26S R2W S23 BT
- A hemlock, 18" dia., bears S.60°E., 55 lks., mkd: T26S R2W S26 BT.
- A cedar, 18" dia., bears S.30°W., 43 lks., mkd: T26S R2W S27 BT.
- A fir, 10" dia. bears N.20°W. 10 lks. mkd: T26S R2W S22 BT

GLO survey by Wm. N Gibb, Deputy Surveyor, under contract No. 783, dated Dec. 3, 1908 - (DCSO records Vol. 10 Page(s) 4227)

Intersect E and W line, 9.27 ohs. E of cor. secs. 22, 23, 26 & 27, which is a stake marked & witnessed as described by the Surveyor General.

Set granite stone, 6x7x14", 10" in the ground for closing cor. secs. 26 & 27, marked with 2 grooves on E & 4 grooves on W face; from which

- A hemlock, 7" dia., bears S.52°E., 32 lks. Marked T26S R2W S26 BT.
- A hemlock, 12" dia., bears S.55°W., 15 lks. Marked T26S R2W S27 BT

I destroy markings on other cor. and bearing trees referring to secs. 26 and 27.

At this cor. set off 12°09'N. on decl. arc and at 0 hrs. 3m. p.m. 1. m. t. observe the sun on the meridian; the resulting latitude is 43°17'.

GLO resurvey by Fred Mensch, U.S. Cadastral Engineer; under Instructions dated May 25, 1916 & April 16, 1918, - (DCSO records Vol. 10 Page(s) 4303 & 4327)

Pg 4303 - Intersect the orig. cor. established by Deputy McQuinn in 1883, as the cor. of sees. 22, 23, 26 and 27, which is a decayed post, witnessed as described by the surveyor general, except for slight discrepancies in position of bearing trees. The NW bearing tree has been cut down I now perpetuate this cor., as follows: at the exact cor. point Set an iron post, 3 ft. long, 2" dia., 24" in ground, for cor. of secs. 22, 23, 26 and 27, with brass cap mkd:

continued next page

CS 67/51-26

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 500300

PRIMARY CORNER DESCRIPTION West Sec. Cor. Secs. 23 & 26, only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

T26S | R2W (Note: This corner changed to
S 22 | S 23 refer to secs. 23 & 26 only
S 27 | S 26 8/10/1945 BBI)
1916

from which

- A fir, 18" dia., bears N.43°E., 11 lks., mkd: T26S R2W S23 BT. Orig. BT
- A hemlock, 20" dia., bears S.58°E., 55 lks., mkd: T26S R2W S26 BT. Orig. BT
- A cedar, 16" dia., bears S.27°W., 45 lks., mkd: T26S R2W S27 BT. Orig. BT
- A hemlock, 10" dia., bears N.23°W., 90 lks., mkd: T26S R2W S22 BT.

from this cor. the established by Deputy Gibb in 1909* as the closing cor. of secs. 26 & 27, on S bdy of sec. 23, which is a granite stone, 4x7x6" above ground firmly set, marked & witnessed as described by the surveyor general, bears S.89°34'E. 9.26 chs. Also the cor. established by Deputy Gibb in 1909 as the closing cor. of sees. 22 & 27, on W bdy, of sec. 23, which is a granite stone, 5x10x8" above ground, firmly set, marked and witnessed as described by the surveyor general, bears N.0°52'E., 14.96 ohs.

I destroy the corresponding cor. of the rejected revision survey & marks on BTs.

Pg 4327 - ... cor. of sec. 22, 23, 26, & 27, which I change to refer to secs. 23 & 26 only

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - E. West - July 1967 - C.S. File 54/40-42

Found - 1918 GLO brass cap, properly marked
Orig. 18" now 22" Fir snag, N.43°E., 7.3 ft. shows good scar.

No trace of orig. BT in sec. 26.

New BTs- 8" Hemlock S.38°E., 3.2 ft. mkd: T26S R2W S26 CS BT.
7" W.Fir, N.55°E., 13.7 ft. mkd: T26S R2W S23 CS BT.

Note - This corner lies on large flat bench in very old logged off unit. Obliterated OBT to SW alive.

Fd & used on BLM dependent resurvey by G. Steven Popken, Cadastral Surveyor, Group No. 871, surveyed June/Sept. 1975 - (DCSO Vol. 46 Page(s) 15722-3)

continued next page

11/3/21

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 500300

PRIMARY CORNER DESCRIPTION West Sec. Cor. Secs. 23 & 26, only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2331, Surveyed April/Oct. 2011 - (DCSO records Vol. 58 Page(s) 22927)

The cor. of secs. 23 and 26 only, monumented with an iron post, 2" dia., firmly set, projecting 8 ins. above ground, with brass cap mkd.

FOUND LOOSE ON GROUND NO POSITION
RESET AT DIST. DIST. INTERSECT
FROM NE HEMLOCK
AND SW CEDAR

T26S
S 23
S 26
R2W

2 1/2" BRASS CAP / 2" ID. I.P. NOW PROT 9" FROM GROUND
IN ROUGH MOUND OF STONE

ADDMARKS 1918

from which the remains of the original bearing trees

BURNED ROOTS A roothole bears N.43°E., 7.3 ft., with a fallen, decayed fir snag, size indeterminate, lying alongside, with no marks visible.

MOSTLY BURNED 38" X 3 STUMP A cedar, 35" dia., bears S.27°W., 29.7 ft., with a healed blaze. SET 4" MAG NAIL NEAR TOP CNTR. AT B&D

DEAD 15" BURNED BASE and BTs mkd. by the Douglas County Surveyor's Office in 1967 A hemlock, 14" dia., bears N.55°E., 19.9 ft., with a healed double blaze. (Record, white fir) 4" MAG NAIL RSC

UPROOTED MOSTLY BURNED A hemlock, 15" dia., bears S.38°E., 3.3 ft., with a healed double blaze **NO POSITION**

NAD 1983 (CORS 96)
Latitude: 43°16'59.11"N. Longitude: 122°54'48.91"W.

10" D. FIR NOT SCRIBED N 03° E, 24 ±

17" x 1 1/2" D. FIR 4" MAG N 29° W, 37 ±
TOP CNTR.

MM GPS BEGIN 13:30
HI = 0.8097 M

CS 67/51-26