

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 255 RANGE 2W SEC. 32 PLSS # 240140

Date: 7/20/2022 By: X

This survey consists of:

DOUGLAS COUNTY OREGON

DATE 5-4-22

Map: _____

Narrative: _____

Corner Rpt: C567/52-38

Corner Designation

C 1/4 S32

DOUGLAS COUNTY
SURVEYOR

Monument(s) Found: (Condition and Source)

___ Condition report

3/4" BLM BRASS CAP ON

___ Not Found

2" I.D IRON PIPE PROJ 14"

Renewed

IRON PIPE N1NW 0.3 FT PROJ 8"

___ Unrecorded

Previous Renewals

___ Surveyed In

HOSFORD 1960 M 19-77

SET CORNER

MONUMENT DETAIL

BLM RESURVEY 1972-1975

101 36 PG 15/32

C 1/4
S32
1975

Accessories Found

ORIG. BT

Root hole N58°W 5.94 FT

BT'S by BLM

Burned Hollow 20" X 5 FT CEDAR STUMP

S43 1/2° E 40.6 FT (REC S42° E)

Burned Hollow 14" X 3 1/2 FT CEDAR STUMP

N67 1/2° W 12.2 FT (REC. N65° W)

C.S. File 67/52-38

New Accessories

Burnt - Dead 15" Hemlock S 39° W 9.8 FT No
 Blaze or Scribe 3" PK RIGHT Side Center

5/8" X 30" Iron Rod N 9° W 30.6 FT Painted
 Red Proj 8"

Sketch of Monument, Accessories, and General Area

Location & Comments

LAT. 43° 21' 04.85" N
 Long 122° 57' 47.10" W

See Attached Sheet for
 Sketch

AREA BURNED 9-2020
 CORNER IS APPROX
 50' SOUTH OF BEGINNING
 OF LANDING AT END
 OF LOGGING ROAD

Comp. Decline. 14 1/2° E
 Agency DCSD
 Party Chief S Flouse
 Note keeper
 Witnesses J. LORSUNG

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR

Ronald A. Gumbly

OREGON
 JULY 14, 1978
 RONALD A. GUMBLY
 1854

Expires: 12/31/2022

T25S, R02W, 240140

5/4/22

C/4 S32

GRAVEL RD.

END OF ROAD LANDING

NEW REF.
5/8" I.R.

305' (M. 60N)
305'

NORTH 250 FT.

(NO SCALE)

1975 BLM AT
BURNED HOLLOW
14" X 3 1/2 FT. TALL
CEDAR STUMP

122'

B.C.

S42 1/2 E, 406'

NEW B.T.
BURNED DEAD
15" HEMLOCK
S39°W, 98'

1975 BLM AT
BURNED HOLLOW
20" X 5 FT. TALL
CEDAR STUMP

DECLINATION 14 1/2° E

CS 67/52-38

3/4

MM CMS 5/4/22
TIME - 10:30
4.6 - 2.000M

RENEWED 5/4/22

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 240140

PRIMARY CORNER DESCRIPTION Center 1/4 Cor. Sec. 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

V.W. Hosford - For: Evans Products Co. - Feb./Oct. 1960 - C.S. File 51/144 - M19-77

Drove a 1 1/2" iron pipe 36" long, 12" above the ground, from which:
20" Fir bears S.83 1/2°E., 25.0 ft. mkd: C 1/4 S32 253 BT.
14" Hemlock bears N.57°W., 5.4 ft. mkd: C 1/4 S32 253 BT.

BLM dependent resurvey by Daniel L. Berry, Harvey E. Wofford, & G. Steven Popken Cadastral Surveyors & Glenn S. Baughman, LS, under contract #52500-CT5-1116 & Group E 786, 848, & 854, surveyed July 1972/Oct. 1975 - (DCSO recs Vol. 36 Page 15132)

The center 1/4 sec. cor. of sec. 32, established & recorded by Hosford, in 1960, monumented with an iron pipe, 1 1/2" dia., firmly set, protruding 5" above ground, from which the remains of the bearing trees mkd ^{2P} by Hosford:

~~NO EVID.~~ A root hole, bears S.74°E., 33 lks., with a down hemlock alongside, 20" dia., with healed blaze. ⁵⁹⁴
~~GONE ONLY ROOTHOLE~~ A hemlock snag, 17" dia., bears N.58°W., 9 lks., with scribe marks C 1/4 S32 visible on open blaze.

At the corner point ^{3 1/4" / 12" IP}
Set an iron post, 28" long, ^{12 1/2"} dia., 25" in the ground, with brass cap mkd. C 1/4 S 32 ✓ ^{PROT 14"}
BLM BRASS CAP 1975

from which new bearing trees ^{43 1/2° 4859}
A cedar, 27" dia., bears S.42°E., 61 1/2 lks., mkd. C 1/4 S32 BT ← (BLZ GONE)
A cedar, 14" dia., bears N.65°W., 18 1/2 lks., mkd. C 1/4 S32 BT ← "

Reset iron pipe alongside iron post. ^{12 1/2"}
(PRDT. 8" NNW ≈ 0 3/4 FT) ↑ (N 67 1/2° W)

BURNED HOLLOW 20" X 5 FT. STUMP
BURNED HOLLOW 14" X 3 1/2 FT STUMP

NEW REFS

DEAD BURNED 15" HEMLOCK NO BLZ OR SCRIB S39°W, 98 FT (3" PK RSC)

5/8" X 30" I.R. SET PROT 8", PAINTED RED N09°W, 306

CORNER IS ON MODERATE NE'LY SLOPE ≈ 50FT, SOUTH FROM BEGINNING OF LANDING AT END OF LOGGING RD.

DECLINATION 14 1/2° E

CS 67/52-38
414