

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 26S RANGE 2W SEC. 23 PLSS # 600300

Date: 10/18/2022 By: Y
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 7-5-22

Map: _____

Narrative: _____

Corner Rpt: CS 67/549

Corner Designation

DOUGLAS COUNTY
SURVEYOR

See Cor 23/24
26/25

Monument(s) Found: (Condition and Source)

___ Condition report

1916 2 1/2" BRASS CAP ON

___ Not Found

1 3/4" T.O IRON PIPE PROJ.

Renewed

10" STRIGHTEN BRASS CAP TO PLUMB

___ Unrecorded

Previous Renewals ADD ROUGH STONE MOUND

___ Surveyed In

GLD RESURVEY 1916-1918 Vol

10 PGS 4291 & 4297-8

DCSD 1967 CS 54/40-70

BLM RESURVEY 1975 Vol 46 pg

15719-20

BLM RESURVEY 2011 Vol 58 pg 22923

MONUMENT DETAIL

T 26S R2W

523 | 524

526 | 525

1916

Accessories Found

Burnt - SAWN 47" X 2 1/2' D. FIR STUMP

N53°E 27.2FT (REC 26.4) ADD 3 1/2" P.K.NAIL

TOP CENTER ORIG BLAZE VISIBLE IN SIDE STUMP

BEARING TREE BY POPKEN

A 21" D. FIR N183°W 62.7FT (REC 43.4)

WITH HEATED SINGLE BLAZE ADD 3 1/2" PK

RIGHT SIDE CENTER

BEARING TREE BY SAUELAND

Burnt base 12" D. FIR S34 1/4°W 23.5FT

(REC 23.8) ADD 3 1/2" P.K.NAIL RIGHT SIDE

CENTER

C.S. File 67/54-9

RENEWAL

Monument Set (Procedure and Description)

MONUMENT DETAIL

New Accessories

Sketch of Monument, Accessories, and General Area

Location & Comments

LAT 43°17'02.37" N
LONG 122°53'37.09" W

CORNER 13 35' E. OF
GRAVEL LOGGING ROAD
COURSE N 20° E
520 W

FOR SKETCH SEE ATTACHED
SHEET.

AREA BURST
9-2020

Comp. Decline. 1 1/2' E

Agency DCSO
Party Chief S. KLAUSE
Note keeper _____
Witnesses J. LORSUNG

REGISTERED
PROFESSIONAL
LAND SURVEYOR



OREGON
JULY 14, 1978
RONALD A. QUIMBY
1654

EXPIRES: 12/31/2022

CS 67/54-9 215

T26S, R02W, 600300

JULY 5, 2022



(NO SCALE)

1975 BLM BT.
LIVE 21" D. FIR



O.B.T (PER GLO 1916)
47" x 2 1/2' FIR STUMP



N83°W
62'

N53°E
27'

B.C.

GRAVEL RD.



1975 BLM BT.
LIVE 12" D. FIR

DECLINATION 14 1/2° E

MM GPS 7/5/22
TIME - 13:30
H.J. - 2.000M

RENEWED 7/5/22

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 600300

PRIMARY CORNER DESCRIPTION Cor. Secs. 23, 24, 25, & 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - E. West - Aug. 23, 1967 - C.S. File 54/40-70

Found - 1916 GLO brass cap, firmly set & properly mkd.
 Orig. 36" now 48" Fir, alive, N.50°E., 26.4 ft. show good scar. Rescribed "T26S R2W S24 CS BT" in bark
 Orig. 8" now 11" Chinquapin snag, N.20°W., 13.9 ft. shows "6S 23" scribe on open blaze.
 Orig. SW BT gone & orig. SE BT burned stub.

New BTs- 18" cedar S.5°E., 91.4 ft. mkd: T26S R2W S25 CS BT.
 10" Pine snag, N.56°W. 7.9 ft mkd. T26S R2W S23 CSBT
 No trees nor stumps to SW.

Note - Corner lies on east edge of old logging road near landing. Secs. 23, 24, & 26 logged off many years ago.

BLM dependent resurvey by G Steven Popken, Cadastral Surveyor Group No. 871, surveyed June/Sept. 1975 - (DCSO Vol. 46 Page(s) 15719-20)

Beginning at the cor. of secs. 23, 24, 25, & 26, monumented with an iron post, 2" dia., firmly set, projecting 10" above ground, with brass cap (properly) mkd., from which the remains of the orig. BTs.

A fir, 46" dia., bears N.53°E., 40 lks., with scribe marks T26S R2W S24 CS visible on bark. This tree was rescribed by Tracy, in 1967. (Record, N.50°E.)
 A chinquapin snag, 10" dia., bears N.14°W., 21 lks., with scribe marks 6 W 23 visible on open blaze. (Record, N.20°W.)

and the remains of BTs mkd. by Tracy
 A cedar, 20" dia., bears S.6½°E., 138 lks., with scribe mks T26S R2W S26 CS BT visible on open blaze.
 A pine snag, 9" dia., bears N.52½°W., 12 lks., with scribe marks T26S R2W S23 CS BT visible on open blaze.

and a new bearing tree
 A fir, 7" dia. bears N.80°W., 96 lks. mkd. T26S R2W S23 BT

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2331, Surveyed April/Oct. 2011 - (DCSO records Vol. 58 Page(s) 22923)

The cor. of secs. 23, 24, 25, and 26, monumented with an iron post, 2" dia., firmly set, projecting 8" above ground, with brass cap (properly) mkd. 1916 2 1/2" B.C. ON 3/4" I.D. I.P 32" LONG SLIGHTLY BENT AND LEANING EAST'LY 1 1/2 FT OFF PLUMB

from which the remains of the original bearing trees

continued next page

CS 67/54-9
4/5

OVER →

7/5/22

TOWNSHIP 26 RANGE 02 POINT IDENTIFIER # 600300

PRIMARY CORNER DESCRIPTION Cor. Secs. 23, 24, 25, & 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

ADD ROUGH STONE MOUND AROUND MON.

AFTER CHECKING B.T. WE REF. BASE POSITION OF B.C. MON. REMOVE AND STRAIGHTEN THEN RETURN PLUMB TO REF. POSITION NOW PROT. 10" ✓ 272

BURNED, SAWN 47" x 2 1/2" D. FIR STUMP

A fir, 50" dia., bears N.53°E., 26.4 ft., with a healed blaze and scribe marks T26S R2W S24 C visible in bark.

ADD 3 1/2" PK TOP CNTR, SEE BLZ, FACE INSIDE STUMP

A burnt, decayed, chinquapin stump, size indeterminate, bears N.14°W., 13.9 ft., with no marks visible.

and a BT mkd. by the Douglas County Surveyor's Office in 1967

FALLEN BROKE INTO PIECES AND BURNED

A cedar, 28" dia., bears S.6 1/2°E., 91.1 ft., with a healed double blaze.

(NOT GOOD ROOTHOLE)

and a bearing tree mkd. by Popken

ALIVE 21"

A fir, 19" dia., bears N.83°W., 63.4 ft., with a healed blaze. (Record, N.80°W.)

and a new bearing tree

ALIVE BURNED BASE 12"

A fir, 9" dia., bears S.34 1/4°W., 23.8 ft., mkd. T26S R2W S26 BT.

NOW GRAVELLED

Corner is located 35 ft. E. of ~~an overgrown~~ logging road, 12 ft. wide, bears N.20°E. and S.20°W.

A search was made for all original line trees bet. secs. 24 and 25 as well as bet. secs. 25 and 26 and none were recovered.

DECLINATION 14 1/2° E