

TOWNSHIP 21 RANGE 07 POINT IDENTIFIER # 500240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 27 END OK 12/12/19

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by L.H. Wheeler under Contract No. 467 dated April 7, 1883 (DCSO records Vol. 2 Page(s) 643)

Set post, 4" dia., 4 ft. long, with marked stone, 12" in ground, for qr. sec. cor. marked 1/4 S on W face; from which  
Fir, 24" dia., bears N.71°E., 62 lks., mkd: 1/4 S BT. 4092  
Cedar, 60" dia., bears West, 54 lks., mkd: 1/4 S BT. 3564

Douglas Co. Surveyors Office - James W. Byron, Deputy - M. Godfrey & S. Bilow - May 23, 1958 - C.S. File 49/20

Found - Both orig. BTs  
 Orig. 24" now 48" Fir stump N.71°E., 40.9 ft. shows good scar near base, I do not open.  
 Orig. 60" now 68" Cedar West 35.6 ft., I open & find good scribing "1 4" BTs check for bearing & dist.  
 Set brass cap at corner mkd: 1/4 S27/S26 T21S R7W County  
 (26") BLM N17 1/2° E. 30.2 Surveyors Office, 1958  
 New BTs- 20" Cedar bears N.18°E. 97.5 ft. scribed 1/4 S26 CS BT  
 8" Hemlock bears S.39°W. 5.9 ft. scribed 1/4 S27 CS BT  
 (22") BLM S39 3/4° W. 6L

Fd. ok by Les Roberts 9/1992 - M 115-63

FD. ok on BLM Dependent resurvey by Timothy J. Moore, Cadastral Surveyor and Robert H. Browning, Surveying Technician under Group #1916, surveyed Aug. 1999/May 2000. (DCSO rec. Vol. 53 page(s) 20636)

BLM AGREES WITH ORIG BT'S BEARING AND DIST'S

**FILED**

Date: 11/3/2022 By: X  
 This survey consists of:  
 Map: \_\_\_\_\_  
 Narrative: \_\_\_\_\_  
 Corner Rpt: CS67/54 3L

**DOUGLAS COUNTY SURVEYOR**

C.S. FILE 67/54-36

ROTTED STMP  
STMP.

1999/2000  
BLM  
95.9A.