

FND OK

MMGPS 7/19/21

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 200600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 5, 6, 7 and 8

Alias _____	Description _____	SEE PG 2 FOR ACC, CHANGES.
Alias _____	Description _____	
Alias _____	Description _____	
Alias _____	Description _____	

GLO survey by William R. Whipple, Deputy Surveyor, under Contract #622, dated June 23, 1893 (DCSO records Vol. 6 Page(s) 2608)

Set a post 4 ft. long, 4" sq., 2 ft. in ground for cor. to secs. 5, 6, 7 and 8, marked T23S S5 on NE.; R8W S8 on SE.; S7 on SW.; and S6 on NW.; faces with 5 notches on E. and S. faces, from which

- A Fir 50" dia., bears N.1°E., 22 lks. dist. mkd. T23S R8W S5 BT.
- A Chitten 4" dia., bears S.43½°E., 81 lks. dist. mkd. T23S R8W S8 BT.
- A Fir 24" dia., bears S.31°W., 30 lks. dist. mkd. T23S R8W S7 BT.
- A Fir 24" dia., bears N.79°W., 48 lks. dist. mkd. T23S R8W S6 BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Dec. 1966 - C.S. File 54/12-46

FILED Found - Unrecorded 1½" I.P. with cast iron cap blazed on top and marked.

Date: 11-3-2022 By: X

This survey consists of: Orig. 50" Fir, N.1°E., 14.5 ft., face. Find old axe mark in remains of bark at base of badly decayed stump.

Map: _____

Narrative: _____
Corner Rpt: CS 67/54-43 Orig. 24" Fir S.31°W., 19.8 ft., to hole, remains of turned out tree. No scribe found.

DOUGLAS COUNTY SURVEYOR

Orig. 24" now 30" Fir, badly decayed stump N.79°W., 31.7 ft., face, find "BT" barks scribe in very poor condition at base of stump.

No trace of BT to SE.

- New BTs- 17" R.Cedar N.45°E., 17.9 ft. mkd. T23S R8W S5 CSBT
- 13" D.Fir N.56°W., 17.3 ft. mkd. T23S R8W S6 CS BT.
- 17" Hemlock S.11°W., 13.8 ft. mkd. T23S R8W S7 CS BT
- 14" D.Fir S.75°E., 15.0 ft. mkd. T23S R8W S8 CS BT.

Corner lies approx. 100 ft. South of road, course E-W.

BLM survey by Harvey E. Wofford, Cadastral Surveyor, under Group #1005, surveyed July/Dec. 1980 - (DCSO records Vol. 43 Page(s) 16831-32)

The Sec. cor., perpetuated and recorded by Tracy in 1966, monumented with an iron post 1½" dia., loosely set, with iron cap mkd. S5 S6 S7 S8, from which the remains of the original bearing trees:

(Cont. Next Page)

C.S. FILE 67/54-43

198845.96007831

TOWNSHIP 23 RANGE 08 POINT IDENTIFIER # 200600

PRIMARY CORNER DESCRIPTION Sec. Cor. for 5, 6, 7 and 8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

A decayed Fir stump 38" dia., bears N.1°E., 24 lks. dist., with old axe marks visible on decayed bark blaze. (Rec. and to face, 22 lks.)

A roothole bears S.31°W., 30 lks. dist., alongside of which is a downed, decayed Fir, size indeterminate, no marks remaining.

A decayed Fir stump size indeterminate bears N.79°W., 48 lks. dist. no marks remaining.

and the remains of bearing trees mkd. by Tracy

A Cedar 22" dia., bears N.45°E., 27 lks. dist., with scribe mark 8 visible on partially healed blaze.

NOW SAWN - 5' TALL STUMP - A Fir 19" dia., bears S.75°E., 22½ lks. dist. with healed blaze.

A Hemlock 20" dia., bears S.11°W., 21 lks. dist. with fragmentary scribe marks visible on partially healed blaze.

A roothole bears N.56°W., 26 lks. dist. alongside of which is downed Fir 14" dia., no marks remaining.

At the corner point

Set an iron post, 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T	23	S	R	8	W
	S	6	S	5	
	S	7	S	8	
				1980	

from which a new bearing tree

A Fir 26" dia., bears N.69 3/4°W., 44 lks. dist. mkd. T23S R8W S6 BT.

Deposit iron capped iron post alongside iron post.

Fd. Ok by C. Mulkins, 12/95 - M 123-32