

FNM OK 3/28/23

TOWNSHIP 26 RANGE 06 POINT IDENTIFIER # 100140

PRIMARY CORNER DESCRIPTION 1/4 Cor. for 31; and 36 of T.26-7

Alias \_\_\_\_\_ Description DCRS CANYONVILLE COTTAGE GROVE COORD.S

Alias \_\_\_\_\_ Description \_\_\_\_\_

Alias \_\_\_\_\_ Description 157592.750 N

Alias \_\_\_\_\_ Description 128728.980 E

Original - Elder & Gile, Contract #31 dated April, 1853

Set 1/4 sec. post, from which  
 A Yellow Oak 15" dia. bears N.58 1/2°E., 84 lks.  
 A W. Oak 18" dia. bears N.45 1/2°W., 310 lks.

**FILED**  
 Date: 5-4-2023 By: X  
 This survey consists of:  
 Map: \_\_\_\_\_  
 Narrative: \_\_\_\_\_  
 Corner Rpt: C 567/56-8

William B. Paulin, Doug. Co. Road Dept. (date ?)  
C.S. File 58/176-42

**DOUGLAS COUNTY SURVEYOR**

Found large rotten Oak hollow in center. Found remnants of upper & lower blazes. Could not find visible scribe. Found evidence of axe mark along edge of one face. Went into other quadrant record distance & bearing. Found old stump cut off short but showing remains of lower half of blaze. Assume first mentioned tree to be original BT.

Don E. Garrett, For: Willard Nickolaus - Dec. 29, 1967  
M 35-17

1/4 Corner set from field notes by William Paulin -  
 Set 5/8" iron rod at 1/4 Corner.  
 Set - Brass cap stamped W.C. 1/4 S 36 T26S R7W S31 T26S  
 R6W LS 544 30 ft. West to Cor.  
 16" Oak bears S.16°W., 16.3 ft. scribed WC 1/4 S31 BT.

Douglas Co. Surveyors Office - Randall Smith; Stephen Flause  
January 5, 1990 - C.S. 64/5-1

Found - 1967 2 1/4" dia. brass cap on a 1 1/4" O.D. Iron pipe that protrudes 4" above ground.  
 5/8" Iron rod set at a position for 1/4 corner is under AC in road. A strong metal reading was taken at a point 30 ft. West of witness cor.  
 16" now 9" dia. W. ✓ Oak with fully healed double blaze bears S.16°W., 16.3 ft.  
 5/8" Iron rod property pin bears West, 1.19 ft. (See M 35-17)  
 5/8" Iron rod property pin bears N.1 1/2°W., 59.87 ft. (Rec. N.1°08'09"W., 60.01 ft. M 35-17)

TREE NOW 14" 19"

(Cont Next Page)

19"

C.S. FILE 67/56-8

TOWNSHIP 26 RANGE 06 POINT IDENTIFIER # 100140

PRIMARY CORNER DESCRIPTION 1/4 Cor for Sec. 31; and 36 of T.26-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

New Accessories:

5/8" Iron rod with yellow plastic cap marked "L.S. 1075" bears S.50 $\frac{3}{4}$ °W., 78.90 ft.

5/8" Iron rod with alum. cap (CRRW 10+00.00 PT on south side of Cleveland Loop Dr.) bears N.19 $\frac{1}{2}$ °E., 197.40 ft.

5/8" Iron rod with alum. cap (CRRW 10+46.76 PC on south side of Cleveland Lp Dr.) bears N.32 $\frac{3}{4}$ °E., 202.36 ft.

Corner lies 1 $\frac{1}{2}$  ft. North of the intersection of a North-South and East running fence line.

Fd. OK, James Artman, July, 1991 - MLP 1991-0046

Fd. OK, Douglas Jacobson, June 1998 - 1998-0073

DCSO-GIS Corner visitation - 6/18/2004 - Typed: 1/25/2011 - C.S. File 67/33-1

-----  
Monument - BC/IP 1.25"  
Comment - ok