

TOWNSHIP 265 RANGE 3W SEC. 2 PLSS # 500660

Date: 6/29/2023 By: X
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 6-20-23

Map: _____

Narrative _____
Corner Rpt: CS 67/56 40

DOUGLAS COUNTY
SURVEYOR

Corner Designation

N 1/16 3/2

Monument(s) Found: (Condition and Source)

3" BLM BRASS CAP UP
2"

___ Condition report

___ Not Found

Renewed

___ Unrecorded

___ Surveyed In

Previous Renewals

Weyerhaeuser Timber 1943

CS 51/87-7

MONUMENT DETAIL

Weyerhaeuser Timber 1965

CS 51/306-S

N 1/4

BLM Resurvey 1995 Vol 52 pg 19889-90

S3 | S2

CHRISTENSEN 1999 M 133-77 (Replat)

1995

CHRISTENSEN 1998 M 128-59

Accessories Found

13" Burnt-Dead D. Fir N13 1/2° E 6.9 FT

Healed Single BLAZE

18" X 1 1/2 FT Burnt-Sawn D. Fir Stump S89 1/2° W

17.8 FT EVIDENCE OF BLAZE AT 9" ADD 3 1/2"

Mag Nail Top Center

Corner By Baretta for Weyerhaeuser Timber

1 1/2" Aluminum Pipe S1° 32' 35" W 3.17 FT

up 4" Bent Easterly From Which

A 24" X 2 FT D. Fir Burned AND SAWN

Stump S 37 1/4° E 16.2 FT NO MARKS VISIABLE

New Accessories

Sketch of Monument, Accessories, and General Area

Location & Comments

Fences Reported by BLM Now
Destroyed
OLD Reprod in N.W. QUADRANT
Rest is Clearcut on moderate
West Slope

CORNER IS APPROX
150 FT WESTERLY
OF GRAVEL ROAD

AREA BURNED
9-2020

CCRS COORDINATE SYSTEM
COTTAGE GROVE - CANYONVILLE
ZONE

Comp. Decline. $14\frac{1}{2}^{\circ} E$
Agency DCSO
Party Chief S. FIAUSE
Note keeper
Witnesses J. LORSUNG

N 185103.814
E 244749.715

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald A. Quimby

OREGON
JULY 14 1978
RONALD A. QUIMBY
1654

EXPIRES: 12/31/2024

CS 67/56-40
214

MM GPS 6/20/23
TIME - 9:22
H.I. - 2.000M

19889

T265-R3W-500660

Dependent Resurvey of a Portion of the Subdivisional Lines,
T. 26 S., R. 3 W., Willamette Meridian, Oregon

CHAINS	
	<p style="text-align: center;">DOUGLAS COUNTY SURVEYORS T26S 1/4 * R S 3 * S 2 3 1993 W OFFICE</p> <p>from which the remains of an original bearing tree</p> <p>A sawed fir stump, 59 ins. diam., bears N. 45° W., 50 lks. dist., with healed blaze.</p> <p>and a bearing tree mkd. by Byron</p> <p>A cedar, 23 ins. diam., bears S. 64½° E., 55 lks. dist., no marks visible.</p> <p>and bearing trees mkd. by Smith</p> <p>A cedar, 8 ins. diam., bears S. 88° E., 37½ lks. dist., with scribe marks 1/4 S2 CS BT visible on open double blazes.</p> <p>A fir, 14 ins. diam., bears S. 28¾° W., 50 lks. dist., with scribe marks 1/4 S3 CS BT visible on open double blazes.</p> <p>A fir, 8 ins. diam., bears S. 82¼° W., 32 lks. dist., with scribe marks 1/4 S3 CS BT visible on open double blazes.</p> <p>From this point, the Bureau of Land Management, Geodetic Control Station No. EC41244, at latitude 43° 20' 15.039" N., longitude 123° 01' 57.651" W. (NAD 1983(91)), determined by the NAVSTAR Global Positioning System, bears N. 70° 31' 40" W., 9.364 chs. dist. (mean bearing and sea level distance); monumented with an aluminum cap, 3¼ ins. diam., firmly set flush with the ground, with top mkd. EC41244 GPS 1995.</p> <p>N. 0° 33' 58" E., bet. secs. 2 and 3.</p> <p>Ascend over broken SW. slope, through second growth timber and dense undergrowth.</p>
0.25	Graveled road, 20 lks. wide, bears N. 35° W. and S. 35° E.
19.851	Point for the N 1/16 sec. cor. of secs. 2 and 3. RENEWED 6/20/23
	<p>Set a stainless steel post, 28 ins. long, 2¼ ins. diam., 27 ins. in the ground, with brass cap mkd. PROPERLY MARKED</p> <p style="text-align: center;">3" B.C. N 1/16 PROT 2" S 3 S 2 1995</p> <p>from which</p> <p>BURNED DEAD 13" - AD fir, 8 ins. diam., bears N. 13¾° E., 10½ lks. dist., mkd. N1/16 S2 BT. FHSB</p> <p>BURNED SAWN 18" x 1½" STUMP fir, 9 ins. diam., bears S. 89½° W., 27 lks. dist., mkd. N1/16 S3 BT. EVID. OF BLZ AT 9" DIA.</p> <p style="text-align: right;">693 1782 ADD 3½" MAG NAIL TOP CNTR.</p>

CS 67/56-40
3/4

Dependent Resurvey of a Portion of the Subdivisional Lines,
T. 26 S., R. 3 W., Willamette Meridian, Oregon

CHAINS	
	<p>Deposit a white "DEEP-1" magnetic marker at base of stainless steel post.</p> <p>The corner is located N., ⁷²⁶ 0.11 chs. dist. of a fence corner, extending S. and W. FENCES DESTROYED</p> <p>From this point, a point established as the N 1/16 sec. cor. of secs. 2 and 3 by Robert Barta for Weyerhaeuser Company, in 1965, recorded in the Douglas County Surveyors Office files CS 51/87 and CS 51/306, bears S. 1° 32' 35" W. 0.048 chs. dist. ⁴ monumented with an iron pipe, 1 1/2 ins. diam., bent, projecting 2 ins. above ground, from which bearing trees mkd. by Barta:</p>
	<p>A fir, 20 ins. diam., bears S. 3 1/4° E., 24 1/2 lks. dist., no marks visible. 3 1/4 16 1/2 BENT EASTLY</p> <p>A sawed fir stump, 24 ins. diam., bears N. 75 1/2° W., 62 lks. dist., no marks visible. 40 92</p> <p>This point is rejected due to improper methods and is not utilized in this survey. DECLINATION 71 ON 14 1/2 E</p> <p>Ascend over SW. slope. ON MODERATE WEST SLOPE</p>
23.15	Graveled road, 20 lks. wide, bears N. 40° W. and S. 40° E. N. 150 FT WESTERLY FROM GRAVEL RD.
39.205	The cor. of secs. 2, 3, 34 and 35, on the N. bdy. of the Tp.
<p>Subdivision of Section 3, T. 26 S., R. 3 W., Willamette Meridian, Oregon</p>	
<p>From the 1/4 sec. cor. of secs. 3 and 10, perpetuated by Vernon Ray Tracy, Deputy County Surveyor, in 1968, recorded in the Douglas County Surveyors Office corner renewal file, T. 26 S., R. 3 W., 440600, further recorded by Eugene A. Bloom, Registered Land Surveyor No. 492, in 1985, recorded in the Douglas County Surveyors Office map file M99-12; monumented with an iron pipe, 1 1/2 ins. diam., firmly set, projecting 4 ins. above ground, with brass cap mkd.</p> <p style="text-align: center;">COUNTY SURVEYORS OFFICE S 3 1/4 ----- S 10 1968</p> <p>from which the original bearing trees</p> <p>A madrone, 40 ins. diam., bears North, 31 1/2 lks. dist., with fragmentary scribe marks visible on opened blaze. (Record, 26 lks. dist.)</p> <p>A madrone, 28 ins. diam., bears S. 65° W., 60 lks. dist., with fragmentary scribe marks visible on partially healed blaze.</p> <p>and bearing trees mkd. by Tracy</p>	

ALUMINUM

BURNED SAWN 24" X 2 FT STUMP

GONE NO EVID.

CS 67/56-40
4/4