

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 24S RANGE 1W SEC. 20 PLSS # 300300

Date: 8/2/2023 By: JS

This survey consists of:

Map: \_\_\_\_\_

DOUGLAS COUNTY OREGON

DATE 7-26-23

Narrative: \_\_\_\_\_

Corner Rpt: CS 67/56-51

Corner Designation

sec COR 20/21  
29/28

DOUGLAS COUNTY  
SURVEYOR

Monument(s) Found: (Condition and Source)

2 1/2" DCSD BRASS CAP  
up 8" possible stone  
on west side up 14"

\_\_\_ Condition report

\_\_\_ Not Found

Renewed

\_\_\_ Unrecorded

\_\_\_ Surveyed In

Previous Renewals

DCSD 1961 CS 52/42-4

DCSD 1970 CS 54/27-184

BLM Resurvey 1981-1982

Vol 45 pg 17334

MONUMENT DETAIL

County Surveyors  
OFFICE

T24S R1W

S20/S21

S29/S28

1961

Accessories Found

SAWN FIR STUMP MOSTLY ROTTED AWAY N14 1/2° E  
21.2 FT

20" MOSTLY ROTTED AWAY FIR STUMP N10° W  
17.8 FT

48" X 20 FT TALL FIR SNAAG N26° W 10.2 FT  
(Rec N22° W) FRAGMENTARY SCRIBES VISIBLE  
ON PARTIALLY HEATED DOUBLE BLAZE  
ADD 3 1/2" NAG NAIL DRIVEN IN FACE OF  
UPPER BLAZE - (shattered snag)

RENEWAL

Monument Set (Procedure and Description)

MONUMENT DETAIL

New Accessories

6" CHINGWAPIN S23W 6.2 FT 3 1/2" MAG  
NAIL RIGHT SIDE CENTER

25" GRAND FIR S64W 11.2 FT 3 1/2" MAG  
NAIL RIGHT SIDE CENTER

5" DOUGLAS FIR N5W 11.5 FT 3 1/2" MAG  
NAIL RIGHT SIDE CENTER

Note: TREES NOT BLAZED OR SCRIBED

Sketch of Monument, Accessories, and General Area

Location & Comments

CORNER ON MODERATE EAST  
SLOPE IN OLDER SECOND  
GROWTH

MON. IS APPROX.  
120 FT EAST OF  
MAIN GRAVEL ROAD

AREA BURNED  
9-2020

DCRS COORDINATE SYSTEM  
COTTAGE GROVE - CANYONVILLE  
ZONE

Comp. Decline. 14 1/2° E  
Agency DCSO  
Party Chief S. F. LAUSE  
Note keeper  
Witnesses J. LOZUNG

N 231259.386

E 300231.386



EXPIRES: 12/31/2024

CS 67/56-51  
2/4

TOWNSHIP 24 RANGE 01 POINT IDENTIFIER # 300300

PRIMARY CORNER DESCRIPTION Cor. Secs. 20, 21, 28 & 29

OCS CANYONVILLE COTTAGE GROVE COORNS

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

SEE PG. 1 FOR MONUMENT DESCRIP.

MOSTLY ROTTED AWAY

A sawed fir stump, 24" dia., bears N.14½°E., 32 lks., with scribe marks T24S R1W S21 BT visible on an opened blaze.

21 1/2

NOT EVIDENT

A sawed fir stump, 30" dia., bears S.11½°E., 56 lks., with a healed blaze. (Rec. S.14°E.)

36 96

FALLEN OUT OF POSITION

A fir, 45" dia., bears S.4°W., 47 lks., with scribe marks T24S R1W S29 BT visible on opened blaze.

17 82

LOW 20+"  
MOSTLY ROTTED AWAY STUMP

A fir snag, 12" dia., bears N.10°W., 27 lks., with scribe marks 24 R W visible on partially healed blaze. (Rec. N.4°W.)

SHATTERED SNAG  
4-8" X 20 FT. TALL

and a BT mkd. by Godfrey  
A fir, 39" dia., bears N.22°W., 15½ lks., with fragmentary scribe marks visible on partially healed double blaze.

BLAZE AS DESCRIBED

3 1/2" MAG NAIL DRIVEN IN FACE OF UPPER BLAZE

The cor. lies in timber edge, bears N & S, with timber to the west; no suitable trees available to the east.

NEW REFS

6" CITINQUARIN 3 1/2" MAG NAIL R.S.C., BEARS S23°W, 62

25" GRAND FIR " " " , BEARS S64°W, 112

5" DOUGLAS FIR " " " , BEARS N05°W, 115

ON MODERATE EAST SLOPE IN OLDER SECOND GROWTH  
APPROX. 120 FT. EAST FROM MAIN GRAVELLED RD.

CS 67/56-51

TOWNSHIP 24 RANGE 01 POINT IDENTIFIER # 300300

PRIMARY CORNER DESCRIPTION Cor. Secs. 20, 21, 28 & 29

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Carl S. Nicklin, Dep. Surveyor under contract # 664, dated May 23, 1896 - (DCSO recs Vol. 7 Page(s) 2828)

Set a basalt stone 14x12x8" 10" in the ground for cor. of secs. 21, 28, 29, & 20, marked with 4 notches on E & 2 notches on S edges, from which

A fir, 24" dia., bears N.14½°E., 32 lks., mkd: T24S R1W S21 BT.

A fir, 30" dia. bears S.14°E. 56 lks. mkd: T24S R1W S28 BT

A fir, 30" dia. bears S.4°W., 47 lks. mkd: T24S R1W S29 BT

A fir, 10" dia. bears N.4°W., 27 lks. mkd: T24S R1W S20 BT

This cor. is on a hillside, sloping E, about 150 ft. above creek.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - Vernon Tracy - Clete Putnam - Oct. 1961 - C.S. File 52/42-4

Found - Orig. rock with 4 notches on E & 2 notches on E edges, rock lying loose on top of ground.

Fir tree, now 27" N.14½°E., 21.1 ft., has been opened recently good scribing "T24SR1W S21 BT" plainly visible.

Fir tree, now 12" N.4°W., 16.4 ft., (instead of 17.8 ft.) has been opened several years ago, scribing visible "24SRW20", face shows signs of decay although tree is alive.

Fir tree, now 44" S.10°W., (instead of S.4°W.) 31.0 ft., recently opened, good scribing "T24S R1W S29 BT" visible.

Fir tree, now 45", S.10°E., (instead of S.14°E., 37.0 ft., shows good axe scar, did not open.

Set - Brass cap mkd: County Surveyors T24S R1W S 20|S 21 OFFICE 1961 S 29|S 28

New BTs- 40" Fir N.22°W., 10.3 ft., mkd: T24S R1W S20 CS BT.

2 1/2" B.C. PROPERLY MARKED

Fd. Ok by DCSO, VRT May 1970 - C.S. File 54/27-184

BLM Dependent resurvey by James E. Jelley & Wayne L. Rogers, Cadastral Surveyors under Group #1051 surveyed April 1981/Sept. 1982 - (DCSO records Vol. 45 Page(s) 17334)

From the corner of secs. 20, 21, 28 & 29, perpetuated & recorded by Godfrey in 1961, monumented with an iron post, 1 1/4" dia., firmly set, projecting 14" above ground with brass cap (properly) mkd., from which the remains of the orig. BTs

PROT. 8"

continued next page

POSSIBLE ORIG. STONE ON WEST EDGE

CS 67/56-51 1/4