

GOVERNMENT CORNER RESTORATION FORM

TOWNSHIP 21S RANGE 9W SEC. 27 PLSS # 440200

FILED  
Date: 9/11/2023 By: JC  
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 8-28-23

Map: \_\_\_\_\_  
Narrative: as  
Corner Rpt: 67/56-62

DOUGLAS COUNTY  
SURVEYOR

Corner Designation

$\frac{1}{4}$  COR  $\frac{27}{34}$

Monument(s) Found: (Condition and Source)

BLM BRASS CAP

- Condition report
- Not Found
- Renewed
- Unrecorded
- Surveyed In

Previous Renewals

EDWARDS 2000 M 135-6  
BLM Resurvey 2013 Vol  
58 pgs 23167-8

MONUMENT DETAIL

T21S R9W  
 $\frac{1}{4}$   $\frac{S27}{S34}$   
2013

Accessories Found

21" D. FIR S83'14" W 9.7 FT Fully Healed  
Single BLAZE

11" D. FIR N11" W 5.7 FT Fully Healed  
Single BLAZE

Steel Post 2 FT West

Monument Set (Procedure and Description)

MONUMENT DETAIL

Horizontal lines for Monument Set description.

New Accessories

Horizontal lines for New Accessories description.

Sketch of Monument, Accessories, and General Area

Location & Comments

OERS Coordinate System  
Cottage Grove - Canyonville  
Zone

N 318793.397

E 52520.334

Comp. Decline 14 1/2° E  
Agency DCSO  
Party Chief S. F. HAUSE  
Note keeper  
Witnesses J. Zorsung

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Ronald A. Quimby*

OREGON  
JULY 14, 1978  
RONALD A. QUIMBY  
1654

EXPIRES: 12/31/2024

CS 67/56 62  
2/3

FWD. OK 8/28/23

TOWNSHIP 21 RANGE 09 POINT IDENTIFIER # 440200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 34

Alias _____	Description <u>OGRS CANYONVILLE COTTAGE GROVE COND.S</u>
Alias _____	Description _____
Alias _____	Description <u>318793.397 N</u>
Alias _____	Description <u>52520.334 E</u>

GLO survey by Alonzo Gesner, Deputy Surveyor, under Contract #608, dated April 17, 1893 - (DCSO rec. Vol. 2 Page(s) 942)

Set Hemlock post, 4½ ft. long, 4" sq., 24" in the ground on steep hillside sloping East for ¼ sec. cor., mkd: ¼ S on the North face; from which

- A Fir, 30" dia., bears N.8°E., 18 lks., mkd: ¼ S BT.
- A Fir, 50" dia., bears S.4°W., 31 lks., mkd: ¼ S BT.

David Edwards - For: Roseburg Resources - June 2000 - M 135-6

- Found - 1½" x 40" iron pipe & Orig. BT stumps  
 9" Fir S.10°E., 14.61 ft.  
 New BTs- 12" Fir, S.25°W., 20.69 ft.  
 15" Fir, S.86°W., 10.06 ft.  
 8" Fir, N.24°W., 6.15 ft.

BLM Dependent resurvey by Joseph M. Mannix, Cadastral Surveyor under Group No. 2721, surveyed June/Aug. 2013 - (DCSO records Vol. 58 Page(s) 23167-8)

The ¼ sec. cor. of secs. 27 & 34, perpetuated by person(s) unknown, and further perpetuated by Edwards, in 2000; monumented with a steel pin, 48" long, ⅝" dia., firmly set, projecting 28" above ground, with an alum. cap (properly) mkd from which the remains of an original bearing tree

A decayed fir stump, 3½ ft. high, 21" dia., bears N.19°E., 11.9 ft., with a burnt healed blaze. (Record, N.8°E.) and the bearing trees mkd. by Edwards

- 21" AD. fir, 17" dia., bears S.83¼°W., 9.7 ft., with a healed blaze. *FHSB*
- AD. fir, 11" dia., bears N.11°W., 5 ft., with no scribe marks visible on a ~~partially healed blaze.~~ *FHSB*

At the corner point Set a stainless steel post, 28" long, 2½" dia., 23" in the ground, in a collar of stone, with brass cap mkd.

T21S R9W  
 ¼ S 27  
 S 34  
 2013

Lying alongside the cor. is a disturbed iron pipe, 60" long, 2" dia. Remove the steel pin and the iron pipe from the area.

Corner is located on a ridge, bears N.25°W. and S.35°W.

*DECLINATION 14½°E*

~~N 43.70726~~ *FWD STEEL LATH 2 FT WEST*  
~~E 123.75476~~  
*CS 67/56-62*  
*3/3*