

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 25S RANGE 2W SEC. 23 PLSS # 600340

Date: 7/9/2024 By: X
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 6-19-24

Map: _____

Narrative: _____

Corner Rpt: 6567/58-11

Corner Designation

1/4 COR 23/24

DOUGLAS COUNTY
SURVEYOR

Monument(s) Found: (Condition and Source)

3 1/4" BRASS CAP BLM
UP 3"

___ Condition report

___ Not Found

Renewed

___ Unrecorded

___ Surveyed In

Previous Renewals

Hosford 1967 CS 42/308-B M16-5
Mc Chesney 1958 CS 53/112-39
BLM Resurvey 1962 Vol 32 pg 13217
DCSO 1966 CS 49/102-13
DCSO 1976 CS 59/26-28
BLM Resurvey 2001-2002
Vol 54 pgs 20909-10
EDWARDS 2020 M176-59
Accessories Found

MONUMENT DETAIL

1/4
S23 | S24
T25S R2W
Reset 1976
1962

Very Rotted - Burnt 40" X 3 FT FIR STUMP
S26°E 18° FT Center Root Crown (Rec S18 1/2° E
16.6 FT) Spike Gone

Very Rotted - Burnt 48" X 4 FT FIR STUMP S41 1/4 W
33.1 FT (Rec 32.6 FT) Bridge Spike in Top
24" X 1 FT D. FIR STUMP S57 1/4° E 17.5 FT (Rec
18.1 FT BLAZE inside ADD 3 1/2" MAG NAIL
TOP - Center

Burned Broken off 20" X 25 FT D. FIR
S29 1/2° W 24.8 (Rec 24.6) ADD 3 1/2" MAG
NAIL RIGHT Side Center

GALVANIZED Steel Post 2 FT South

C.S. File 67/58-11

Monument Set (Procedure and Description)

MONUMENT DETAIL

Blank lines for Monument Set (Procedure and Description)

New Accessories

Blank lines for New Accessories

Sketch of Monument, Accessories, and General Area

Location & Comments

Clear cut to East old
Reprod to West

MON on moderate
westerly slope
35 FT west of
Abandoned dirt
Logging Road

BCRS Coordinate System
Cottage Grove Canyonville
Zone

AREA Burnt 9/2020
Comp. Decline. 14 1/4° E
Agency DCSO
Party Chief S. F.ause
Note keeper
Witnesses J. Lorusan

N 199769.293
E 280892.006

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald A. Quimby

OREGON
JULY 14, 1978
RONALD A. QUIMBY
1654

EXPIRES: 12/31/2024

CS 67/58-11

2/3

TOWNSHIP 25 RANGE 02 POINT IDENTIFIER # 600340

PRIMARY CORNER DESCRIPTION 1/4 Cor Secs 23 & 24

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM resurvey by A. Bert Skeesick, Cadastral Surveyor under Group #1979, surveyed 2001/2002- (DCSO rec. Vol. 54 Page(s) 20909-10)

RENEWED 6/19/24

The 1/4 sec. cor. of secs 23 & 24, perpetuated by Tracy, in 1966. The uprooted monument set by Brooks in 1962 was recovered & reset by Monrean, in 1976, monumented with an iron post, 2 1/2" dia., firmly set, projecting 3" above ground, with brass cap mkd. 1/4

*3 1/4" B.C. S 23 | S 24
T25S R2W
RESET 1976
1962*

DECLINATION 14 1/4° E

from which the remains of a bearing tree mkd. by Tracy
A hemlock stump, 14" dia., bears S. ~~41 1/2°~~ E., 25.1 ft., with healed blaze.

30 1/2

and accessories mkd. by Monrean
A bridge spike driven into top of a fir stump, 61" dia., bears S. ~~18 1/2°~~ E., 16.6 ft., mkd. B02

SPIKE GONE

CENTER ROOT CROWN S 20° E 18° FT.

A bridge spike driven into top of a fir stump, 61" dia., bears S. ~~41 1/4°~~ W., 32.6 ft., mkd. B01

and new bearing trees
AD. fir 11" dia., bears S. ~~57 1/4°~~ E., 18.1 ft., mkd. 1/4 S24 BT.
AD. fir 13" dia., bears S. ~~29 1/2°~~ W., 24.6 ft., mkd. 1/4 S23 BT.

175

BLAZE INSIDE ADD 3 1/2" MAG NAIL TOP CENTER

Each new bearing tree has a ~~2 1/2" x 1/4"~~ magnetic nail (Mag Nail) driven at the base right side-center

ADD 3 1/2" MAG NAIL R.S.C.

(NOW INSIDE TREES) 24B

Fd. 2 BTs w/healed blazes and a ~~6" steel post set 2' S. 87° E.~~
By D. Edwards 3/2020 - M176-59

GONE

GALVANIZED STEEL LATH ≈ 2 FT SOUTH

MONUMENT IS ON MODERATE WESTERLY SLOPE ≈ 35 FT WEST FROM ABANDONED DIRT LOGGING RD. CLEAR CUT TO EAST, OLD REPROD. TO WEST.

*OGRS CANYONVILLE COTTAGE GROVE
199769.293 N, 280892.006 E*

*VERY ROTTED AND BURNED 40" X 3 FT STUMP
VERY ROTTED AND BURNED 48" X 4 FT STUMP
SAUN BURNED 24" X 1 FT STUMP
BURNED BROKEN OFF SNAG 20" X 25 FT*