

CONDITION REPORT

TOWNSHIP 22 RANGE 11 POINT IDENTIFIER # 500673 8/2/24

PRIMARY CORNER DESCRIPTION M.C. on West bdy. Sec. 2

Alias <u>882080</u>	Description <u>M.C. Left bank Umpqua River</u>
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #202, dated March 11, 1875, - (DCSO records Vol. 5 Page(s) 1856)

Set Post for M.P. from which
 An Alder 12" dia., bears S.14°E., 300 lks. dist.
 An Ash 6" dia., bears S.41°W., 250 lks. dist.

Wilford N. Haines, #239 - Jan. 1956 - C.S. File 42/121

Place for meander corner not set because it would be destroyed by road construction.

Set Witness corner for meander cor. S.03°19'E., 136.84 ft. from point for corner.

Set a 36" angle iron with brass cap inscribed "Survey Point Wilford N. Haines 239", from which **ANGLE IRON PROT 14" BRASS CAP GONE**
 A Spruce bears N.46°36'W., 39.55 ft.

B.O. on rock, N.80°06'E., 35.76 ft. **CORNER AND ACCESSORIES FOUND OK**

Now 86"

MMI GPS
43.69009
123.99123

FILED

Date: 8/8/2024 By: JC

This survey consists of:

Map: _____

Narrative: _____

Corner Rpt: CS 67/58-41

DOUGLAS COUNTY
SURVEYOR

C.S. FILE 67/58-41