

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 24S RANGE 2W SEC. 19

PLSS # 100340

Date: 10/31/2024 By: X

This survey consists of:

Map: \_\_\_\_\_

Narrative: \_\_\_\_\_

Corner Rpt: CS 67/59-10

DOUGLAS COUNTY OREGON

DATE 10-29-24

DOUGLAS COUNTY SURVEYOR

Corner Designation

1/4 COR 524/S19  
R3W R2W

Monument(s) Found: (Condition and Source)

2 1/2" DCSD BRASS CAP  
Proj 6"

\_\_\_ Condition report

\_\_\_ Not Found

Renewed

\_\_\_ Unrecorded

\_\_\_ Surveyed In

Previous Renewals

DCSD 1968 CS 54/27-145

MONUMENT DETAIL

COUNTY SURVEYORS OFFICE

T 24S

R 3W 1/4 524 S19 2W R

1968

Accessories Found

BURNED ROTTED 16" X 4 FT D. FIRE STUMP  
S 45° W 15.0 FT (REC 54B9W) TO CENTER  
ROOT CROWN BLAZE GONE

1/2" IRON PIPE AT N EDGE OF BRASS  
CAP UP 6"

RENEWAL

Monument Set (Procedure and Description)

MONUMENT DETAIL

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

New Accessories

3 5/8" X 30" IRON RODS WITH DC60  
PLASTIC CAPS PROF 3"

N 51° E 7.6 FT

S 37 1/2° E 8.6 FT

N 59° W 7.7 FT

Sketch of Monument, Accessories, and General Area

Location & Comments

MON IN DENSE STAND OF  
OLDER REPIOD GROUND BURD

AREA BURNT

9/2020

OGRS COORDINATE SYSTEM  
COTTAGE GROVE - CANYONVILLE  
ZONE

Comp. Decline. 14 1/4° E

Agency DC60

Party Chief S. FRAISE

Note keeper

Witnesses J. LORSUM

N 231787.316

E 255364.677

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Ronald A. Quimby*

OREGON  
JULY 14, 1978  
RONALD A. QUIMBY  
1654

EXPIRES: 12/31/2024

CS 67/59-10  
213

TOWNSHIP 24 RANGE 02 POINT IDENTIFIER # 100340

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 19; & 24, T24-3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description <u>O.C.R.S. CANYONVILLE COTTAGE GROVE COORD.S</u>

231787.316 N  
255364.677 E

GLO survey by W.H. Byars, Deputy Surveyor, under Contract #152, dated June 3, 1871, - (DCSO records Vol. 7 Page(s) 2948)

Set 1/4 sec. post, from which  
 A Hemlock 12" dia., bears S.35°E., 24 lks. dist.  
 A Hemlock 12" dia., bears S.88°W., 26 lks. dist.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew March 1968 - C.S. File 54/27-145

DECLINATION 14 1/4° E RENEWED 10/29/24

Found - 1/2"  I.P. set at corner and "W" method BT, unrecorded. NOW AT NORTH EDGE B.C. MON. PROT 6"  
~~NO EVIDENCE~~ Orig. 12" now 14" Hemlock S.35°E., 15.8 ft., now down and out of position, we find probable stump hole, face rotted, no scribe.

~~NO EVIDENCE~~ Orig. 12" now 14" Hemlock S.88°W., 17.2 ft., now stump, leaning, "BT" scribe visible on previously opened blaze.

BURNED ROTTED 16" x 4 FT. 30" D. Fir stump S. <sup>45°</sup>W., 15.0 ft. TO CRC "W" nail, we mark BLAZE GONE GONE  
~~"1/4 S24 CS BT"~~

Set Brass cap at cor. mkd. County Surveyors Office

2 1/2" R T 24 S ✓ R PROT 6"  
 B.C. 3W 1/4 S 24 S 19 2W  
 1968

~~NO EVIDENCE~~ New BT 20" Cedar stump S.28°E., 40.1 ft. mkd. 1/4 S19 CS BT. Corner lies on moderate NW. slope changing to very steep NW.

NOW IN DENSE STAND OF OLDER REPROD, GROUND SPREAD BURN

NEW REFS

- 5/8" x 30" I.R./DCSU SET PROT. 3" BEARS N 51°E, 7 1/2 FT. DIST. PLASTIC CAP
- " " " BEARS S 37 1/2°E, 8 1/2 FT. DIST.
- " " " BEARS N 54°W, 7 1/2 FT. DIST.

CS 67/59-10  
3/3 1