

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 26S RANGE 2W SEC. 15 PLSS # 440400

Date: 1/2/2025 By: X  
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 12-18-24

Map: \_\_\_\_\_  
Narrative: \_\_\_\_\_  
Corner Rpt: CS 67/59-32

Corner Designation 1/4 COR 15/22

DOUGLAS COUNTY  
SURVEYOR

Monument(s) Found: (Condition and Source)

2 1/2' 1918 GLO BRASS CAP  
IN ROUGH MOUND OF  
STONE

- Condition report
- Not Found
- Renewed
- Unrecorded
- Surveyed In

Previous Renewals

GLO Survey 1908 Vol 10 pg 4229  
GLO Resurvey 1916-1918  
Vol 10 pg 4324  
BLM Resurvey 1959 Vol 30 pg  
12728-9  
BLM CSL3/140-8 1992

MONUMENT DETAIL

1/4 515  
522  
1918

Accessories Found

48" SUGAR PINE BURNT BASE N1/6°E 27.1 FT  
(Rec 41 LKS)

BURNT 17" HEMLOCK S7 1/2°W 43.6 FT (Rec 66  
LKS)

C.S. File 67/59-32

RENEWAL

Monument Set (Procedure and Description)

MONUMENT DETAIL

Blank lines for Monument Set description.

New Accessories

Handwritten text: No suitable References Nearby

Sketch of Monument, Accessories, and General Area

Location & Comments

MON IS 25 FT ± NORTH OF STREAM  
RUNNING S.E AND GENERALLY  
SOUTH

MON. PARTLY BURNED  
OLD GROWTH

AREA BURNED  
9-2020

BCRS COORDINATE SYSTEM  
COTTAGE GROVE CANYONVILLE ZONE

Comp. Decline 14 1/4 E

Agency DCSO

Party Chief S. K. HAUSE

Note keeper

Witnesses J. CORNING

N 170017.205

E 273246.970

REGISTERED PROFESSIONAL LAND SURVEYOR

Handwritten signature: Ronald A. Quimby

OREGON  
JULY 14, 1978  
RONALD A. QUIMBY  
1654

EXPIRES: 12/31/2026

CS 67/59- 32

2/3

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 15 & 22

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by John A. McQuinn, Deputy Surveyor, under contract No. 466, dated April 5, 1883 - (DCSO records Vol. 10 Page(s) 4205)

-----  
 Set maple post 3" sq. 3 ft. long, 24" in ground for 1/4 sec. cor. marked 1/4 S on N face, from which  
     A dogwood, 8" dia., bears N.40°W., 17 lks., mkd: 1/4 S BT.  
     A hemlock, 20" dia., bears S.10°E., 20 lks., mkd: 1/4 S BT.

GLO survey by Wm. N Gibb, Deputy Surveyor, under contract No. 783, dated Dec. 3, 1908 - (DCSO records Vol. 10 Page(s) 4229)

-----  
 Unable to find any trace of 1/4 cor. after diligent search.  
 Set stone, 8x10x14" 10" in the ground for 1/4 cor., sec. 15 marked 1/4 on N face & raise mound of stone, 2 ft. base, 1 1/2 ft. high, north of cor. from which  
     A fir, 12" dia., bears N.14°E., 81 lks., mkd: 1/4 S15 BT.

GLO resurvey by Fred Mensch, U.S. Cadastral Engineer; under Instructions dated May 25, 1916 & April 16, 1918, - (DCSO records Vol. 10 Page(s) 4324)

-----  
 Set an iron post, 3 ft. long, 1" dia., 26" in the ground, for 1/4 sec. cor., with brass cap mkd:

1/4     $\frac{S \ 15}{S \ 22}$   
           1918

from which

    A sugar pine, 36" dia. bears N.16°E. 41 lks. mkd: 1/4 S15 BT  
     A fir, 18" dia., bears S.69°E., 54 lks., mkd: 1/4 S22 BT.

An old cor. apparently set as the 1/4 cor. of secs. 15 & 22 bears S.86°37'W., 6.44 chs. This is the cor. mentioned by Irving P. Gardner in his statement in regard to this line and is also described by Collier in notes of revision survey in this Tp. I find an old post, which I classify as dogwood, about 2" dia., faced on one side, scribed 1/4 S, similar in appearance & scribing to the post of the McQuinn survey. It is witnessed by 2 BTs as follows:

    A red fir, 30" dia., bars S.11°E., 22 lks.  
     A red fir, 36" dia., bears N.13°W., 18 lks.

The blazed on these trees have been deeply overgrown and have been cut out in recent years. The cor. appears old enough to have been made at the time of the McQuinn survey. The blaze on the SE tree faces nearly West, no where near the post, & the blazes on the 2 trees do not face any common point.

continued next page

MINIGIS  
 43.29916  
 122.92310