

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 30 RANGE 7W SEC. 19 PLSS # 100306

Date: 1/28/2025 By: KL  
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 1-22-25

Map: \_\_\_\_\_  
Narrative: \_\_\_\_\_  
Corner Rpt: CS 67159-48

Corner Designation

RBW R7W  
524 | 519  
SEC COR 525 | 530

DOUGLAS COUNTY  
SURVEYOR

Monument(s) Found: (Condition and Source)

BLM BRASS CAP  
PROJ 6"  
GALVANIZED POST N.E. EDGE

Condition report  
 Not Found  
 Renewed  
 Unrecorded  
 Surveyed In

Previous Renewals

DCSO 1965 CS 53/40-76  
NOT FD  
BLM RESURVEY 1972 Vol 35  
PG 14884  
Quimby 2014 CS 65/82-35

MONUMENT DETAIL

T 305  
RBW R7W  
524 | 519  
525 | 530

Accessories Found

25" W. FIR (REC Hemlock) N 10° E 14.5 FT  
GOOD SCAR  
10" CEDAR S 68° E 34.0 FT GOOD SCAR

26" FIR N 41° W 20.5 FT GOOD SCAR

20' X 12 FT FIR SNA9 S 76° W 24.3 FT  
VISIBLE SCRIBES

ADD NEW TAG'S TO ALL TREES

Monument Set (Procedure and Description)

MONUMENT DETAIL

Blank lines for Monument Set description.

New Accessories

Blank lines for New Accessories description.

Sketch of Monument, Accessories, and General Area

Location & Comments

OCRS COORDINATES  
Cottage Grove - Canyonville  
zone

Cor 15 50± south  
of road to landing  
in S.E. corner  
of old logging

N 39508. 285  
E 96763. 020

Comp. Decline. 14 1/2° E  
Agency DCSO  
Party Chief S. F. KAUSE  
Note keeper  
Witnesses J. LORSUNG

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

Ronald A. Quimby

OREGON  
JULY 14, 1978  
RONALD A. QUIMBY  
1654

EXPIRES: 12/31/2026

TOWNSHIP 30 RANGE 07 POINT IDENTIFIER # 100300

PRIMARY CORNER DESCRIPTION Sec. Cor. for 19 & 30; & 24 & 25, T30-8

Alias _____	Description _____
Alias _____	Description <u>DCRS CANYONVILLE COTTAGE GROVE CORP. S</u>
Alias _____	Description _____
Alias _____	Description <u>39508.285 N</u>
	<u>96763.820 E</u>

GLS survey by W.H. Byars, Deputy Surveyor under contract # 45 dated July 28, 1882 (DCSO records Vol. 17 Pages 7250-51)

Marked a Fir tree 16" dia. for the cor. to secs. 19, 24, 25 and 30. Marked T30S R7W S19 on the NE.; S30 on the SE. face.; R8W S25 on the SW. face.; and S24 on the NW. face. Also two notches on the S. and four on the N. edges, and from which

A Fir 4" dia., bears N.48°E., 13 lks mkd. T30S R7W S19 BT.  
 A Fir 6" dia., bears S.58°E., 40 lks mkd. T30S R7W S30 BT.  
 A Fir 24" dia., bears S.80°W., 37 lks mkd. T30S R8W S25 BT.  
 A Fir 7" dia., bears N.20°W., 19 lks mkd. T30S R8W S24 BT.

Not fd by DCSO 6/1965 C.S. File 53/40-76

BLM resurvey by Stephen D. Albright and Jack W. Bowder, Cadastral Surveyors, under Group #787, surveyed July/Aug. 1972 - (DCSO records Vol. 35 Page(s) 14884)

Point for the cor. of secs. 19, 24, 25 and 30, at proportionate distance; there is no remaining evidence of the original corner.  
 Set an iron post 28" long, 2 1/2" dia., 24" in the ground, with brass cap mkd:

T	30	S
R	8	W
R	7	W
S	24	S
S	25	S
S	30	
1972		

PROT 6"  
 GALVANIZED METAL LATH ON NE EDGE

from which

A Hemlock 13" dia., bears N.10 1/2°E., 22 lks. mkd. T30S R7W S19 BT.  
 A Cedar 5" dia., bears S.68°E., 54 1/2 lks. mkd. X BT  
 A Fir 9" dia., bears S.61°W., 34 lks mkd. T30S R8W S25 BT.  
 A Fir 18" dia., bears N.41°W., 31 lks mkd. T30S R8W S24 BT

Ron Quimby - Crew: J. Leonard and N. Fromdahl - 4/2014 - C.S. File 65/82-35

Found - BLM brass cap W. FIR 2 RENEW ALL TAGS  
25" 24" hemlock N.10°E., 14.5 ft. good scar ✓  
 10" cedar S.68°E., 36.0 ft. good scar ✓  
 26" fir N.41°W., 20.5 ft. good scar ✓  
 New 20x12" SNAG 20" fir S.76°W., 24.3 ft. scribed T30S R8W S25 BT. SCRIBING VIS.  
 Note - Corner is 50' ± south of road to landing in SE cor. of old logging.  
 Compass decl. 15 1/2°E.

MINI GIS  
 42,94145  
 123,58458  
 NOT PART OF RENEWAL  
 TAKE WILLCAT CRK. AT ABOUT 2 MI PAST END OF  
 PAVT. OLLALA CRK. THEN 1/2 MI. GO RT. AT SWITCHBACK  
 STAY RT MOSTLY, TAKE LFT WHEN  
 CROSSING HIGH RIDGE  
 CONTINUE SWLY TO COR.