

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 30S RANGE 7W SEC. 36 PLSS # 620100

Date: 4/22/2025 By: YC
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 4-1-25

Map: _____

Narrative: _____

Corner Rpt: CS 67160-15

Corner Designation

DOUGLAS COUNTY
SURVEYOR

W 1/4 S 36-1 T 31-7

Monument(s) Found: (Condition and Source)

___ Condition report

3/4" BLM BRASS CAP

___ Not Found

unreadable LEANS slightly

Renewed

North Flush

___ Unrecorded

Previous Renewals

___ Surveyed In

BLM Resurvey 1969 Vol 35 pg 14499

BLM Resurvey 1977 Vol 41 pg 16258

DCSO 1999 CS 6412-28

MONUMENT DETAIL

Accessories Found

(Rec N 71°W)

3/4" BLM BRASS CAP N 67 1/2° W 36.3 FT
Flush This monument is approx.
1 1/2 FT SSW OF 16" ponderosa PINE

24" D. FIRE N 9 1/2° E 32.5 FT (REC N 18° E
32.9 FT) Fully heated Double Blize
ADD 3 1/2" mag Nail left side Center

1/2" Iron Rod with yellow BLM Plastic
Cap MKD BLM N 77° E 217.5 FT (Rec
N 74 1/2° E)

Corpe is 6 FT Northerly of Northerly
RAIL OF RR TRACKS

BEARINGS ARE LOCAL MAGNETIC MEASURED
FROM CORNER RR RAIL LIKELY INFLUENCE
COMPASS

New Accessories

5/8" x 30" Iron Rod South 30.0 FT
with yellow DCSO plastic cap
projecting 6"

Sketch of Monument, Accessories, and General Area

Location & Comments

DCRS Coordinate System
Cottage Grove - Canyonville
Zone

N 29312.967

E 124301.627

Comp. Decline. 14 1/2° E

Agency DCSO

Party Chief S.K. KAUSE

Note keeper

Witnesses J. Lorusong

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald A. Quimby

OREGON
JULY 14, 1978
RONALD A. QUIMBY
1654

EXPIRES: 12/31/2026

PRIMARY CORNER DESCRIPTION W 1/16 Sec. 36, & S 1 T31-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM resurvey by James E. Jelley, Cadastral Surveyor - under Group #350;680, surveyed April/Sept. 1969 - (DCSO records Vol. 35 Page(s) 14499)

Point for the W 1/16 sec. cor. of secs. 1 & 36.
Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:
W 1/16 $\frac{S\ 36}{S\ 1}$
1969

from which a BT & reference monument
A Fir, 5" dia., bears N.66°W., 55½ lks., mkd: 1/16 S36 BT.
An iron post, 28" long, 2½" dia., set 24" in the ground, for a reference monument, bears S.48°E., 59½ lks., with brass cap mkd: W 1/16 S1 RM 1969 and an arrow pointing to the corner.

BLM resurvey by James E. Jelley, Cadastral Surveyor - under Group #680, surveyed June 1977 - (DCSO records Vol. 41 Page(s) 16258)

Point for the W 1/16 sec. cor. of secs. 1 & 36 erroneously established by Jelley in 1969, bears N.71°02'W., 0.17 chs., set, mkd. & witnessed as described in the official rec.
I remove the iron post, destroy the marks on the bearing tree, and at the corner point.
Reset the iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked:
W 1/16 $\frac{S\ 36}{S\ 1}$
1977
1969

from which
An iron post, 28" long, 2½" dia., set 24" in the ground, for reference monument, bears N.71½°W., 55 lks., with brass cap mkd: W 1/16 S36 RM 1977 and an arrow pointing to the corner.
An iron post, 28" long, 2½" dia., set 24" in the ground, for a reference monument, bears S.39 ¾°E., 43½ lks., with brass cap mkd: W 1/16 S1 RM 1969 and an arrow pointing to the corner.

RENEWED 4/1/25

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 9/20/1999 - C.S. File 66/12-28

Found - ^{3/4}2½" dia., BLM brass cap on a 2½" O.D. iron pipe, flush with ground, brass cap marred and unreadable. 1977 BLM **MONUMENT DAMAGED LEANS SLIGHTLY NORTH**
^{3/4}2½" dia., BLM brass cap on a 2½" O.D. iron pipe **FLUSH WITH** protrudes ~~2"~~ above ground, bears N.71½°W., 36.3 ft. (agrees w/rec.) 1977 continued next page

THIS MON. IS APPROX 1 1/2 FT SSW FROM 16" PONDEROSA PINE

67 1/2" 1 CS 67160-15 pg 3/4

TOWNSHIP 30 RANGE 07 POINT IDENTIFIER # 620100

PRIMARY CORNER DESCRIPTION W 1/16 Sec. 36, & S 1 T31-7

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

Alias _____ Description _____

DECLINATION $14^{\circ}12'E$
 $9\frac{1}{2}^{\circ}$

New BOS ~~17~~ ²⁴ 1977 SE ref. monument now gone ✓
D. Fin ✓ double blazed & scribed "W 1/16 S36 CS BT" FHDB
bears N. ~~8~~ ⁸ E., ~~32.9~~ ^{32.5} ft. **32.5 FT. ADD 3 1/2" MAG NAIL L.S.C.**
1/2" I.R. with yellow BLM plastic cap mkd: BLM ✓ bears
N. ~~7 1/2~~ ^{7 1/2} E., 217.5 ✓ ft.

Note - Corner lies 6 ft. northerly of northerly rail of R/R ✓
tracks. See sketch in file.

$77\frac{1}{2}^{\circ}$

NEW REFERENCE

A 5/8" x 30" IRON ROD WITH A YELLOW DCSO PLASTIC CAP BEARS SOUTH, 30² FT.
MONUMENT PROT. 6"

BEARINGS ARE LOCAL MAGNETIC MEASURED FROM CORNER
MONUMENT. RR RAILS PROBABLY INFLUENCE COMPASS.

MONUMENT CONDITION IS NOT IMPROVED AREA IS REGULARLY
DISTURBED BY RAILROAD MAINTENANCE.

CS 67/60-15

pg 4/4