

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 32S RANGE 7W SEC. 33 PLSS # 460100

Date: 5/5/25 By: 10
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 4-21-25

Map: _____

Narrative: _____

Corner Rpt: CS 67/60-26

Corner Designation

S.C. 33/34

DOUGLAS COUNTY
SURVEYOR

Monument(s) Found: (Condition and Source)

BLM BRASS CAP
UP 1"

___ Condition report

___ Not Found

___ Renewed

___ Unrecorded

___ Surveyed In

Previous Renewals

PRICE 1954 CS 41/301

DCSO 1967 CS 54/36-101

BLM Resurvey 1975 Vol 41 pg 16270

Templin 1995 M122-53

Quimby 2014 CS 65/86-18

MONUMENT DETAIL

S.C.
T32S R7W
533/534
1975

Accessories Found

26" Cedar Stump 7" TALL N134°W 10.2 FT
GOOD SCAR

16" Cedar Stump 6' TALL N48°E 19.0 FT
GOOD SCAR

27" Cedar Stump 6' TALL N55°E 37.0 FT
GOOD SCAR

Metall Post ± 2. FT EAST

Monument Set (Procedure and Description)

MONUMENT DETAIL

Blank lines for Monument Set description.

New Accessories

Blank lines for New Accessories description.

Sketch of Monument, Accessories, and General Area

Location & Comments

OCRS COORDINATE SYSTEM
Cottage Grove - Canyonville
Zone

MON ON STEEP DRAW
BANK FACING NNW
ADD 15' E NORTH
OF GRAVEL ROAD

N-34011.168
E 112344.688

Comp. Decline. 14 1/2° E
Agency DCSD
Party Chief S. E. HAUSE
Note keeper
Witnesses J. LORSUNG

CS 67160-26

pg 2/4

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald A. Quimby

OREGON
JULY 14, 1978
RONALD A. QUIMBY
1654

EXPIRES: 12/31/2026

KEUBEN RD. CORN

TOWNSHIP 32 RANGE 07 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION S C for Secs. 33 and 34 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

MINI GIS
42.73983
123.52579

42° 44' 23.47968" N -34011.168 N
123° 31' 32.74855" W 112344.688 E

GLO survey by W.H. Byars, Deputy Surveyor under contract # 420 survey dated Sept 16 1881 (DCSO records Vol. 20 Page(s) 8703 and Page 8733)

Set Fir post, 4½ ft. long, 4" sq., and 20" in the ground, for S Cor. to Secs. 33 and 34, from which

- A Cedar 12" dia., bears N.55°E., 56 lks. dist. mkd. S C T32S R7W S34 BT.
- A Fir 28" dia., bears N.75°W., 34 lks. dist., mkd. S C T32S R7W S33 BT.
- A Cedar 24" dia., bears S.20°E., 34 lks. dist., mkd. S C T33S R7W S4 BT.

Survey by Norman D. Price - For: Dollar and Patterson Lumber Co. - March/Aug. 1954 - C.S. File 41/301

Determined at record bearing and distance from the only extant original bearing tree.

At the Corner point

Set an Iron pipe, 3 ft. long, 2" dia., 28" in the ground, mkd. RS33.

From which an original bearing tree

- An Incense Cedar 24" dia., bears N.55°E., 56 lks. dist., with the scribe marks S34 SC visible.
- New BT - An Incense Cedar 14" dia., bears N.34½°W., 15½ lks. dist., mkd. T32S R7W S33 SC RS33 BT.

Fd. OK, DCSO, J.Powell, Dec. 5, 1967, C.S. File 54/36-101

BLM resurvey by Lynn M. Roseberry and Rollin D. Aanrud, Cadastral Surveyors, Under Group #845, surveyed April/Nov. 1975 (DCSO records Vol. 41 Page(s) 16270)

The standard cor. of secs. 33 and 34, perpetuated and recorded by Price, in 1954, monumented with an iron pipe 2" dia., firmly set, projecting 6" above ground, with brass washer mkd. RS 33, from which the remaining original bearing tree:

- A Cedar 24" dia., bears N.55°E., ^{36⁹⁶}56 lks. dist., with healed blaze.

and a bearing tree mkd. by Price

- A Cedar 18" dia., bears N.34½°W., ^{10²³}15½ lks. dist., with healed blaze.

At the corner point

Set an iron post, 28 ins. long, 2 1/2 ins. dia., 24 ins. in the ground, directly over iron pipe, with brass cap marked (Cont. Next Page)

OUT BOTTOM RU
OK 3RD NIGHT GOING UP
(EXTREME) - STAY TO RIGHT ON
MAIN RD.

TOWNSHIP 32 RANGE 07 POINT IDENTIFIER # 400100

PRIMARY CORNER DESCRIPTION S C for Secs. 33 and 34 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

<table border="0"> <tr><td>S</td><td>C</td></tr> <tr><td>T 32</td><td>S R 7 W</td></tr> <tr><td>S 33</td><td>S 34</td></tr> <tr><td colspan="2">1975</td></tr> </table>	S	C	T 32	S R 7 W	S 33	S 34	1975		<p><i>SEE PAGE 1 FOR GPS LOCATION</i></p>
S	C								
T 32	S R 7 W								
S 33	S 34								
1975									
<p><i>DECLINATION 14 1/2° E</i></p>	<p><i>VISITED 4/21/25</i></p>								
<p>Found OK by R. Templin, July 1995 - M122-53</p>									
<p>Ron Quimby - Crew: N. Fromdahl & D. Manring - 9/2014 - C.S. File 65/86-18</p> <p style="text-align: center;">-----</p>									
<p>Condition report only</p> <p>Found - BLM brass cap <i>(AS ABOVE) PROT 1"</i></p> <p style="margin-left: 20px;">26" Cedar stump (7' tall) N.34°W. 10.2 ft good scar.</p> <p style="margin-left: 20px;">16" Cedar stump (6' tall) N.48°E. 19.0 ft good scar.</p> <p style="margin-left: 20px;">27" cedar stump (6' tall) N.55°E. 37.0 ft good scar.</p> <p>Note - Area badly burnt 2013. Compass decl. 15 1/2° E.</p>									
<p><i>FOUND A METAL LATH SET ≈ EAST, 20 FT.</i></p> <p><i>MONUMENT IS ON STEEP DRAW BANK FACING NNW AND IS ≈ 15 FT NORTH FROM A GRAVEL RD</i></p>									