

TOWNSHIP 32S RANGE 9W SEC. 5 PLSS # 240600

Date: 5/28/25 By: Ke
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 5-13-25

Map: _____
Narrative: _____
Corner Rpt: CS 67/60-32

Corner Designation

1/4 COR 5/8

DOUGLAS COUNTY
SURVEYOR

Monument(s) Found: (Condition and Source)

2 1/2" GLO BRASS CAP
proj 1"

- Condition report
- Not Found
- Renewed
- Unrecorded
- Surveyed In

Previous Renewals

GLO Resurvey 1916 Vol 21 pg 8918
DCSO 1967 CS 54/44-43

MONUMENT DETAIL

1/4 55
58
1917

Accessories Found

BADLY ROTTED 30" X 2 1/2' D. FIRE STUMP
S23°E 15.8 FT (slope Dist) 14° Horiz.

17" D. FIRE N 80°E 56.5 FT Fully Healed
SINGLE BLAZE TREE ON TOP OF HIGH
CUT BANK

Monument Set (Procedure and Description)

MONUMENT DETAIL

New Accessories

48" D. FIR S 43° E 14.3 FT, Not Scribed
 3 1/2" MAG NAIL RIGHT SIDE CENTER

Sketch of Monument, Accessories, and General Area

Location & Comments

GIS MAP LOCATION
 42.81180 N
 123.78526 W

CORNER 20 FT
 SOUTH OF OLD
 ROAD

Comp. Decline. 14 1/2° E
 Agency DCSO
 Party Chief S. HAUSE
 Note keeper
 Witnesses J. LORSUDY



EXPIRES: 12/31/2026

CS 67160-32

pg 2/3

TOWNSHIP 32 RANGE 09 POINT IDENTIFIER # 240600

PRIMARY CORNER DESCRIPTION 1/4 Cor Secs 5 & 8

Alias _____	Description _____
Alias _____	Description <u>GIS MAP NO SATELLITES AVAILABLE</u>
Alias _____	Description _____
Alias _____	Description <u>42.81180°N</u>
Alias _____	Description <u>123.78526°W</u>

MINI GLO
42.81180
123.78526

GLO Dependent survey by Fred Mensch & Gerald A. Sorrels, Dep. Surveyors under special instructions dated Dec. 22, 1916 - (DCSO records Vol. 21 Page(s) 8918)

RENEWED 5/13/25

Set an iron post, 3 ft. long, 1" dia., 26" in the ground, for 1/4 sec. cor., with brass cap marked

1/4 S 5/8 1917

2" GLO CAP PROT. 1"

NOT ABLE TO OCCUPY TOO CLOSE TO

from which

A fir, 18" dia., bears S.23°E., 24 lks., mkd: 1/4 S8 BT. TOP OF CUTBANK
A fir, 24" dia., bears N.14°W., 7 lks., mkd: 1/4 S5 BT.

Douglas Co. Surveyors Office - John M. Powell - Frank Jones & J Brady - June 1967 - C.S. File 54/44-43

Found - GLO Brass Cap at 1/4 Corner mkd: In 1917. SLOPE DIST - 14° HORZ. 18", now 35" D. Fir, S.23°E. 15.8 ft., shows scars: ~~18" D. Fir, now 24" snag, N.14°W. 4.7 ft., scribing~~ visible.

ALMOST ROTTEN - 30" x 2 1/2" AWAY STUMP

(NO EVIDENCE)

New BT 17 1/2" D. Fir N.80°E. 56.5 ft. mkd: 1/4 S5 CS BT. FHSB
Note - This corner lies 20.0 ft. south of old road, in cut unit. AT TOP OF HIGH CUTBANK

NEW REF.

40" D. FIR NOT SCRIBED ADD MAG NAIL R.S.C. TREE BEARS S43°E, 14 3/4 FT