

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 32S RANGE 8W SEC. 32 PLSS # 300106

Date: 6-19-25 By: UC
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 6-16-25

Map: _____
Narrative: _____
Corner Rpt: CS 67/60-41

DOUGLAS COUNTY
SURVEYOR

Corner Designation

Sec 32 | 33
4

Monument(s) Found: (Condition and Source)

2 1/2" DCSO BRASS CAP
Flush with surface

- Condition report
- Not Found
- Renewed
- Unrecorded
- Surveyed In

Previous Renewals

GLO Resurvey 1916 Vol 21 pg
8856 - 57
DCSO 1968 CS 54/65-63
Thompson 1983 M 95-33 CS
58/275 (N)

MONUMENT DETAIL

COUNTY SURVEYORS
OFFICE
T32S
Douglas 32 | 33
Josp. Co. 54
T33S
1968

Accessories Found

Sawn Rotted 30" x 5 FT Sugar Pine Stump
N 8° E 32.8 FT (Rec 32.0) BLAZE E SCAR
ADD 6" spike top center

30" D FIR 510°W 64.0 (Rec 64.1 1968) Fully
Healed Single BLAZE ADD 3 1/2" MAG Nail
RIGHT Side Center

New Accessories

5/8" X 30" Iron Rod with DCSO plastic cap 520°E 20.4 FT set flush with ground

5/8" X 30" Iron Rod with DCSO plastic cap N85°W 24.9 FT cap 10" above ground

Iron Rods ARE IN Easterly AND Westerly shoulder of Gravel Road

Sketch of Monument, Accessories, and General Area

Location & Comments

Trimble Geo XT Position
42°44'23.063"N
123°39'29.454"W

MON. 15 APPROX
9 FT FROM
E GRAVEL ROAD

Comp. Decline. 14 1/2°E
Agency DCSO
Party Chief SIFHAUSE
Note keeper
Witnesses J. Corsun

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald A. Quimby

OREGON
JULY 14, 1978
RONALD A. QUIMBY
1654

CS 67/60-41 pg 2/4

EXPIRES: 12/31/2026

TOWNSHIP 32 RANGE 08 POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION Standard Sec. Cor. for 32 & 33 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

MINI GIS
42.73972
123.65812

GLO survey by Richmond S. Dickerson, Deputy Surveyor, under Contract #474, dated May 10, 1883 - (DCSO records Vol. 21 Page(s) 8772)

Set a stone 14x12x8 ins., 10" in the ground for the standard cor. to secs. 32 and 33 marked SC on N. face with 4 notches on E. and 2 notches on W. edges, from which

- Pine 10" dia., bears N.14°E., 40 lks. dist. mkd. T32S R8W S33 BT.
- Fir 12" dia., bears S.42°E., 40 lks. dist. mkd. T33S R8W S4 BT.
- Fir 5" dia., bears N.64°W., 67 lks. dist. mkd. T32S R8W S32 BT.

BLM Resurvey by Norman D. Price, U.S. Surveyor, Under instructions dated Sept. 22, 1916 - (DCSO records Vol. 21 Page(s) 8856-57)

The standard cor. of secs. 32 and 33, which is a granite stone, 12x8x4 ins., above ground, firmly set, mkd. and witnessed as described by the surveyor general. The old bearing trees being in poor condition, I obliterate markings on same and take new bearing trees as follows:

- A Pine 30" dia., bears N.8°E., 50 lks. dist. mkd. T32S R8W S33 SC BT.
- A Fir 12" dia., bears N.51½°W., 96 lks. dist. mkd. T32S R8W S32 SC BT.

Douglas Co. Surveyors Office - John M. Powell, and crew - May 1968 - C.S. File 54/65-63

Found - No trace of corner stone. (Sec. Cor. falls in shoulder of road.)

- 30" now 38" Pine, N.8°E., 33.0 ft., scribe visible, "3" "8" & others.
- NW. tree falls in road.

Set Brass cap at cor. mkd: County Surveyors Office

T 32 S	R
Doug.Co.S 32	S 33
Josp.Co.	S 4
T 33 S	
1068	

New BT - No trees available to the North.

- 12" D.Fir S.10°W., 64.1 ft. mkd. T33S R8W S4 SC CSBT

Corner lies on E. edge of road in mound of stone.

(Cont. Next Page)

CS 67/60-41 pg 3/4

TOWNSHIP 32 RANGE 08 POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION Standard Cor. for Secs. 32 & 33 only

Alias _____	Description _____
Alias _____	Description <u>TRIMBLE GED XT POSITION</u>
Alias _____	Description _____
Alias _____	Description <u>42°44'23.063"N</u>

DECLINATION 14 1/2°E 123°39'29.454"W

RENEWED 6/16/25

Survey by Robert M. Thompson, LS #1358 - For: Boise Cascade
Tmber Lands of Oregon - Oct. 21. 1983 - M 95-33; C.S. File
58/275(n)

Found - 1968 DCSO brass cap on 1" Galv. I.P. nearly
uprooted, lying on surface of road shoulder.

SAWN ROTTEN STUMP

30" x 5 FT. 40" Sugar Pine N. 8° E, 33.0 ft., face healed. BLZ. S.C.A.R.
30" x 5" D. Fir S. 10° W, 64.0 ft. (1968) face healed. FHSB

328 2 1/2" BC. MARKED AS PREVIOUSLY
DESCRIBED FND. FLUSH WITH
SURFACE

ADD 6" SPIKE TOP CONTR.

Since the hole remnant checks with the above BTs, I RESET the
monument therein flush with the surface, in northeasterly
shoulder of Rd. No. 34-8-1, northwesterly & southeasterly.

ADD 3 1/2 MAG
NAIL R.S.C.

NEW REFERENCES:

- A 5/8" x 30" IRON ROD / DCSO SET TOP FLUSH WITH GROUND; BEARS S 20° E, 206 FT.
- " " " " PLASTIC CAP
- " " " " SET TOP 10" ABOVE GROUND; BEARS N 85° W, 249 FT.

I.R.s ARE IN EASTERLY AND WESTERLY SHOULDER OF GRAVEL RD.

BC. MONUMENT IS ≈ 9 FT. EAST OF GRAVEL RD. ♀.