

TOWNSHIP 24S RANGE 3W SEC. 22

PLSS # 500340 Date: 10/20/25 By: lc
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 10-1-25

Map: _____

Narrative: _____

Corner Rpt: CS 07/01-33

Corner Designation

1/4 COR 22/23

DOUGLAS COUNTY
SURVEYOR

Monument(s) Found: (Condition and Source)

2 1/2" BRASS CAP

Proj 5"

Condition report

Not Found

Renewed

Unrecorded

Surveyed In

Previous Renewals

DCSO 1968 CS 54/27-151

BAKER 1983 M 90-48

MONUMENT DETAIL

Accessories Found

BURNED OFF 16" X 6 FT FIR STUB N 56° E 22.7 FT
(RPC N 57° E 22.2 FT) Fully Healed Single
BLAZE

BROKEN BURNED 14" X 1 FT Hemlock stub
N 10° W 24.6 FT (RPC N 12° W)

metal pipe Not FD destroyed by
landslide

New Accessories

6" D. Fir Singed base 56 1/2° W 24.0 FT
3 1/2" MAG NAIL RIGHT SIDE CENTER

23" X 2' Burned SAWN D. Fir STUMP 555° W
35.8 FT 3 1/2" MAG NAIL TOP CENTER

6" X 4 FT Broken SWAG N 54° W 30.2 FT
3 1/2" MAG NAIL RIGHT SIDE CENTER

Sketch of Monument, Accessories, and General Area

Location & Comments

OCRS Cottage Grove -
CANYONVILLE ZONE LOCATION
43° 23' 03.23651 N
123° 01' 51.27119 W

MON ON N. Edge
LARGE BENCH ID
Recent Clearcut
older Reprod To
North
AREA BURNED
9/2020
Comp. Decline. 14' 14" E
Agency DCSD
Party Chief S. F. AUSE
Note keeper
Witnesses J. LORSUNO

CS 67161-38

pg 2/3

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Ronald A. Quimby

OREGON
JULY 14, 1978
RONALD A. QUIMBY
1654

EXPIRES: 12/31/2026

PRIMARY CORNER DESCRIPTION 1/4 Cor Secs 22 & 23

Alias _____	Description _____
Alias _____	Description <u>OCS CANYONVILLE COTTAGE GROVE POSITION</u>
Alias _____	Description _____
Alias _____	Description <u>43°28'03.23651"N</u>
	<u>123°01'51.27119"W</u>

GLO survey by L.H. Wheeler under Contract No. 467 dated April 7, 1883 (DCSO records Vol. 7 Page(s) 2991)

Set a cedar post 3x4" 3 1/2 ft. long, 24" in the ground for 1/4 sec. cor. marked 1/4 sec. cor. mkd. 1/4 S on W face from which
A hemlock, 8" dia., bears S.19°E., 32 lks., mkd: 1/4 S BT.
A fir, 10" dia., bears N.21°W., 15 lks., mkd: 1/4 S BT.

Douglas Co. Surveyors Office, - Vernon "Ray" Tracy - Jack Heritage - V. Perron - March 1968 - C.S. File 54/27-151

Condition report only
Found - Unrecorded 1/2" pipe & 1 1/2"x8' marker pipe with "W" method BTs
30" Fir stump N.65°E., 20.8 ft., "W" nail & tag.
50" Fir stump S.72°W., 54.0 ft., "W" nail & tag.
We find no trace orig. BTs.

Dan Baker, For: Weyerhaeuser Co. - Dec. 8, 1983 - M90-48

Set - ^{0.01} 2 1/2"x36" iron pipe with brass cap with standard markings
 8" Fir ^{22.2} N.56°E., 22.2 ft. ^{FHSB 57°E MON PROT. 5"}
 8" Hemlock ^{22.2} N.42°W., 26.6 ft.
 Note - 1/2" monel pipe ^{10°} set by Weyer Co. bears N.80°15'49"E., 82.32 ft. **NOT FOUND LANDSLIDE IN THIS LOCATION**

NEW REF

6" LIVE SINGED BASE D. FIR ^{WITH} 3 1/2" MAG NAIL R.S.C.; BEARS S6 1/2° W, 24°

23" x 2 FT. SAWN BURNED D. FIR STUMP, 3 1/2" MAG NAIL ^{TOP CENTER} BEARS S55° W, 35.8

6" x 4 FT. BROKEN SNAG ^{WITH} 3 1/2" MAG NAIL R.S.C.; BEARS N54° W, 30.2

ON NORTH EDGE OF LARGE BENCH IN RECENT CLEARCUT
OLDER REPROD TO NORTH

CS 67161-33

MINGS
43.46764
123.03114

BROKEN OFF 16" x 6 FT
SNAG
BROKEN BURNED 14" x 1 FT STUMP

29' N 79 1/2° E to 50"