

GOVERNMENT CORNER RESTORATION FORM

FILED

TOWNSHIP 24S RANGE 8W SEC. 14 PLSS # 520400

Date: 3/19/26 By: KE  
This survey consists of:

DOUGLAS COUNTY OREGON

DATE 3-17-26

Map: \_\_\_\_\_

Narrative: \_\_\_\_\_  
Corner Rpt: CS 67/62-28

Corner Designation

SEC COR 15/14  
22/23

DOUGLAS COUNTY  
SURVEYOR

Monument(s) Found: (Condition and Source)

2 1/2" DC SO BRASS CAP

- Condition report
- Not Found
- Renewed
- Unrecorded
- Surveyed In

Previous Renewals

DC SO 1963 CS 49/84-10

Shrum 1979 MB1-33

MONUMENT DETAIL  
COUNTY SURVEYORS  
OFFICE  
T 24S R 8W  
515 | 514  
522 | 523  
1963

Accessories Found

21" D. FIR N69°E 10.8 FT (REC N69°E 9.8 FT  
Fully Healed Single BLAZE

28" W. FIR S18°E 28.2 FT Fully Healed  
Single BLAZE

22" D. FIR N45°W 30.4 FT Fully Healed  
Single BLAZE

Steel Post 2 FT West

Add 3 1/2" MAG NAIL RIGHT SIDE CENTER  
TO TREES

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

New Accessories

No Suitable Trees To SW  
A 5/8" x 30" Iron Rod with DCSO  
PLASTIC CAP prog 3" BEARS 567 1/2 W  
7.4 FT

Sketch of Monument, Accessories, and General Area

Location & Comments

Trimble GEOXT Location  
43° 47499194 N  
123° 62427624 W

Comp. Decline. 14 1/4° E  
Agency DCSO  
Party Chief S. F. Hulse  
Note keeper  
Witnesses J. Corning

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR



OREGON  
JULY 14, 1978  
RONALD A. QUIMBY  
1654

EXPIRES: 12/31/2026

CS 67162-23 pg 2/3

TOWNSHIP 24 RANGE 08 POINT IDENTIFIER # 500400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 14, 15, 22 and 23

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description <u>43.47499194°N</u>
	<u>123.62427624°W</u>

GLO Survey by Henry L. Chandler, U.S. Deputy Surveyor, under Contract #619, dated June 5, 1893 - (DCSO records Vol. 8 Page(s) 3331-32)

Set a post 4 ft. long, 4" sq., 24" in the ground for cor. to secs. 14, 15, 22 and 23, marked T24S S14 on NE.; R8W S23 on SE.; S22 on SW.; and S15 on NW. faces, with 3 notches of S. and 2 notches on e. edges, from which

- A Fir 15" dia., bears N.4°E., 25 lks. dist. mkd. T24S R8W S14 BT.
- A Fir 14" dia., bears S.40°E., 33 lks. dist. mkd. T24S R8W S23 BT.
- A Fir 40" dia., bears S.42°W., 27 lks dist. mkd. T24S R8W S22 BT.
- A Fir 30" dia., bears N.15°W., 35 lks. dist. mkd. T24S R8W S15 BT.

DECLINATION 14 1/4° E

RENEWED 3/17/26

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew May 1963 - C.S. File 49/84-10

- Found - 2" squared wooded stake.
- ~~GONE~~ - 38" dead Fir snag N.15°W., 23.1 ft. (to face) cut open and found good scribing "BT"
  - ~~GONE~~ - 26" Fir stub, N.4°E., 16.5 ft., opened previously, face rotted away.
  - ~~GONE~~ - Fir, old, uproot, down, S.42°W., 17.8 ft. Burl wood visible, bark gone.
  - ~~GONE~~ - Stump hole, Fir roots and portion of stump remaining, S.40°E., 21.8 ft.

LOGGING DESTROYED THIS EVIDENCE

Set Brass cap at cor. mkd: County Surveyors Office

T	24	S	R	8	W
S	15	S	14		
S	22	S	23		
				1963	

- New BTS- 21" 6" D. Fir 67° N.69°E., 108 9.8 ft. mkd. T24S R8W S14 CS BT. FH 5/8
  - VERY ROTTED STUMP 28" 14" W. Fir 108 S.18°E., 28.2 ft. mkd. T24S R8W S23 CS BT. FH 5/8
  - ~~11" W. Fir S.57°W., 24.6 ft. mkd. T24S R8W S22 CS BT~~
  - 22" 8" D. Fir 108 N.45°W., 30.4 ft. mkd. T24S R8W S15 CS BT. FH 5/8
- Corner lies on steep NE. slope approx. 100 ft. 108 E. of top of ridge. FND STEEL LATH 2 FT, WPST

NEW REFERENCE

(NO SCITABLE TREES IN SW QUADRANT)

SET A 5/8" x 30" I.R. WITH A 1/2" DCSD PLASTIC CAP PROT. 3" S 67 1/2° W, 74 FT. DISTANT

M 81-33 SHRUM 1979