


DOUGLAS COUNTY SURVEYOR'S OFFICE

Designation: T-083 Station: T 565 RESET T 295 RSW S 32 1/4 A

Date Set: (1958) Set by (Agency): OSRD

Date Recovered: 6/97 Recovered by: DCSO

- | | | |
|------------------------------------|-------------------------------------|------------------------------------|
| <input type="checkbox"/> Found | <input type="checkbox"/> New | <input type="checkbox"/> Reset |
| <input type="checkbox"/> Not Found | <input type="checkbox"/> Referenced | <input type="checkbox"/> Destroyed |



VERTICAL CONTROL

NGVD 29 Elevation: 639.73 Feet File # CS 66/51
 Precision: 3rd Agency: DCSO Project: _____ Date: 6/97

NAVD 88 Elevation: _____ Meters File # _____
 Precision: _____ Agency: _____ Project: _____ Date: _____

HORIZONTAL CONTROL - south zone

N 500970.92 E 1249378.91 Datum/Adj.: Z7 Precision: 1/25,000

Lat: _____ Long: _____ Agency: DCSO File # CS 66/51 Date: 6/97

N 500935.32 E 4170337.41 Datum/Adj.: 83 Precision: 1/25,000

Lat: _____ Long: _____ Agency: DCSO File # _____ Date: _____

N _____ E _____ Datum/Adj.: _____ Precision: _____

Lat: _____ Long: _____ Agency: _____ File # _____ Date: _____

N _____ E _____ Datum/Adj.: _____ Precision: G15

Lat: 43 00 24 Long: 122 10 24 Agency: DCSO File # 66/51 Date: 2002

DESCRIPTION AND TO REACH

NOTE NO CS FILE AVAILABLE FOR ORIGINAL 1978 DCSO CO ORD VALUES.

NEW ELEVATION ON OLD CAP MARKED "RESET" (BRIDGE RAISED)

STANDARD OSHD DISK MARKED "T 565 RESET" IS FLUSH ON CURB OF OVERPASS 0.6 ABOVE BRIDGE DECK

EXIT 105 ON I-5 (WEAVER CO RD #41) OVERPASS NORTHWEST CORNER

