

DOUGLAS COUNTY SURVEYOR'S OFFICE

Designation: T-083 Station: T 565 RESET T 295 RSW S 32 $\frac{1}{4}$ A

Date Set: (1958)

Set by (Agency): OSHD

Date Recovered: 6/97

Recovered by: DCSO

☐ Found

☐ New

☐ Reset

☐ Not Found

☐ Referenced

☐ Destroyed



VERTICAL CONTROL

NGVD 29 Elevation: 639.73 Feet

File # CS 66/51

Precision: 3rd

Agency: DCSO

Project: _____

Date: 6/97

NAVD 88 Elevation: _____ Meters

File # _____

Precision: _____

Agency: _____

Project: _____

Date: _____

HORIZONTAL CONTROL - south zone

N 500970.92 E 1249378.91

Datum/Adj.: 27

Precision: 1/25,000

Lat: _____ Long: _____

Agency: DCSO

File # CS 66/51 Date: 6/97

N 500935.32 E 4170327.41

Datum/Adj.: 83

Precision: 1/25,000

Lat: _____ Long: _____

Agency: DCSO

File # _____ Date: _____

N _____ E _____

Datum/Adj.: _____

Precision: _____

Lat: _____ Long: _____

Agency: _____

File # _____ Date: _____

N _____ E _____

Datum/Adj.: _____

Precision: G15

Lat: 43 00 24 Long: 122 10 24

Agency: DCSO

File # 66/51 Date: 2002

DESCRIPTION AND TO REACH

NOTE NO CS FILE AVAILABLE
FOR ORIGINAL 1978 DCSO
COORD VALUES.

NEW ELEVATION ON OLD CAP
MARKED "RESET" (BRIDGE RAISED)

STANDARD OSHD DISK MARKER
T 565 RESET" IS FLUSH
ON CURB OF OVERPASS 0.6 ABOVE
BRIDGE DECK

EXIT 105 ON I-5 (WEAVER CO RD
#41) OVERPASS NORTHWEST
CORNER

