

Survey No.

Made for *Robt. Hall*
L. H. Smith

J 25 & R 4 St.

Chairmen { *J. L. Mohr*
A. V. Abern

Sec 21° 30' E.

April 24 1913

Field Bk 13-39
Pages 30-33

33.68 Ch

6.43

South

13.96

South

49.26

West

25.01

Began at the (SW) corner of the
Markham Cl. 39. Set corner N 55° W 88 lks from
original cedar witness tree. Fir st. missing
Thence West on South boundary.
Intersect 28 lks South of corner reset from
original trees.

On random.

Intersect 6 lks E of Corner which I re-establish from
remains of original witness trees. Set stake for
corner from which
A W Oak 5 in dia S 81½° W 27 lks
A W Oak 5 in dia N 64° E 32 "

Intersect 5 lks East of Cor to Secs 15, 16, 21 & 22.
Establish corner from remains of original trees
and mark. A W Oak 4 in dia S 45° E 60 lks
A W Oak 4 in dia S 31° W 53 "
" B " 6 " " N 36° W 128 "
" " " 6 " " N 62½° E 180 "

From the interior "L" Corner I run

Intersect South boundary of Cl. 7474 lks East of Cor.
which I establish from original trees
From SW Cor Cl 39 which I set from orig. trees

Intersect 15 lks South of Cor. which I renew
from stump of oak B. mark new trees
A fir 30 in dia tree S 14° E 194 lks
" " 24 " " " N 65¼° W 282 "

Renew ¼ Cor on South side of Sec 22. from
remains of original trees Set a post from which
A fir 12 in dia tree N 23° W 6 lks
" " 18 " " " S 14° E 31 lks.