

5

COUNTY SURVEYOR'S RECORD, DOUGLAS COUNTY, OREGON

Survey No. 0	Made on Dec. 14th. & 15th 1915	Survey No.	Made on
In Town. 27 S. Range 4 W. Secs 3 & 10		In Town.	Range Sec.
Made for Wm. Singleton & Geo. Riter		Made for	
Purpose of Deed description		Purpose of	

chs.

Began survey at a point 39 lks. N. of the $\frac{1}{4}$ cor. bet. secs. 3 & 10 T. 27--4 . The $\frac{1}{4}$ cor. was definitely located from old bearing tree, but was not established. Thence on ran. line from $\frac{1}{4}$ cor.

West

6.32 and made search for S.E.cor. of D.L.C. # 41, found nothing except old tree with markings cut out. Cont. on ran. line at

17.03 offset N. 1.75 chains. Cont. on ran. line at ^{offset}

20.00 set temp. stake. Cont. on ran. line at ^{offset}

29.50 set temp. stake, offset S. 1.75 chs., and made small search for old "B.T" for cor. of D.L.C. No.41. I found nothing, but am satisfied that trees could be found after a more diligent search. Offset back N. 1.75 Chs. to offset ran, line running west, and cont.

40.00 and set temp. stake. I again offset S. ^{1.75 chs.} and set stake "A", and after search definitely locate one fallen wit. tree for cor. of secs 3,4,9 & 10. I set in small stake from the calls of this tree and note that I Fall westerly 1.62 chs. from stake "A" True bring. of closing line I could not get on account of darkness. The day was foggy & rainy. The line was run through the forest over very steep ground. The chmen. and flagman was inexperienced Variation used was 21°-15' E.

Dec. 15th.

Began survey at $\frac{1}{4}$ cor. bet. secs. 3 & 4, and run a line

South

2.00 and set a temp. stake. Thence,

Easterly along north bdy. of D.L.C.No. 41

34.34 to fence cor. that marks N.E.Cor. of D.L.C.No. 41, I use fence cor. as good for Cl.cor. and run

West

15.50 and set a big unmarked oak st. for beginning pt. of line across Cl. Th. run ran. line South 18°-- 08' W. 32.50 chs. to pt."X". Th. west 1.00 chs. to pt. "Y"

Then returned to sec/ cor. common to secs. 3,4,9 & 10 and run

South

20.00 and set in pt. "Z" I then return to pt. "Y", sight on pt. "X" turn rt. 105°-58' and ch. dist.bet. pts. "Y" & "Z" which I find is 27.63+ chs. and note that bearing is S. 15°-58' W. After computation I find the true line should have been as follows.- S. 18°-03' 32.50 chs., West 1.00 ch., and S 16°-04' W. 27.63 chs. and so corrected my line by setting an unmarked S.Stone at new "X", and an old steel plow point at new "Y".

From the above work I made out the deed, and made report to the interested parties that the calls did not make a closed survey as the entire boundary lines were not run out by me. A copy of the deed description is in file envelope marked " Miscellaneous Deeds Descriptions"

Note-- The $\frac{1}{4}$ cor. bet. secs. 3 & 4 was set in by C.C.Boyer, Dep. Co. Sur.

All the ching. was by inexperienced men, viz., Wm. and Loris Singleton

The work was carefully executed and is correct as could be made with help furnished.

M. B. Gemond
Dep. Surv.