

COUNTY SURVEYOR'S RECORD, DOUGLAS COUNTY, OREGON

Survey No Made on Jan. 23, 24, 25 '11  
In Town 25 S Range 4 W. Sec 5  
Made for Tom Harvey & Goe Manning  
Purpose of survey was to establish a property line between their farms. This line was the N. bdy of D.L.C No. 48  
F B 12 = 42

Survey No Made on July 15-16, 1919  
In Town 32 S Range 6 W Sec 26  
Made for E F Tullett  
Purpose of Survey to establish lines & corners  
F B No 15 = 46

I began the survey by establishing the section cor. common to secs. 5, 6, 7 & 8 in above tp and rg I then run a poor random line north by needle to find the 1/4 cor. bet secs 5 and 6 I found trees that agree very well with the calls of the old notes but cannot find a single mark, so do not establish the corner. I then return to the S. Cor. of Cl No. 48 and reest this corner from one of the old bearing trees. I then run a line from this corner on a bearing of north by needle and carefully chain the line twice and find

I began the Survey at Cor Secs 26, 27, 34 & 35 above Tp & Range which I identified by Gout B.T.s all standing I then ran N 4°-24'W along Sec Line of Secs 26 & 27 at 2501 ch. I set a 5/8" x 18" Iron bolt from which a 14" Pine brs S 83°W 66 1/2 Lks and a 10" Pine brs N 66 1/2°W 58 Lks scribed these Trees C S B T I then continue N 4°-24'W and at 4002 ch. I hit 1/4 Sec Cor of Secs 26 & 27 which I identify by stake and Gout B T.s I then return to 5/8" x 18" bolt and run S 88°-48'E and at a distance of 4030 ch I mark an 18" Fir with 3 notches on N side and 3 notches on W side. I then run North (Mag) 1500 ch to a post set by Frank Cain and said to be the center of Sec 26 E F Tullett expressed himself as being satisfied with the Survey Chaining was good. Gurley Transit used. Bearings from Needle Chainmen J C Hate and Bert Gilpatrick.

J C Fear  
Deputy County Surveyor