

COUNTY SURVEYOR'S RECORD, DOUGLAS COUNTY, OREGON

BUSHONG & CO. PORTLAND, ORE. 87545

Survey No. <del>23</del> 3-23	Made on Nov. 3-6, 1925	Survey No.	Made on
In Town. 29	Range 4	Sec. 21-16	
Made for property lines		Made for	
Purpose of I.S. Weaver		Purpose of	
W.H. Woods Surveyor			
W.S. Crear, Chain			

FN. LL.

P.R. Weaver, G.M. Dyer, W.H. McClain, W.O. Wofford, present

At the corner to 16-17-20-21, I find 2 trees standing and stump of 3rd. that approximates very closely the bearing and distance given in the field notes, being some doubt in my mind, I go to the West corner on the North line of Hans Weaver D.I.C. No. 39, and run south 3 chains on West boundary of said claim to sec. line and west 5.25 chains and intersect the point where I have established temporary corner. Mr. McClain states that this is the point where the corner used to be. After checking the other measurements given to this corner in the field notes of D.I.C. No. 39 and finding them checking closely, I locate the corner at this point. Setting an iron pipe 1"x 3' and mark following B.T.'s.

- N 12°10'E 38 lks. A. Red Fir 8" marked S 16 C.S. B.T.
- S 67°30'E 33 lks. " " " 10" " S 21 C.S. B.T.
- S 76°15'W 93 lks. " " " 18" " S 20 C.S. P.M.
- N 72° W 1.18 lks. " " " 12" " S 17 C.S. P.M. thence

N 0°30'E On random line between Sec. 16-17

20.00 Set temp. 1/16 corner ( Moved 1.42 chs and East 0.11 chs

42.84 Fell 0.22 Chs East of 1/4 corner as established below.

At 1/4 corner to 16/17, I find one tree bearing S 40°E 33 lks and at S 25°E 5 lks. I find traces of a stump. I set a 4 x 4 x 2.5 cedar stake marked 1/4 16-17 C.S., and mark a Red Fir 15" in dia. S 43 1/2 E 50 lks. marked 1/4 S 16 C.S.

thence

N 0°30'E On random line between Sec. 16-17

20.00 Set temp. 1/16 cor. (moved South 3.25 ch. and west 1.25 chs

33.49 Intersect corner 2.27 West of corner as established below.

I find the bearing trees all in place but down and rotting and remark trees as follows.

- A Fir 12" N 48°30'W 28 lks. S 8 B.T. C.S.
- A Fir 12" S 9°00'W 34 lks. S 17 B.T. C.S.
- A Fir 10" S 44°00'E 43 lks. S 16 B.T. C.S.
- A Fir 9" N 19°00'E 40 lks. S 9 B.T. C.S.

N 0°50'E On true line between sections 16-17 bearings by sun

21.49 Set iron pipe for 1/16 corner

42.84 1/4 corner between sections 16-17

N 3°24'W On true line between sections 16-17

16.75 Set iron pipe for 1/16 corner

33.49 Section Corner 8-9-16-17

At the 1/4 corner between Sec. 16/9 I find both B.T.'s standing. The one N 67°W 1.64 ch. is O.K. The other is dead and I mark a new tree, A Red Fir 12" S 74°30'W 10 lks, scribed 1/4 S 16 C.S. thence

West On random line between 9 and 16

20.00 Set temp 1/16 cor.

37.04 I fall 70 lks. south of corner.

I retrace this line setting the 1/16 corner at 18.52 chs on true line.