

Subdivision of Sections 25, 26, 35 & 36 in T29S R6W And Section 31 in T29S R5W

Roseburg Lumber Company Roseburg, Oregon April, 1975 (See Plat of January, 1975) Scale: 1" = 400'

Bearings Based on South Line of Section 25 BLM Plat of July 7, 1977

Legend Monument Found Monument Set Original Data Lines indicate Section Lines, Property Lines and Limits of Survey

REGISTERED PROFESSIONAL LAND SURVEYOR Howard W. Johnston DREG 6156 HOWARD W. JOHNSTONE 498



Note: Corners found in Section 31 set by Ben Irving in 1928. See County Surveyor Map File 141-61. Township corner set on E & W blazed line 217' West of rocky ridge per original survey.

MAP FILE 141-61-12

MAP FILE 141-61-12