



- LEGEND**
- INDICATES FOUND ODOT MONUMENT
  - INDICATES FOUND MONUMENT FROM PUBLIC SURVEY
  - INDICATES MONUMENT SEARCHED FOR BUT NOT FOUND

POINT NO.	NORTHING.	EASTING	DESCRIPTION	MAP REFERENCE
354	487969.3477	4162793.3927	5/8 INCH SMOOTH IRON ROD 0.1 ABOVE SURFACE, 0.4 EAST OF FENCE, OLD 4"x4" ROW POST ALONGSIDE	137-15
378	487988.1561	4162546.0011	5/8 INCH SMOOTH IRON ROD FLUSH WITH SURFACE, 0.3 EAST OF ROW FENCE, 0.8 NORTHWEST OF 4"x4" ROW POST	O.D.O.T. 7B-22-19
615	487840.8399	4162676.9849	11/2" ALUMINUM CAP ON IRON ROD MARKED "ODOT HORIZ. CONTROL 47"	129-39
616	488355.1050	4162728.8091	11/2" ALUMINUM CAP ON IRON ROD MARKED "ODOT STATE HWY DIV" 0.2' BELOW SURFACE	129-39
621	488816.2336	4163291.2073	5/8 INCH SMOOTH IRON ROD 2.0 BELOW SURFACE, 1.0 EAST OF 4"x4" ROW POST	O.D.O.T. 7B-22-19 137-15, 129-39
623	489138.9993	4163765.9547	1 INCH IRON PIPE, FLUSH WITH SURFACE, 3.0 WEST OF FENCE CORNER 1.1 BELOW SURFACE	129-39 CORWIN SUBDIVISION PLAT
625	489063.2382	4163375.0390	1 INCH IRON PIPE, 0.3 BELOW SURFACE 4"x4" ROW POST ALONGSIDE	129-39, 137-15
627	489081.6732	4163292.6312	4 INCH BRASS DISC, FLUSH WITH ASPHALT, SOUTHEAST CORNER DLC 41	129-39 132-7, OTHERS
698	488666.0761	4162803.1530	11/2" ALUMINUM CAP ON IRON ROD MARKED "ODOT HORIZ. CONTROL 46"	129-39
6603	488462.9668	4163121.1363	5/8 INCH SMOOTH IRON ROD IN ROW FENCE, 0.1 ABOVE SURFACE, 0.5 EAST OF FENCE	7B-22-19, 137-15
6604	488457.8383	4163117.7421	5/8 INCH REBAR WITH YELLOW PLASTIC MARKED "LANG SURVEYING", 0.3 ABOVE GROUND, 0.6 EAST OF FENCE	58-44
7002	487493.6807	4162803.5064	5/8 INCH SMOOTH IRON ROD AT ANGLE POINT IN ROW FENCE, FLUSH WITH GROUND, 0.3 EAST OF FENCE POST, 1.2 NORTH OF 4"x4" ROW POST	7B-32-14
7003	487499.4549	4162853.0532	5/8 INCH SMOOTH IRON ROD AT ANGLE POINT IN ROW FENCE, 0.6 ABOVE GROUND, 0.4 EAST OF FENCE, 1.5 NORTHEAST OF 4"x4" ROW POST	7B-32-14
10316	488511.9418	4162604.2283	5/8 INCH SMOOTH IRON ROD, NO POST FLUSH WITH GROUND	7B-22-19
10362	489127.1900	4164057.5711	1 INCH IRON PIPE, BENT, 0.7 BELOW GROUND	PLAT OF NICKEL SUBD.
10363	489127.2133	4164062.6295	5/8 INCH REBAR WITH BROKEN YELLOW PLASTIC CAP	PLAT OF NICKEL SUBD.
10365	489118.3354	4164242.3619	5/8 INCH REBAR, BENT, 0.5 BELOW GROUND	PLAT OF NICKEL SUBD.
10373	489055.5150	4163625.3414	1 INCH IRON PIPE, FLUSH WITH GROUND, 5.0 WEST OF PP #076200	C.S. 42/319
10374	489026.3534	4164433.3538	1 INCH IRON PIPE, FLUSH WITH GROUND, 3.0 WEST OF PP #077202	C.S. 42/319

FILED  
 Date 8-16-2004  
 M. J. St. Hwy  
 K. 15-17 A-H  
 Douglas County Surveyor

REGISTERED PROFESSIONAL LAND SURVEYOR  
  
 OREGON  
 JAN 21, 1998  
 HARMON E. MCLENDON  
 2537  
 News 12/21/04

**MONUMENT RECOVERY SURVEY**  
 NW1/4, SW1/4 & SE1/4 SECTION 7, T30S, R5W, W.M.  
 DOUGLAS COUNTY, OREGON

OREGON DEPARTMENT OF TRANSPORTATION

SCALE: 1"=100'

DATE: JULY 2004

JOB NO. 863-60

anderson perry associates, inc.  
 ENGINEERING SURVEYING MATERIALS TESTING  
 LA GRANDE, OR. WALLA WALLA, WA.

SHEET 3/8