



SECTION 2, T. 22 S., R. 11 W. W.M.  
 Survey to locate lines + corners.  
 surveyed for Frankie Boye  
 January 1956  
 Scale 1" = 400'

Note - Lot markers are 3/16" angle irons with brass caps inscribed - Survey point - Wilford N. HAINES 239.



FILED  
 RECEIVED  
 JAN 27 1956  
 COUNTY SURVEYOR  
 DOUGLAS COUNTY, ORE.

COUNTY SURVEYORS FILE DATA  
 DO NOT REMOVE FROM OFFICE

C.S. File No. 42/124

MAP FILE 12-13

MAP-13