



N.E. Cor. Sec. 8
T.24S., R.5W., W.M.
Found: County Brass
Cap - Pipe Bent
by falling tree
40" Oak B.T. in Sec.
9
10" Fir B.T. in Sec. 8
Five killed snag
12" Fir B.T. in Sec. 5
five killed snag

FILED
RECEIVED
JUN 27 1972
COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

COUNTY SURVEYORS FILE DATA
DO NOT REMOVE FROM OFFICE

SURVEY of DIVISION LINE

For JAMES CLARK

Portion N $\frac{1}{2}$ Sec. 8, T.24S., R.5W., W.M.

Scale 1" = 100'

June 1972

Bearings based on the $\&$ S.P.R.R. track - The bearing
N29°14'E from the survey of PLAT A ORCHARD
HILL LAND CO.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Larry D. Bishop

OREGON
JULY 31, 1972
LARRY D. BISHOP
896

S 1° 45' 20" W
Distance Unknown

• Denotes $\frac{5}{8}$ " I. Rod Set

Note: I. Rod set to
control the direction
of the N-S division
line only - no attempt
was made to intersect
the East-
West $\&$ of sec.
8 exactly

Approx. East-West $\&$ Sec. 8

M 46-3

MAP FILE M 46 - 3