



LEGEND

- Corner found, see CS corner notes ○
- Corner set, 3/4" x 40" iron rod with 2 1/2" aluminum cap mkd. "Roseburg Resources Co." ●
- Corner computed, not set ●
- Property line marked with blazes, red paint & 6 ft. steel fence posts ———
- Gravel road - - - - -
- Stream ———>

Basis of bearings is west line of Section 34.
 Scale: 1" = 200 ft.

NARRATIVE

The survey was done for the purpose of setting property corners and marking property lines as shown hereon. The south 1/4 section corner of Section 34 was set as an original corner, set for the first time as per US Bureau of Land Management Cadastral Surveyor instructions. (See CS File No. _____ for copy of letters.)

Several surveys of record at the Douglas County Surveyors Office were relied upon as follows:

Ref. No. (R)	Map File No.	Surveyor	Date
1	USGLO T30S, R4W	William M. Bushey	1893
2	USGLO T31S, R4W	William M. Bushey	1893
—	CS 42/356 CS 42/391	John H. Markham, Jr.	1959
—	(Corners Only)		
—	Various CS	Douglas Co. Surveyor	

The north 1/4 section corner of Section 34 was reestablished in 1999 by the USBLM Cadastral Surveyor in their survey of Section 27 & used by us in this subdivision of said Section 34. See CS File No. 65/30-19A^{THUS} for the USBLM "Unofficial Advance Copy" of the Section 27 survey.

See CS File No. 65/30-19A^{THUS} for detailed corner notes this survey. The survey was done in June and July, 2000, using a Jena 0°00'01" theodolite and a Mac II electronic distance meter.

REGISTERED
 PROFESSIONAL
 LAND SURVEYOR
 Bruce A. Shaner
 OREGON
 OCT. 4, 1957
 BRUCE A. SHANER
 430
 Renews June 30, 2002

PROPERTY LINE SURVEY
 in Section 34, T30S, R4W, W.M.,
 Douglas County, Oregon

For: Roseburg Resources Company
 P.O. Box 1088
 Roseburg, Oregon 97470

By: Shaner Engineering, Inc.
 P.O. Box 1430
 Roseburg, Oregon 97470

July 4, 2000