

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 30 S T. S. R 8 W R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 3181

141

Douglas County
Surveyor's Office
Randall Smith
Stephen Flause
Oct. 23, 1996
C.S. File 65/9-31

Section Corner for Sections 21, 22, 27 and 28
Found - 2½" dia. DCSO brass cap on a 1½" O.D. iron pipe, protrudes 8" above ground. (ren. #57) See renewal #139

Accessories Found -

- 8" now 22" dia. D.Fir with a fully healed double blaze, bears S.25°W., 19.0 ft. (rec. S.25°W., 18.5 ft. dist. would go to orig. face.) O.B.T.
- 8" now 10" dia. 1 ft. high rotted D.Fir stump, no scribing visible, bears N.33°E., 7.9 ft. to center (rec. N.33°E., 7.2 ft.) O.B.T.
- 14" now 33" dia. tipped out of ground D.Fir, no scribing visible. Root hole agrees well with rec. "N.71°W., 11.9 ft." O.B.T.
- 16" now 18" dia. tipped out of position D.Fir stump, with a partially healed blaze, illegible scribing visible, root hole near rec. bearing and dist. "N.26°E., 16.6 ft." (ren. #57)
- 8" now 9" dia. tipped out of position and rotted Cedar root hole near rec. bearing and dist "S.13°E., 35.6 ft. (ren. #57)
- 10" now 10" dia. tipped out of position D.Fir stump, soil covered, no root hole. Rec. bearing & dist. "S.82½°E., 37.3 ft." 1975 BLM
- 30" now 30" dia. tipped out of position D.Fir with an unhealed blaze, scribing visible "T30S R8W S21 BT" root hole near rec. bearing and distance "N.36½°W., 30.4 ft." 1975 BLM

New Accessories -

- 7" dia. Grand Fir, double blazed and scribed "T30S R8W S22 CS H" bears N.72°E., 19.1 ft.
- 18" dia. Cedar, double blazed and scribed "T30S R8W S21 CS BT" bears N.63°W., 24.2 ft.
- 7" dia. D.Fir, double blazed and scribed "T30S R8W S27 CS BT" bears S.52°E., 44.2 ft.

FO. OK BY M. SMALLEY AUG. 2002, M137-56 **142**

B.L.M.
Wayne Rogers
Brian Seibold
John Powell
Apr. 2, 1997
C.S. 65/17-1

SW COR. SEC. 5
Mon. Fd.- 1½" iron post with 1965 Co. Surveyors Brass cap
Bt's Fd.- 22" Fir snag, bears S.56°E., 8 lks.
10" Chinquapin, bears N.54°E., 13 lks. with healed blaze
10" Fir, bears S.18½°E., 20 lks. with healed blaze
11" Fir, bears S.81½°W., 8½ lks. with healed blaze

New Accessories -

- 12" Fir, bears N.45½°W., 6 lks., mkd. T30S R8W S6 BT

corner is located 20' south of gravelled road 20' wide BLM rd. No. 30-08-5.2
see previous ren. #61

143

Gary
Smithers
Mar. 16 2001
C.S. File
65/37-2

East 1/4 Corner Sec. 4

Found - 1985 BLM brass cap on iron pipe firmly set.
13" D.Fir at S.33°E., 22 lks. with healed face.
9" D.Fir at S.29°W., 9 lks. with healed face.

New BTs - 8" D.Fir, S.64°E., 20.0 ft. to spike driven in side center, mkd. "¼ S3 BT" with BT tag.
10" D.Fir, N.65°W., 15.7 ft. to spike driven in side center, mkd. "¼ S4 BT" with BT tag.

Ren 58

144

Bruce Shaner
For: Seneca
Jones Timber Co.
4/2002
M139-72
C.S. File
65/42-42A

1/4 Cor. Secs. 25 & 36

Found - 1" IP with 2½" BC, properly marked, from which a:
32" D.Fir, now 6 ft. high stump, opened face, bears S.33°W., 52.8 ft.
14" D.Fir, now 6 ft. high stump, opened face, bears S.7°W., 8.6 ft.
18" D.Fir, face overgrown, bears N.34°W., 9.2 ft.
14" D.Fir, face overgrown, bears S.46°E., 22.4 ft.

New - 6 ft. steel fence post, West, 1.0 ft.