

FILED

GOVERNMENT CORNER RESTORATION FORM

Date: 5/31/2011 By: JC

Township 21S Range 5W Sec. 34

County DOUGLAS This survey consists of:

State OREGON Date APRIL 19, 2011

No. 440100 Narrative: _____

Corner Rpt: CS 67/33-35

Corner Designation

1/4 $\frac{534}{53}$

- DOUGLAS COUNTY
- Con Surveyor Part Only
- Not Found
- Renewed
- Unrecorded
- Surveyed In
- Referenced Out

Previous Renewals 1988, 1996

MONUMENT DETAIL

Monument(s) Found: (Condition and Source)

FROM 1988 A 1 INCH I. D. IRON PIPE WITH A YELLOW PLASTIC CAP (MARKED AS AT RIGHT AND ORIENTED SOUTH) IS FIRMLY SET PROTRUDING 16 INCHES ABOVE GROUND.

WEYER. CO.

Accessories Found:

ONE ORIGINAL BEARING TREE. A FIR 50" DIA. NOW A VERY ROTTEN 72 INCH DIAMETER 1 FOOT TALL FIR STUMP WITH NO BLAZE OR SCRIBING REMAINING; BEARS N08°E, 47[±] FEET DISTANT (AS PER RECORD).

THREE 1988 RENEWAL BEARING TREES. A 14" FIR NOW A 22 INCH ^{DIAMETER} FALLEN TO SIDE FIR WITH A PARTIALLY HEALED DOUBLE BLAZE (NO VISIBLE SCRIBING) ("W" NAIL NOT SEEN). THE ROOT-HOLE OF THIS TREE BEARS N39³/₄°W 28[±] FEET DISTANT (THIS B. AND D. AGREE WITH 1996 RENEWAL, 1988 RECORD N38°W, 28[±] FT.)

15" FIR NOW A FALLEN ON FACE AND OUT OF POSITION 21 INCH FIR WITH A PARTIALLY HEALED DOUBLE BLAZE SHOWING ILLEGIBLE SCRIBING ("W" NAIL NOT SEEN). THE ROOT-HOLE OF THIS TREE BEARS S2°W, 44[±] FEET DISTANT (RECORD S2°W, 42[±] FT. TO "W" NAIL).

14" FIR NOW A 26 INCH D. B.H. DOUGLAS FIR WITH A FULLY HEALED DOUBLE BLAZE; BEARS S72¹/₂°W, 62[±] FEET DISTANT (RECORD S70°W, 60[±] FT. TO "W" NAIL (NAIL NOT SEEN)).

1996 RENEWAL ^{ACCESSORY} A 6 FOOT METAL FENCE POST NOW A METAL FENCE POST PROTRUDING 4 FEET ABOVE GROUND; BEARS SOUTH 1 FOOT (AS PER RECORD).

